This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

+ *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.

+ *Refrain from automated querying* Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.

+ *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.

+ *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at `http://books.google.com/`

Digitized by Google

BRANNER
GEOLOGICAL LIBRARY

STANFORD UNIVERSITY LIBRARIES

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

WATER-SUPPLY PAPER 417

PROFILE SURVEYS OF RIVERS IN WISCONSIN

MAY 4 1917

PREPARED UNDER THE DIRECTION OF
W. H. HERRON
ACTING CHIEF GEOGRAPHER

Prepared in cooperation with
THE STATE OF WISCONSIN

WASHINGTON
GOVERNMENT PRINTING OFFICE
1917

Digitized by Google

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

Water-Supply Paper 417

ROFILE SURVEYS OF RIVERS IN WISCONSIN

PREPARED UNDER THE DIRECTION OF
W. H. HERRON
ACTING CHIEF GEOGRAPHER

Prepared in cooperation with
THE STATE OF WISCONSIN

WASHINGTON
GOVERNMENT PRINTING OFFICE
1917

Digitized by Google

766856

ADDITIONAL COPIES
OF THIS PUBLICATION MAY BE PROCURED FROM
THE SUPERINTENDENT OF DOCUMENTS
GOVERNMENT PRINTING OFFICE
WASHINGTON, D. C.
AT
45 CENTS PER COPY

STANFORD LIBRARY

Digitized by Google

CONTENTS.

	Page.
Introduction	5
General features of drainage of Wisconsin	5
River surveys	6
Peshtigo River basin	6
Chippewa River basin	7
Black River basin	10
Wisconsin River basin	11
Gaging stations	14
Publications	16

ILLUSTRATIONS.

PLATE I. Map of Wisconsin showing streams surveyed and gaging stations.

II–V. Plan and profile of Peshtigo River from Peshtigo to Strong Falls and Copper Rapids, Wis. (4 sheets, A to D).

VI. Profile of Chippewa River from mouth to Chippewa Falls (1 sheet).

VII–X. Plan and profile of Chippewa River from Chippewa Falls to Flambeau, Wis. (4 sheets, A to D).

XI–XVI. Plan and profile of Flambeau River from mouth to Turtle River, Wis. (6 sheets, A to F).

XVII–XIX. Plan and profile of Black River from Black River Falls to Minneapolis, St. Paul, & Sault Ste. Marie Railway, Wisconsin (3 sheets, A to C).

XX–XXX. Plan and profile of Wisconsin River from Kilbourn to Tomahawk, Wis. (11 sheets, A to K).

XXI–XXXII. Plan and profile of Eau Claire River from mouth to Dells of the Eau Claire, Wis. (2 sheets, A and B).

46982°—17

Digitized by Google

Digitized by Google

PROFILE SURVEYS OF RIVERS IN WISCONSIN.

Prepared under the direction of W. H. HERRON, Acting Chief Geographer.

INTRODUCTION.

In order to determine the location of undeveloped water powers the United States Geological Survey, alone and in cooperation with State organizations, has from time to time made surveys and profiles of some of the rivers of the United States that are adapted to the development of power by low or medium heads, ranging from 20 to 100 feet.

The surveys are made by means of plane table and stadia. The elevations given are derived from primary or precise levels determined by the United States Geological Survey. The maps are made n the field and show not only the outlines of the river banks, the islands, the positions of rapids, falls, shoals, and existing dams, and the crossings of all ferries and roads, but the contours of banks to an elevation high enough to indicate the possibility of using the stream. The elevations of all bench marks left are shown on the maps.

Those parts of the manuscript that deal with the geology of the drainage basins have been reviewed by W. O. Hotchkiss, State geologist of Wisconsin, who also prepared the description of the general features of drainage. The material on power plants constructed since the original surveys were made, as well as that relating to storage, has been supplied by W. G. Hoyt.

GENERAL FEATURES OF DRAINAGE OF WISCONSIN.

By W. O. HOTCHKISS, State Geologist.

About one-third of the area of the State of Wisconsin is drained by streams that flow north into Lake Superior and southeast and east into Lake Michigan, 3,020 square miles being tributary to Lake Superior and 14,570 square miles to Lake Michigan; the remaining two-thirds, comprising 38,500 square miles, is drained to the Mississippi through St. Croix, Chippewa, Wisconsin, and Rock rivers and minor streams.

The northern part of the State is a comparatively flat highland. Along the shore of Lake Superior there is a rather steep descent from a general altitude between 1,300 and 1,800 feet above the sea to the level of the lake—602 feet. This descent takes place in

Digitized by Google

a distance ranging from 15 to 30 miles. This northern highland slopes much more gently to the southwest, south, and southeast, so that elevations of 1,000 feet are reached on St. Croix River in Burnett County, on Chippewa River in northern Chippewa County, on Wisconsin River at Kilbourn, on Peshtigo River at High Falls, and on Menominee River at Niagara. The slopes on the southwest and east of the high central and northern area are steeper than those on the south.

A short distance below the 1,000-foot contour most of the large streams enter the area of flat-lying sandstones and limestones, where the stream gradients are much gentler and the valleys are deeply filled with loose sand and gravel.

Nearly all the northern highland is covered with thick glacial drift. It is a gently rolling country, in which there are few prominent elevations and thousands of lakes and swamps—features that combine to furnish excellent natural storage and help to regulate run-off.

The divides between the major drainage basins on the upper reaches of the streams are low—at some places so low as to be indeterminate over large areas. In the lower reaches of the streams tributary to the Mississippi there is little or no glacial drift, and the bordering lands lie 200 to 600 feet and at some places even higher above the streams. As a result of these conditions the main streams are moderately sluggish and relatively constant in volume, though many of the smaller tributaries are "flashy" and have steep gradients.

The streams tributary to Lake Michigan are more variable in character, owing to the heavy glacial drift. The Upper Fox pursues a sluggish course to Lake Winnebago, from which it descends rather steeply to Green Bay. The streams north of the Fox are very sluggish in their lower courses and much swifter in their upper courses. The streams that flow directly into Lake Michigan south of Sturgeon Bay are all relatively small and their gradients are very irregular; at some places they fall over limestone ledges, and at others they wind irregularly, with slight fall, through the glacial drift.

The gaging stations that have been maintained on the streams of Wisconsin are listed on pages 14–16 and their positions are shown on the map (Pl. I).

RIVER SURVEYS.

PESHTIGO RIVER BASIN.

Peshtigo River rises in the western part of Forest County, northeastern Wisconsin, flows southeastward across the southwestern part of Marinette County, and empties into Green Bay, an arm of Lake Michigan, at the extreme southeast corner of Marinette County, about 7 miles south of Marinette. The drainage area measured above the mouth comprises about 1,160 square miles.

Digitized by Google

The basin is fairly regular in outline and measures about 80 miles in length and 14 miles in average width. The river itself is about 150 miles long. Among its larger tributaries are Rat, Thunder, and Little rivers, which enter on the west or right bank, and Eagle Nest and Noque Bay rivers, which enter on the east or left bank. In the upper two-thirds of its course the river flows through an area of ancient crystalline rocks; in the lower third it crosses successively beds of sandstone and limestone. The largest falls and rapids are in the crystalline area.

In this region, as in other parts of Wisconsin, practically all the original timber has been cut off and has been replaced by second growth and brush. A considerable area is being brought under cultivation. These changes in forest conditions have probably not appreciably altered the flow of the streams, but a marked effect on the run-off may be caused by the draining of the numerous swamps and lakes at the sources of the river.

The mean annual rainfall is about 32 inches. The winters are severe, the river being icebound for about three months of each year.

The opportunities for storage have not been investigated, but the numerous lakes and swamps in the basin must afford excellent sites for reservoirs.

The stream is still used to some extent for logging, but the run of logs is small. A good share of the timber is being used for making pulp.

The river rises in the highest land in northern Wisconsin. At North Grandon Railroad crossing, near its sources, the river is 1,620 feet above sea level, at the mouth its elevation is 580 feet, so that it falls 1,040 feet in about 140 miles, or about 7 feet to the mile. This high average gradient gives rise to more and larger rapids than occur in any other river in Wisconsin, and, together with the high and rocky banks, insures numerous water powers.

Plates II to V show the results of a survey made in 1906 from Peshtigo, near the mouth, to Strong Falls and Copper Rapids. Since these surveys were made a dam owned by the Wisconsin Public Service Co. and operated for generating electric power has been built on the river in secs. 1 and 2, T. 32 N., R. 18 E. The head on the dam is about 37 feet and on the wheels 85 feet.

CHIPPEWA RIVER BASIN.

The Chippewa River drainage system has its sources in more than a hundred lakes, large and small, and many connecting swamps, lying in northwestern Wisconsin near the Michigan boundary, only 20 miles from Lake Superior. The main line of drainage runs very nearly along the central line of the basin, but the name Chippewa River is not applied to the continuation of the main stream. The river divides 112 miles from the mouth. One branch, the prolonga-

Digitized by Google

tion of the line of drainage, called the Flambeau, rises in the lakes near the Michigan line at an elevation of a little over 1,600 feet above sea level; the other branch, the Chippewa, is formed in the central part of Sawyer County by the union of East and West branches, both of which rise in the southwestern part of Ashland County. The course of the river is general southwestward to its junction with the Mississippi at the foot of Lake Pepin. The Flambeau drains about 1,980 square miles; the Chippewa above its junction with the Flambeau drains only about 1,780 square miles.

The larger tributaries of the Chippewa from the west, beginning at the sources are West Branch and Red Cedar rivers; those from the east are East Branch, Thornapple, Flambeau, Jump, Yellow, and Eau Claire rivers.

The total length of the Chippewa is 267 miles. The total drainage area is about 9,540 square miles, of which more than 5,000 square miles include the least settled part of northern Wisconsin.

The drainage basin is regular in outline and measures about 180 miles by 60 miles. The part of it that lies above Chippewa Falls is covered with glacial drift, and the underlying crystalline rocks appear only in the river bed. In the southern part of the basin the rivers have eroded deeply into the drift, but in the northern part they have not cut much below the surface. The country is level or rolling.

With few exceptions all the many and important water powers on Chippewa River are in the region of crystalline rocks, but on account of the deep glacial drift the powers on the upper streams occur as boulder rapids.

The lakes in this drainage basin lie in two widely separated groups—one in its extreme northeastern part, at the headwaters of the Flambeau, the other in its northwestern part, at the headwaters of Chippewa and Red Cedar rivers. In the remainder of the basin there are very few lakes. The wooded regions, however, include large areas of swamps. The elevation at the sources of Chippewa River is about 1,500 feet above sea level; at Chippewa Falls it is 806 feet, and at the mouth of the river it is about 665 feet. At the sources of Flambeau River the elevation is about 1,650 feet; at Ladysmith it is 1,115 feet.

This drainage basin contains rich forests of both hard and soft woods. Though lumbering has been carried on actively for many years, considerable pine timber still remains, chiefly at the upper headwaters, but it is fast disappearing. The upper half of the basin may be considered forested.

The mean annual rainfall is about 30 inches. The winters are severe. The snowfall is heavy and lasts a long time, and ice forms on the streams to a thickness of about 2 feet and remains three to four months.

Digitized by Google

This drainage area affords an unusually large number of excellent sites for reservoirs. The United States Engineer Corps in 1880 located and surveyed 12 reservoir sites, whose total capacity was about 25 billion cubic feet. The highest dam necessary will measure about 26 feet. The operation of these reservoirs, it was estimated, would increase the ordinary low-water flow of the river by 3,245 second-feet for 90 days, thus about doubling the present available water power of the river. The main obstacle to building such reservoirs by the Government is the fact that, owing to the settling of this region, the land that would be flooded has become very valuable. Private enterprise has developed some of the smaller of these reservoirs.

The results of profile surveys on the Chippewa from its mouth to Flambeau, Wis., and of Flambeau River from its mouth to Turtle River, Wis., are shown in Plates VI–XVI.

The Chippewa and its tributaries afford several valuable developed water powers and numerous undeveloped power sites. The Dells dam, near Eau Claire, was constructed in 1877. The head, as determined by the Wisconsin Geological Survey,[1] was 21 feet. The head on the wheels at the present time (1916) is about 27 feet at ordinary stage. Apparently the dam is about 7 feet higher than when originally constructed.

The Wisconsin-Minnesota Light & Power Co. is building a dam in sec. 3, T. 28 N., R. 8 W., and sec. 34, T. 29 N., R. 8 W., which, when completed, will back water to the foot of Jim Falls, at the north line of lots 4 and 5, sec. 30, T. 30 N., R. 7 W. This dam, which is known as the Wissota dam, will have a head of about 57 feet.

In 1910 the river was dammed at Jim Falls, in secs. 19, 20, and 29, T. 30 N., R. 7 W. No gates were put in this dam, and neither the power house nor the canal has yet been built. The present head at the dam is 6 or 7 feet. When the plant is completed the head on the wheels will be about 55 feet.

A dam designed to furnish power for a paper mill was built in 1913 at Brunet Falls, in sec. 18, T. 31 N., R. 6 W. The head at ordinary water is about 38 feet.

Several of the exceptionally good power sites afforded by the Flambeau were developed prior to the surveys on which Plates XI–XVI are based. Two other dams have been constructed since the surveys were made—the Port Arthur dam, in lots 2 and 7, sec. 18, T. 34 N., R. 6 W., constructed in 1906, furnishing 17 feet head and supplying power used in manufacturing pulp; and the Thornapple dam, in lots 1 and 2, sec. 22, T. 34 N., R. 7 W., constructed in 1910. The head on the Thornapple dam is 11 feet at all times, and the power is used for making pulp.

[1] Smith, L. S., The water powers of Wisconsin: Wisconsin Geol. and Nat. Hist. Survey Bull. 20, Economic ser., No. 13, p. 97, 1908.

Digitized by Google

On account of the numerous lakes in the drainage basin of the Chippewa and the possibility of using them for storage, this river system is destined to become a great center of power, but the development of the power sites is retarded because the region is not thickly settled and railroad facilities are lacking in many parts of it.

The upper headwaters of the river and its tributaries are used for running logs, but in areas where there are railroads the logs are moved by rail, as the rivers can not compete with the railroads in log running.

BLACK RIVER BASIN.

The drainage basin of Black River lies west of the central part of the State of Wisconsin. The river rises in the northeastern part of Taylor County, flows in a generally southwesterly direction, and joins the Mississippi at La Crosse. The drainage basin is long and narrow and the tributaries are small. The largest are Poplar River and East Fork of Black River, both of which enter from the east. The total length of the river is about 145 miles; the total drainage area is about 2,300 square miles.

The basin is about 120 miles long and has an average width of 20 miles. All that part of the river that lies north of Black River Falls is in crystalline rocks. Through a part of this stretch the river has worn deeply into the rock, and the banks rise 40 to 60 feet above the river. In places the rock is covered with glacial drift. Below Black River Falls the river flows in a sandstone region; its valley is wide and the banks are usually low. The surface of the basin is level or rolling. The soil in the upper part of the basin is clay loam. This region was at one time covered with pine. In the lower part of the basin the soil is sandy.

The elevation at the source of the river is about 1,400 feet; at Neillsville, 990 feet; and at the mouth of the river, 628 feet.

The timber on this drainage basin has been nearly all cut and the river is no longer used for running logs. The country is well settled.

The mean annual rainfall is about 32 inches. The winters are severe. The snowfall is heavy, and ice forms to a thickness of 1 to 2 feet and lasts about three months.

Storage possibilities have not been investigated. There are but few lakes in the drainage basin, and some of these may make suitable reservoirs, but the basin is so well settled that the building of storage reservoirs would be prohibited by the cost of the land that would be flooded.

The conditions of stream flow are not favorable for the development of water power, but power sites at which there is considerable head, favorably located for the building of dams, are numerous, and some of them will probably be developed. Most of the sites are above Black River Falls.

Digitized by Google

The results of surveys made to determine the possibility of using Black River for developing power are presented in Plates XVII–XIX.

The dam of the Greenwood Municipal Light Co., built about 1905, in sec. 34, T. 27 N., R. 2 W., does not appear on the profile. At ordinary stages the head of the dam is about 11 feet.

A dam built at Neillsville in 1870 and still in existence is not shown on the profile. The dam is in secs. 10 and 11, T. 24 N., R. 2 W., maintains a head of approximately 7½ feet, and the power is used by a gristmill.

The Dells dam, shown on the profile in sec. 18, T. 23 N., R. 2 W., was damaged in October, 1911, when about 400 feet of the core wall, extending from the west end of the main concrete dam into the west bank, was entirely carried away; this section has not yet been replaced.

The Hatfield dam, in sec. 3, T. 22 N., R. 3 W., was constructed in 1912, after failing in 1911. The head at the dam is about 38 feet and the total head at the plant about 92 feet. The plant is owned and operated by the Wisconsin Railway, Light & Power Co.

WISCONSIN RIVER BASIN.

The drainage basin of Wisconsin River, except a few square miles, is in Wisconsin. The river rises in Lac Vieux Desert, directly on the boundary between Michigan and Wisconsin, whence it flows southward about 300 miles to the city of Portage, near the center of Portage County. From this point it flows westward 118 miles to Prairie du Chien, Wis., about 40 miles from the southern boundary of the State, where it enters the Mississippi. The total length of the river is about 429 miles. The river receives from the west or right Tomahawk, Rib, Big Eau Pleine, Eau Pleine, Yellow, Lemonweir, Baraboo, Pine, and Kickapoo rivers; from the east Pelican, Prairie, Eau Claire, and Plover rivers.

The basin is about 225 miles long, about 50 miles in average width, and includes 11,800 square miles. The river flows for the most part in the eastern half of its basin; below Portage it flows within 10 miles of its southern edge. At Portage the divide between Wisconsin River and Fox River is so low that during high water some of the excess flows into the Fox.

Like all the large rivers of the State, the Wisconsin heads in the drift-covered region. The part of the Wisconsin basin above Nekoosa, including more than half the area drained, is underlain by crystalline rocks, which, by presenting a barrier to erosion, cause numerous rapids that afford excellent sites for water power. Below Nekoosa the crystalline rocks give way to the softer sandstone. This lower part of the valley is deeply filled with sand and gravel, which have made the bed of the river a succession of shifting sand bars almost to

Digitized by Google

its mouth. Where the sandstone is near the surface in the surrounding country the soil is very light and in places even sterile. North of Nekoosa this sandy belt rapidly narrows, and at Merrill, Wis., about 90 miles above, it almost disappears, being replaced by clayey loams and loamy clays. North of Tomahawk the clays are again replaced by sandy soils containing gravel and by boulders and glacial drift.

In general the country is level or undulating. At a few places the surface is broken by decided ridges, as, for example, the Baraboo ranges of quartzite and the bluffs along the lower river. The northern part of the basin is covered with innumerable lakes and swamps, which tend to make the flow of the stream uniform and steady.

According to the United States Engineer Corps, the elevation of Lac Vieux Desert, the source of the river, is about 1,650 feet, the elevation at the mouth is about 604 feet, so that the total fall is about 1,050 feet. About 634 feet of this fall occur in the 150 miles between Rhinelander and Nekoosa, an average of over 4 feet to the mile. This descent is concentrated at many places, producing a large number of valuable water powers.

The dense growth of pine which covered the upper part of the basin of Wisconsin River has nearly all been cut off, and a thick growth of brush and second-growth timber has taken its place; large areas have been brought under cultivation. In some places this second growth has been burned over, leaving almost impenetrable thickets of brush and dead timber.

The mean annual rainfall on the headwaters of the river is about 31 inches; at the lower part of the basin the rainfall is about 34 inches.

The winters, except in the very lowest part of the basin, are severe. The snowfall is rather heavy, and stays on the ground for long periods, and the streams are covered with ice 1 to 2 feet thick for three to four months. These conditions tend to make winter the period of minimum flow.

The basin affords numerous opportunities for storage. The United States Engineer Corps located and surveyed eight reservoir sites at the headwaters of Wisconsin River to aid navigation of the Mississippi River. The capacity of these reservoirs is about 20,000,000,000 cubic feet, and it was estimated that a flow of 3,000 cubic feet per second could be maintained for three months. Such a flow would nearly double the low-water flow of the river and its resulting water power. Several of these reservoirs have been constructed by private parties for water-power development. The Wisconsin Valley Improvement Co. has been authorized by law to construct, acquire, and maintain a system of reservoirs on the tributaries of Wisconsin River north of the south line of township 34, about 6 miles below Tomahawk, for the purpose of producing a uniform flow of water. The law provides that when this company shall have completed

Digitized by Google

reservoirs of a capacity of 2,000,000,000 cubic feet it may collect and receive reasonable tolls from the owner of every improved and operated water power on the river below such reservoirs.

The following tables show the reservoirs maintained by the Wisconsin Valley Improvement Co. in 1915, and the developed powers on Wisconsin and Tomahawk rivers above Nekoosa, Wis.

Reservoirs maintained by the Wisconsin Valley Improvement Co. in 1915.[a]

Name.	Location of reservoir.	Location of dam.	Area of reservoir.	Drainage area.	Capacity (millions of cubic feet).	
					Summer.	Winter.
Tomahawk River.			*Square miles.*	*Square miles.*		
Rice Storage	Tps. 35-36 N., Rs. 5-7 E.	Secs. 4 and 9, T. 35 N., R. 6 E.	6.85	558.25	1,788	1,788
Squirrel	T. 39 N., R. 5 E.	Sec. 30, T. 39 N., R. 5 E.	3.00	17.07	152	152
Minocqua	Tps. 38-40 N., Rs. 6-7 E.	Sec. 10, T. 39 N., R. 6 E.	11.31	81.60	291	651
Wisconsin River.						
South Pelican	T. 35 N., Rs. 10-11 E.	Sec. 11, T. 35 N., R. 10 E.	5.49	22.50	0	305
North Pelican	Tps. 36-38 N., Rs. 9-11 E.	Sec. 4, T. 36 N., R. 10 E.	2.33	93.00	83	205
Big St. Germain	Tps. 40-41 N., Rs. 7-8 E.	Sec. 30, T. 40 N., R. 8 E.	2.51	68.76	243	243
Little St. Germain	T. 40 N., Rs. 8-9 E.	Sec. 35, T. 40 N., R. 8 E.	1.57	19.34	142	142
Sugar Camp	Tps. 38-39 N., Rs. 8-10 E.	Sec. 17, T. 39 N., R. 9 E.	3.34	59.00	380	380
Seven Mile	T. 39 N., Rs. 11-12 E.	Sec. 11, T. 39 N., R. 11 E.	.87	14.00	117	117
Upper Nine Mile	T. 40 N., Rs. 11-12 E.	Sec. 36, T. 40 N., R. 11 E.	.24	3.00	14	14
Lower Nine Mile	Tps. 39-40 N., R. 11 E.	Sec. 4, T. 39 N., R. 11 E.	1.14	28.00	93	93
Burnt Rollways	Tps. 37-40 N., Rs. 11-12 E.	Sec. 5, T. 39 N., R. 11 E.	10.91	133.00	386	609
Long on Deerskin	Tps. 41-42 N., R. 12 E.	Sec. 7, T. 41 N., R. 12 E.	3.96	28.80	316	384
Little Deerskin	Tps. 40-41 N., Rs. 10-11 E.	Sec. 33, T. 41 N., R. 11 E.	.49	4.90	22.	22
Buckatabpon	T. 41 N., R. 9 E.	Sec. 24, T. 41 N., R. 9 E.	1.88	14.10	142	142
Twin	Tps. 41-42 N., R. 11 E.	Sec. 19, T. 41 N., R. 11 E.	5.41	25.70	330	380
Vieux Desert	T. 42 N., R. 11 E.	Sec. 17, T. 42 N., R. 11 E.	7.47	27.50	600	600
			68.77	1,198.52	5,099	6,227

[a] From information furnished by Wisconsin Valley Improvement Co.

Power plants on Wisconsin and Tomahawk rivers above Nekoosa, Wis.[a]

Name of power.	Location.	Head developed.	Area of pond in acres.
Wisconsin River.			
Nekoosa—Edwards Paper Co.:		*Feet.*	
Nekoosa dam	T. 21 N., R. 5 E.	19	150
Port Edwards dam	T. 22 N., R. 5 E.	18	50
Centralia Pulp & Water Power Co. dam	T. 22 N., R. 5 E.	13	150
Consolidated Water Power & Paper Co.:			
Grand Rapids dam	T. 22 N., R. 6 E.	28	320
Biron dam	T. 23 N., R. 6 E.	16	160
Whiting—Plover Paper Co. dam	T. 23 N., R. 8 E.	6.5	49
Wisconsin River Paper & Pulp Co. dam	T. 23 N., R. 8 E.	18	76
Jackson Milling Co. dam	T. 23 N., R. 8 E.	8	.....
Wausau Sulphate Fibre Co. dam	Sec. 29, T. 27 N., R. 7 E.	17	674
Marathon Paper Mills Co. dam	Sec. 24, T. 28 N., R. 7 E.	20	1,774
Wausau Street Railway Co. dam	Sec. 35, T. 29 N., R. 7 E.	22	304
Wausau Paper Mills Co. dam	Sec. 3, T. 29 N., R. 7 E.	16	596
Merrill—Merrill Electric Light & Railway Co	Sec. 13, T. 31 N., R. 6 E.	14	.....
Grandfather Falls—Grandfather Falls Co	Sec. 30, T. 33 N., R. 6 E.	33	.....
Tomahawk—Tomahawk Pulp & Paper Co	Sec. 10, T. 34 N., R. 6 E.	16	2,733
Kings—Tomahawk Power Co	Sec. 25, T. 35 N., R. 6 E.	23	1,810
Rat Rapids—Rhinelander Power Co	Sec. 27, T. 36 N., R. 8 E.	20	650
Rhinelander—Rhinelander Paper Co	Sec. 6, T. 36 N., R. 9 E.	32	3,576
Otter Rapids—Eagle River Electric Co	Sec. 36, T. 40 N., R. 9 E.	12	3,250
Tomahawk River.			
Tomahawk—Tomahawk Light, Telephone & Improvement Co.	Sec. 28, T. 35 N., R. 6 E.	13.5	709

[a] From information furnished by Wisconsin Valley Improvement Co.

Digitized by Google

The opportunities for water-power development in this basin are numerous. Some of the larger sites have been developed, but many valuable sites on the main river and on the tributaries are still unused.

The stream was used extensively for logging, but the greater part of the large timber has been cut off and lumbering is decreasing, although considerable pulp wood is being run in the upper reaches of the river. The dams at the water-power sites do not interfere seriously with the small run of logs.

Maps showing the results of surveys made in 1906 on Wisconsin River from Kilbourn to Tomahawk, Wis., form Plates XX–XXX, and the results of surveys on Eau Claire River from the mouth to Dells of the Eau Claire form Plates XXXI–XXXII.

No dams have been built on Eau Claire River since the profiles were made.

The Grandfather Falls dam in sec. 30, T. 33 N., R. 6 E., was built in 1907. The head is approximately 33 feet, and power is transmitted to Merrill, where it is used in the manufacture of paper.

The Rothschild dam on Wisconsin River, in the NE. ¼ sec. 36, T. 28 N., R. 7 W., was built by the Marathon Paper Mills Co. in 1909.

In 1909 the Southern Wisconsin Power Co. built the Kilbourn dam, in sec. 4, T. 13 N., R. 6 E. The head is approximately 17 feet and the power is transmitted to Portage and Milwaukee.

In 1915 the Wisconsin Power Co. built the Prairie du Sac dam, in sec. 25, T. 10 N., R. 6 E.; head, approximately 29 feet. The power generated is transmitted to Milwaukee, Madison, Prairie du Sac, Sauk City. and smaller towns.

GAGING STATIONS.

[NOTE.—Dash following a date indicates that station was being maintained by the U. S. Geological Survey in cooperation with the Railroad Commission of Wisconsin Sept. 30, 1915. Period after date indicates discontinuance.]

ST. LAWRENCE RIVER BASIN.

Streams tributary to Lake Superior:
- Aminicon River near Aminicon Falls, Wis., 1914–
- Brule River near Brule, Wis., 1914–
- Bad River near Odanah, Wis., 1914–

Streams tributary to Lake Michigan:
- Brule River (head of Menominee River) near Florence, Wis., 1914–
- Menominee River at Iron Mountain, Mich., 1902–1914.
- Menominee River at Lower Quinnesec Falls, Wis., 1898-99.
- Menominee River at Koss, Mich., 1902–1909.
- Menominee River at Rapids Power Plant below Koss, 1913–
  - Pine River near Florence, Wis., 1914–
  - Pike River at Amberg, Wis., 1914–
- Peshtigo River at High Falls, Wis., 1913–
- Peshtigo River near Crivitz, Wis., 1906–1909.
- Peshtigo River at Crivitz, Wis., 1906.
- Oconto River near Gillett, Wis., 1906–1909; 1914–
- Oconto River at Stiles, Wis., 1906.

Digitized by Google

Streams tributary to Lake Michigan—Continued.
Fox River at Omro, Wis., 1902–3.
Fox River at Oshkosh, Wis., 1902.
Fox River at Wrightstown, Wis., 1902–1904.
Wolf River at Keshena, Wis., 1907–1909; 1911–
Wolf River at White House Bridge, near Shawano, Wis., 1906–7.
Wolf River at Darrows Bridge, near Shawano, Wis., 1906.
Wolf River at New London, Wis., 1913–
Wolf River at Northport, Wis., 1905.
Wolf River at Winneconne, Wis., 1902–3.
West Branch of Wolf River at Neopit, Wis., 1911–
Little Wolf River near Royalton, Wis., 1914–
Little Wolf River near Northport, Wis., 1907–1910.
Fond du Lac River, West Branch (head of Fond du Lac River) at Fond du Lac, Wis., 1903.
East Branch of Fond du Lac River at Fond du Lac, Wis., 1903.
Milwaukee River at Milwaukee, Wis., 1914–

UPPER MISSISSIPPI RIVER BASIN.

St. Croix River at Swiss, Wis., 1914–
St. Croix River near St. Croix Falls, Wis., 1902–1905; 1910–
Namakagon River at Trego, Wis., 1914–
Yellow River at Webster, Wis., 1914.
Apple River near Somerset, Wis., 1911–
Chippewa River above East Fork, near Winter, Wis., 1911–
Chippewa River below East Fork, near Winter, Wis., 1912–
Chippewa River near Bruce, Wis., 1913–
Chippewa River at Chippewa Falls, Wis., 1888–
Chippewa River near Eau Claire, Wis., 1902–1909.
Flambeau River near Butternut, Wis., 1914–
Flambeau River near Ladysmith, Wis., 1914–
Flambeau River at Ladysmith, Wis., 1903–1906.
Jump River at Sheldon, Wis., 1915–
Eau Claire River near Augusta, Wis., 1914–
Eau Claire River near Eau Claire, Wis., 1913–14.
Red Cedar River near Colfax, Wis., 1914–
Red Cedar River at Cedar Falls, Wis., 1909–
Red Cedar River at Menominee, Wis., 1907–8; 1913–
Trempealeau River at Dodge, Wis., 1913–
Black River at Neillsville, Wis., 1905–1909; 1913–
Black River at Melrose, Wis., 1902–3.
La Crosse River near West Salem, Wis., 1913–
Wisconsin River near Rhinelander, Wis., 1905–
Wisconsin River at Merrill, Wis., 1902–
Wisconsin River near Nekoosa, Wis., 1914–
Wisconsin River near Necedah, Wis., 1902–1914.
Wisconsin River at Muscoda, Wis., 1902–3; 1913–
Tomahawk River near Bradley, Wis., 1914–
Prairie River near Merrill, Wis., 1914–
Little Rib River near Wausau, Wis., 1914–
Eau Claire River at Kelley, Wis., 1914–
Big Eau Pleine River near Stratford, Wis., 1914–
Plover River near Stevens Point, Wis., 1914–
Baraboo River near Baraboo, Wis., 1913–
Kickapoo River at Gays Mills, Wis., 1913–

Digitized by Google

Rock River at Watertown, Wis., 1914.
Rock River at Afton, Wis., 1914–
Catfish River at Madison, Wis., 1902–3.
Lake Mendota at Madison, Wis., 1902–3.
Pecatonica River at Dill, Wis., 1914–
Sugar River near Brodhead, Wis., 1914–

PUBLICATIONS.

Information concerning stream flow at the stations indicated by the preceding table has been published in the reports of the Geological Survey listed below:

Water-Supply Papers 65, 66, 75, 83, 85, 97, 98, 99, 128, 129, 130, 170, 171, 206, 207, 244, 245, 264, 265, 284, 285, 304, 305, 324, 325, 354, 355, 384, 385, 404,[1] 405.[1]

Water-supply papers and other publications of the United States Geological Survey containing data in regard to the water resources of the United States may be obtained or consulted as indicated below:

1. Copies may be obtained free of charge by applying to the Director of the Geological Survey, Washington, D. C. The edition printed for free distribution is, however, small and is soon exhausted.

2. Copies may be purchased at nominal cost from the Superintendent of Documents, Government Printing Office, Washington, D. C., who will, on application, furnish lists giving prices.

3. Sets of the reports may be consulted in the libraries of the principal cities in the United States.

4. Complete sets are available for consultation in the local offices of the water-resources branch of the Geological Survey, as follows:

Boston, Mass., Customhouse.
Albany, N. Y., Room 18, Federal Building.
Atlanta, Ga., Post Office Building.
Madison, Wis., care Railroad Commission of Wisconsin.
St. Paul, Minn., Old Capitol Building.
Helena, Mont., Montana National Bank Building.
Denver, Colo., 403 New Post Office Building.
Salt Lake City, Utah, 421 Federal Building.
Boise, Idaho, 615 Idaho Building.
Tacoma, Wash., 406 Federal Building.
Portland, Oreg., 416 Couch Building.
San Francisco, Cal., 328 Customhouse.
Los Angeles, Cal., 619 Federal Building.
Austin, Tex., Old Post Office Building.
Phoenix, Ariz., 417 Fleming Building.
Honolulu, Hawaii, Kapiolani Building.

A list of the Geological Survey's publications may be obtained by applying to the Director of the United States Geological Survey, Washington, D. C., who will also send, on request, an index map of Wisconsin, showing areas mapped and giving other information in regard to publications of special interest to residents of the State.

[1] In preparation June 1, 1916.

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

ice 10 feet

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google


Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

WATER-SUPPLY PAPER 418

MINERAL SPRINGS OF ALASKA

BY

GERALD A. WARING

JAN 24 18

WITH A CHAPTER ON THE

CHEMICAL CHARACTER OF SOME SURFACE WATERS OF ALASKA

BY

RICHARD B. DOLE AND ALFRED A. CHAMBERS

WASHINGTON
GOVERNMENT PRINTING OFFICE
1917

Digitized by Google

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

Water-Supply Paper 418

MINERAL SPRINGS OF ALASKA

BY

GERALD A. WARING

WITH A CHAPTER ON THE

CHEMICAL CHARACTER OF SOME SURFACE WATERS OF ALASKA

BY

RICHARD B. DOLE AND ALFRED A. CHAMBERS

WASHINGTON
GOVERNMENT PRINTING OFFICE
1917

Digitized by Google

ADDITIONAL COPIES
OF THIS PUBLICATION MAY BE PROCURED FROM
THE SUPERINTENDENT OF DOCUMENTS
GOVERNMENT PRINTING OFFICE
WASHINGTON, D. C.
AT
25 CENTS PER COPY

Digitized by Google

CONTENTS.

	Page.
Preface, by Alfred H. Brooks	7
Introduction	11
Distribution of springs	12
Mineral waters	14
Hot springs	19
Southeastern Alaska	19
Distribution	19
Bell Island Hot Springs	19
Bailey Bay Hot Springs	20
Hot springs near Unuk River	23
Hot springs near Saks Cove	23
Shakes Hot Springs	24
Minor hot springs in the Wrangell region	25
Baranof Hot Springs	26
Sitka Hot Springs	28
Hot springs near Gut Bay	30
Hot springs near Fish Bay	31
Hot springs on North Arm of Peril Strait	33
Hooniah Warm Springs	34
Tenakee Hot Springs	35
Hot springs near head of Tenakee Inlet	38
Other hot springs near Tenakee Inlet	41
Hot spring on Twelvemile Creek	41
Southwestern Alaska	42
Distribution	42
Port Moller Hot Springs	45
Hot springs near Port Heiden	46
Hot springs on shore of Becharof Lake	46
Hot springs near Katmai Pass	47
Hot springs on Bogoslof Island	47
Warm springs on Attu Island	49
Yukon Basin	50
Distribution	50
Circle Hot Springs	51
Hot springs on Big Windy Creek	53
Hot springs near Flat Creek	54
Chena Hot Springs	55
Hot springs near Tolovana River	57
Hot spring near Little Minook Creek	59
Hutlinana Hot Spring	59
Baker Hot Springs	60
Warm springs west of Glacier	63
Warm springs north of Glacier	63
Hot springs on Ray River	64
Little Melozitna Hot Springs	64
Melozitna Hot Springs	66

Digitized by Google

Hot springs—Continued.
Yukon Basin—Continued. Page
Horner Hot Springs ... 6
Warm springs on Alatna River ... 6
Warm spring near Reed River ... 7
Hot springs near Selawik River ... 7
Hot springs on a tributary of Innoko River ... 7
Warm springs near Iditarod ... 7
Hot spring near Whitefish Lake ... 7
Hot springs near Tuluksak River ... 7
Seward Peninsula ... 72
Distribution ... 72
Kruzgamepa Hot Springs ... 72
Arctic Hot Springs ... 75
Warm springs near Inmachuk River ... 76
Hot springs near Kwiniuk River ... 77
Hot springs near Sweepstake Creek ... 77
Carbonated springs ... 77
Southeastern Alaska ... 77
Distribution ... 77
Carbonated springs near New Eddystone Rock ... 78
Carbonated springs near Unuk River ... 79
Carbonated springs near Soda Bay ... 79
Carbonated springs near Trocadero Bay ... 81
Zarembo Springs ... 82
Carbonated springs on south end of Zarembo Island ... 83
Yukon Basin ... 84
Distribution ... 84
Carbonated springs near Woodchopper Creek ... 84
Carbonated springs on Coal Creek ... 84
Carbonated spring on Hoseanna Creek ... 85
Carbonated springs near Marshall ... 85
Seward Peninsula ... 86
Distribution ... 86
Carbonated springs near Bering ... 87
Other carbonated springs on Seward Peninsula ... 88
Sulphur springs ... 89
Distribution ... 89
Sulphur springs on Revillagigedo Island ... 89
Sulphur springs on Prince of Wales Island ... 91
Sulphur springs near Mount Edgecumbe ... 91
Sulphur springs on Bering River ... 92
Sulphur springs near Iliamna Lake ... 92
Sulphur spring near Little Susitna River ... 92
Sulphur springs near Skilak Lake ... 93
Sulphur spring on Eldorado Creek ... 93
Sulphur spring near Nenana River ... 93
Sulphur spring near Platinum Creek ... 94
Sulphur springs on Coal Creek ... 94
Sulphur springs south of Circle ... 94
Sulphur springs near Ignak River ... 95
Iron springs ... 95
Salt springs ... 98

Digitized by Google

Page.
Chemical character of some surface waters of Alaska, by Richard B. Dole and Alfred A. Chambers 99
General character of surface waters 99
Yukon River 99
Character of the basin 99
Mineral analyses of water of Yukon River 101
Chemical composition of water of Yukon River 104
Discharge of Yukon River 105
Comparative composition of waters of great North American rivers 106
Yukon-Tanana region 106
Seward Peninsula 108
Lowe and Copper rivers 109
Stikine River 109
Index 111

ILLUSTRATIONS.

Page.
PLATE I. Map of Alaska showing distribution of mineral springs and volcanoes 12
II. Map of southeastern Alaska showing location of mineral springs 18
III. *A*, Bell Island Hot Springs, southeastern Alaska; *B*, Melozitna Hot Springs, Ruby region 20
IV. *A*, Sitka Hot Springs, Baranof Island, southeastern Alaska; *B*, Tenakee Hot Springs, Chichagof Island, southeastern Alaska; *C*, Circle Hot Springs, Circle district 28
V. *A*, Chena Hot Springs, Fairbanks district; *B*, Baker Hot Springs, Hot Springs district; *C*, Little Melozitna Hot Springs, Tanana region 54
VI. Map of Seward Peninsula, Alaska, showing location of mineral springs 72
VII. *A*, Kruzgamepa Hot Springs, Seward Peninsula; *B*, Carbonated springs near Bering, Seward Peninsula; *C*, Horner Hot Springs, Ruby region 74
VIII. *A*, Carbonated springs, Revillagigedo Island, near New Eddystone Rock, southeastern Alaska; *B*, Warm Springs near Inmachuk River, Seward Peninsula 76
IX. *A*, Zarembo Springs, Zarembo Island, southeastern Alaska; *B*, Carbonate mound formed by springs near Soda Bay, Prince of Wales Island, southeastern Alaska; *C*, Carbonate terraces formed by springs near Trocadero Bay, Prince of Wales Island, southeastern Alaska 82
FIGURE 1. Sketch map of Bailey Bay Hot Springs and vicinity, southeastern Alaska 21
2. Sketch map of Baranof Hot Springs and vicinity, Baranof Island, southeastern Alaska 26
3. Sketch map of hot springs near Fish Bay, Baranof Island, southeastern Alaska 30

Digitized by Google

Pag

FIGURE 4. Sketch map of Tenakee Hot Springs and vicinity, Chichagof Island, southeastern Alaska..... 3
5. Sketch map of hot springs and vicinity near head of Tenakee Inlet, Chichagof Island, southeastern Alaska..... 3
6. Map showing location of mineral springs, Circle district, Alaska.... 5
7. Sketch map of Circle Hot Springs and improvements in 1915, Circle district, Alaska..... 5
8. Map showing location of mineral springs in Fairbanks district, Alaska..... 5
9. Sketch map of Chena Hot Springs and improvements in 1915, Fairbanks district, Alaska..... 5
10. Map showing location of mineral springs in Hot Springs district, Alaska..... 5
11. Sketch map of Baker Hot Springs and improvements in 1915, Hot Springs district, Alaska..... 6
12. Sketch map showing location of Little Melozitna Hot Springs, Tanana region, Alaska..... 6
13. Sketch map showing location of Melozitna Hot Springs, Ruby region, Alaska..... 6
14. Sketch map of Kruzgamepa Hot Springs and improvements in 1915, Seward Peninsula, Alaska..... 7
15. Sketch map of carbonated springs and vicinity near Soda Bay, Prince of Wales Island, southeastern Alaska..... 8
16. Sketch map of carbonated springs and vicinity near Trocadero Bay, Prince of Wales Island, southeastern Alaska..... 8

Digitized by Google

PREFACE.

By Alfred H. Brooks.

Hot springs are widely distributed in Alaska, but they were only slightly utilized by the natives before the coming of the white man. During the Russian occupation of Alaska primitive bathing houses were built at several hot springs, notably near Sitka, and the hygienic value of the springs was recognized. In recent years more elaborate bathing establishments have been constructed at several accessible hot springs and are much used by local residents, and some hot springs that are more difficult of access are occasionally visited by prospectors as health resorts. This local use of the springs has led to a demand for more accurate information about the qualities of the thermal waters than has been available, and for this reason the investigation whose results are here set forth was undertaken.

Though Mr. Waring gave attention principally to the hot springs he examined other mineral springs that lay near the route he traveled. He could not in one field season visit all the springs in Alaska, many of which are in very inaccessible places, but he has compiled for this report all available information about mineral springs.

As Mr. Waring points out, the hot springs may be grouped into several provinces. A larger number have been found in southeastern Alaska than in the interior, perhaps because this part of the Territory is best known. This southeastern mineral-spring province lies adjacent to the great Mesozoic batholiths of the Coast Range and is itself a field of abundant intrusives. Most of the hot springs occur along shear zones within intrusive rocks. Though there are some recent lavas in this field no genetic relation has been established between them and the hot springs. This province, which lies on the western margin of the Pacific Mountain system, has been repeatedly subject to deformation. More directly bearing on the genesis of the springs is the fissuring that has affected the rocks. Though most of this took place in pre-Eocene time, there is some evidence of later movement, and it is in this epoch of later movement that the fissures with which the hot springs are associated were probably formed.

Digitized by Google

The hot springs of the Alaska Peninsula and the Alaska Islan are all in a field of present volcanic activity, and though they ha been but little studied many of them are so near active volcanoes to leave slight doubt that they are genetically related to the volcan activity.

The information at hand indicates that there are but few h springs within the belt of profoundly folded rocks that constitu the Pacific Mountain system. Inland of this system, however, li another ill-defined belt of hot springs, which is traceable throug the central Yukon basin. The springs here are associated with ir trusives, in part Eocene and in part probably Mesozoic, that wer fractured and locally invaded by metalliferous quartz veins and sub sequently, in post-Eocene and perhaps in comparatively recent time were again fractured and deformed. The fractures with which th hot springs are associated were probably formed during the late epoch of deformation.

The history of the hot springs of Seward Peninsula is probabl similar, but the age of the intrusives with which the hot springs ar associated in this field has not been determined. It may be Mesozoi or it may be Tertiary.

Quaternary volcanic rocks are widely distributed in both the Yukon Basin and Seward Peninsula. They come from many small vents and possibly from fissures, but the volcanic accumulations are not extensive. There is no evidence that the hot springs are genetically related to these Quaternary volcanic rocks, for the surface manifestations of the two phenomena have not been found in association.

Relatively few hot springs have been found in northern Alaska, possibly because this province has been little explored and possibly because of the scarcity of Mesozoic and Tertiary intrusives and of Quaternary volcanics in this part of the Territory.

The conditions of erosion and ground-water circulation in the subpolar region of northern Alaska are very different from those in more temperate zones. As these conditions probably affect the composition of the surface waters, an investigation of the subject seemed desirable. With this object in mind, a start was made in 1914 by H. M. Eakin, who collected a few samples of surface waters from the Yukon Basin and from Seward Peninsula. Advantage was taken of the opportunity afforded by Mr. Waring's journey in 1915 to collect a larger number of samples of river and stream waters. These have been analyzed, and the results are set forth and discussed in this report by R. B. Dole and A. A. Chambers. Relatively few samples of water were collected, however, and these only in summer; and the meager information they afford does not permit

Digitized by Google

final conclusions. It is, however, the only information thus far available to show the composition of surface waters in subpolar regions.

The conditions pointed out in this report that may influence the composition of the waters are (1) the paucity of erosion over large areas, due principally to the mat of moss and other vegetation which mantles the soil and to the small rainfall, and (2) the permanently frozen condition of much of the subsoil in the Yukon Basin and Seward Peninsula, which prevents the circulation of ground water. In the central plateau province of Alaska but little bedrock is exposed to erosion, as compared with that exposed in temperate regions. Rock outcrops are found on the crests of some divides, but by no means on all, for many rounded or flat summits are covered with moss; and much the larger part of the slopes are gentle declivities that are covered with moss, grass, and timber and that show rock only here and there. Relatively few of the streams are cutting on bedrock, most of the valleys being filled with alluvial material contributed in part by present or recent glacial erosion and in part by surface soil creep or by solar fluction. Some material is also contributed by a very slow mass movement of the heavy frozen talus which mantles the lower slopes of the smaller valleys, notably on the sides not exposed to the sun. Erosion of this type yields the familiar asymmetric valleys which are typical of the streams of this province. By lateral swinging the larger watercourses in places cut the valley walls, and small cliffs at such places indicate bedrock erosion. The amount of bedrock exposed to erosion in the province as a whole is very small.

The wide distribution of ground frost is even more typical of this subpolar region than is the dearth of erosion. In numerous excavations made in placer mining the ground is permanently frozen to great depths, beginning 18 inches or 2 feet below the surface, and the alluvium is frozen down to hard rock. In the Klondike the alluvium is frozen to a depth of about 200 feet. At Fairbanks permanent ground frost has been found at many places to a depth of more than 200 feet and the deepest shaft sunk there penetrated 318 feet of frozen alluvium. In Seward Peninsula many holes in permanently frozen alluvium are more than 75 feet deep and one is nearly 200 feet deep. These shafts are all in flood plains, but at many places on north-facing hill slopes ground ice can be found within a foot or two of the surface.

Some ground in the province is not frozen, for causes not determined. Underground channels of water have been encountered in some mine workings and have played havoc with the operations, but these appear to be exceptional. When the moss is stripped the

Digitized by Google

ground thaws, and with open-cut mining or cultivation the upp level of permanent ground frost seems gradually to descend. therefore appears that this ground frost is a survival of a clima colder than the present and is preserved by the nonconducting m of moss and other vegetation. It is natural to attribute it to t climatic conditions that brought about the last glacial advance Alaska, during which but little of the central region was ice covere though glaciers advanced into it from the higher mountains on th north and south.

Although the conditions described are general within the centr plateau region, they by no means prevail throughout the Yukon an Kuskokwim basins. Many of the larger tributaries of these river such as White and Tanana rivers, flowing into the Yukon, hav their sources in the high ranges bordering the plateau province, i headwater basins, where the conditions of erosion are normal excep in so far as they are modified by permanent fields of snow and ic The waters of these streams would therefore probably not differ fro those of normal streams working on similar bedrock in more tem perate zones. Mr. Dole and Mr. Chambers point out that certai marked differences in the composition of Yukon waters taken at dif ferent localities may be due to the influx of tributary rivers whos sources lie in the high ranges outside of the plateau province, wher the abnormal subpolar conditions of erosion and underground-wate circulation persist.

Digitized by Google

MINERAL SPRINGS OF ALASKA.

By GERALD A. WARING.

INTRODUCTION.

Geologists and engineers of the United States Geological Survey, who for a number of years have been investigating the mineral resources of Alaska, have incidentally noted and visited hot springs and other mineral springs in the Territory. About 20 hot springs and several cool carbonated, sulphur, and iron springs had been thus observed prior to 1915, when it seemed desirable to make a more detailed examination of these springs, not only because of their medicinal value or because their waters may be marketable, but because of their relation to the other features of the geology. The writer was accordingly detailed to examine these springs during the field season of 1915, and the present report is an account of field work done in that year between June 15 and September 4. The writer spent the first five days in examining springs between Ketchikan and Wrangell, in the southeastern part of the Territory, in company with Theodore Chapin, of the Survey, who was carrying on geologic studies in the same region. He next visited Warm Springs Bay, on Baranof Island, making the trip from Wrangell in company with G. L. Drake, forest expert, in a launch of the Forest Service, through the courtesy of that bureau. He spent the succeeding 10 days in examining the hot springs on Baranof and Chichagof Islands, and thence went to Whitehorse and down Yukon River to Circle. Four days was spent in visiting Circle Hot Springs and four days in waiting for the next downstream steamer. The Fairbanks and Hot Springs districts were then visited, and about two weeks were spent there, notes being obtained from others on several springs in addition to those that were examined. Three hot-spring localities on the north side of the Yukon below Tanana were then examined. The next stop was at Anvik, on the lower Yukon, where arrangements were made with Rev. John W. Chapman for the collection of daily samples of water from Yukon River throughout a year, for chemical study. During the journey on the Yukon and its tributaries samples of the stream waters were collected for analysis. From

Digitized by Google

as taken to St. Michaels and the
five days were spent in visiting a
nd a group of hot springs.
spent in the Territory, only 5
ork, five days at the end of the
for a southbound steamer, an
ent in travel from one region to
the work was started, and Nor
ed was 4,800 miles, half of this b
the Tanana.
on 23 springs were visited and n
se existence was not before knov
erning two spring groups in sou
n Mr. Chapin, and notes concerni
y H. M. Eakin, G. L. Harring
in, F. H. Moffit, and P. S. Smith
erning 22 springs in the Aleuti
has been compiled from the pub
and Petrof.[3]
ngs listed (see Pl. I), 75 are hot o
ated or "soda" springs, 13 are cool s
s, and 1 is a salt spring. The the
nstitute nearly three-fourths of tho
ng due to the facts that such springs
ng the Alaska Peninsula and in the
hose in the other regions have no c
ation than cool mineral springs. Co
issue at many places of which no re
ulphur springs doubtless occur at ma
ormations of the Territory.

DISTRIBUTION OF SPRINGS.

Alaska may be divided into five geogr
Pacific Mountain system, which en
d islands of the southeastern "panh
l subsidiary ranges in the southern por
e southwestern extension, consisting of
Aleutian Islands; (2) the Central Plate

ng zur Kenntniss der orographischen und geognostisc
Küste Amerikas mit den anliegenden Inseln: Russ.
p. 76, 1850.
and its resources, Boston, 1870.
a, its population, industries, and resources: Tenth C

physiographic provinces of Alaska (unpublished). The
are recognized and described in The geography and
rvey Prof. Paper 45, pp. 15–17 and pl. 2, 1906.

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

which includes the basins of the great rivers, the Yukon and the Kuskokwim; (3) the Rocky Mountain system, embracing subsidiary mountains in the northern part of Alaska; (4) the Arctic Mountain system, which includes the Endicott Range and subsidiary mountains parallel to the Arctic coast; (5) the Arctic slope region, lying north of the Arctic Mountain system.

So far as present knowledge indicates, the hot and other mineral springs appear to be confined almost wholly to the two southern provinces. This apparent fact may be due, however, to our better knowledge of the southern regions, for detailed surveys in northern Alaska may reveal the presence there of both hot and cool springs.

Four general regions in Alaska are known to contain springs—the southeastern part of the Territory, the southwestern peninsula and islands, the Yukon Basin, and Seward Peninsula.

In southeastern Alaska hot springs are fairly common, and most of them appear to be associated with masses of granitic rocks, probably Mesozoic,[1] which have been intruded into the older sediments that occur in a great part of that region. These granitic masses cover large areas in the region, and the springs apparently issue along minor fault or fracture zones in the rock. Carbonated springs also issue at several places in this region. In at least one place (near New Eddystone Rock) the production of carbon dioxide appears to be connected with relatively recent volcanic activity. In other places the carbonic-acid gas is of more obscure origin, but it may be generated by intrusive rocks or be derived directly from limestone, of which the gas is a constituent.

Nearly all the reported springs of the Alaska Peninsula and the Aleutian Islands are hot and are evidently direct results of volcanic activity, for the region includes many volcanoes, some of them still active.[2] It is worthy of note, however, that although the Wrangell region, in southern Alaska, includes a great lava-covered area[3] and Mount Wrangell is still mildly active, no hot springs are known to have been reported in this region. Small areas of lavas of Quaternary age are widely distributed in the Yukon basin,[4] and in the Pribilof, Nunivak, and Nelson islands in Bering Sea,[5] but no hot

[1] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, pp. 57–58, 1908.

[2] The geology of portions of the peninsula is described by Atwood, W. W., Geology and mineral resources of parts of the Alaska Peninsula: U. S. Geol. Survey Bull. 467, 1911.

[3] Mendenhall, W. C., Geology of the central Copper River region, Alaska: U. S. Geol. Survey Prof. Paper 41, pp. 54–57, 1905.

[4] The following publications contain geologic maps showing areas of late volcanic rocks in portions of the Yukon basin:

Prindle, L. M., A geologic reconnaissance of the Fairbanks quadrangle, Alaska: U. S. Geol. Survey Bull. 525, pls. 8 and 11, 1913; also, A geologic reconnaissance of the Circle quadrangle, Alaska: U. S. Geol. Survey Bull. 538, pl. 2, 1913.

[5] Brooks, A. H., The geography and geology of Alaska, a summary of existing knowledge: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

Digitized by Google

springs are known to be associated with them. Detailed st
the Alaska Peninsula and the Aleutian Islands may reveal, in
tion to the many hot springs, cool carbonated and cool s
springs also; for both carbon dioxide and hydrogen sulphi
common accompaniments of volcanic activity and in some
are thrown out long after other evidences of volcanism have c

The known hot springs in the Yukon basin form three more
well-defined groups, consisting of those in the region between
and Fairbanks, those in the Hot Springs-Eureka district, and
in the region north of the Yukon between Tanana and Ruby.
hot springs in these areas, like those in southeastern Alaska, se
be associated with masses of intrusive granitic rock, most of v
however, are smaller than the similar masses in that region. A
eral places the occurrence of hot springs at the borders of
granitic masses suggests strongly that they rise along the frac
zone between the intrusive granite and the country rock; at o
however, the relation of the springs to intrusive rocks is
obscure.

There are three well-known groups of hot springs on Se
Peninsula, and two other groups are also reported, whose posi
and characteristics were not definitely learned. Arctic Hot Spr
in the northern part of the peninsula, are at the western edge
small area of intrusive granite, where the relation of intrusive
to the hot water appears to be well shown, but at the other spr
on the peninsula that have been examined the source of the hot w
is not so apparent. A number of cool carbonated springs also i
on Seward Peninsula. Two or three of them seem to be plaus
ascribed to the intrusion of small masses of lavas or dike rocks
the country rocks,[1] but as these consist in large part of limestone
may possibly furnish the carbon dioxide.

MINERAL WATERS.

All spring, river, and other natural waters might, strictly spe
ing, be termed mineral waters, for to a greater or lesser degree w
dissolves nearly every substance with which it comes in contact.
natural waters therefore contain more or less mineral matter
solution. Generally speaking, however, only waters that carry s
cient amounts of material in solution to give them a perceptible t
are popularly known as mineral waters.

The use of mineral waters at health resorts, under the care
competent physicians, is often attended with very beneficial resu

[1] The general geology of the peninsula is shown in a report by Collier, A. J., and oth
The gold placers of parts of Seward Peninsula, Alaska: U. S. Geol. Survey Bull.
pls. 10 and 11, 1908.

Digitized by Google

One of the chief sources of benefit is doubtless the change of habits and the relaxation at such places, but the proper use of the water itself, aside from its mineral constituents, both for drinking and for bathing, is capable of producing great improvement in health. The mineral springs of Alaska have been used most beneficially for bathing. The several springs that are thus used locally have been of great benefit to prospectors and miners, who, after weeks or months of work in the cold waters of the creeks, find great relief from rheumatism in hot-spring baths.

Few highly mineralized waters have been found in Alaska, but as the substances in solution in even moderately mineralized springs have some effect on the human system, the more common substances found in them and their chief effects are briefly stated below.

Silica (oxide of silicon, SiO_2) is the chief constituent of most kinds of rock, mainly in the form of quartz. It is only slightly soluble in ordinary water and hence is present in most waters in only small amounts, 50 parts per million being an unusually high proportion. It is believed to be usually present in water in suspension, as a colloid, or in solution as a silicate or a hydrated silicic acid. Silica in the amounts found in most waters is believed to have very little effect on the human system.

Iron and aluminum are very common in rocks, but, like silica, neither is taken into solution in large quantities by most natural waters. Most waters contain more iron than aluminum, which in many waters occurs in an amount so small that it in analyses is not determined separately from the iron. The total amount of both is rarely more than 25 parts per million. The medicinal value of aluminum in most waters is insignificant. Water containing iron is considered to be of some benefit for drinking, in remedying a deficiency of iron in the blood. Iron-bearing waters are likely to form rusty spots on clothes washed in them and may stain bathtubs and washbasins.

Calcium and magnesium are very common in feldspar and certain other rock minerals. They are fairly soluble and are present in many waters in considerable amounts. The proportion of calcium is usually two to five times that of magnesium. Both substances render water "hard" and are the main basic constituents of the hard scale that is deposited in teakettles and steam boilers. Waters containing considerable amounts of calcium carbonate or magnesium carbonate are of value in neutralizing acidity of the stomach and thus in relieving certain forms of indigestion. Calcium and magnesium waters that contain predominant amounts of chloride and sulphate instead of carbonate are believed to tend to form calculi (gallstones).

Digitized by Google

cal reactions, such as the oxidation of pyrite (iron sulphide) t sulphate, liberate heat and may also thus increase the temper of underground waters.

The results of analyses of water are reported in several way of late years the statement of the radicles present in parts per n by weight is most common and is used in this report. The an of the constituents stated in the analyses therefore indicate th portion, by weight, of the several constituents to the weight mineralized water. For instance, the statement that the amou calcium radicle in a water is 200 parts per million means that in million pounds of the water there is 200 pounds of calcium indicate this in quantities that can be better appreciated, it m stated that a heaping teaspoonful of an ordinary salt dissolv 1 gallon of water represents approximately 4,000 parts per mi a rounding teaspoonful about 2,500 parts; a thimbleful abou parts; and the amount that can be held on the point of a pen 10 to 20 parts.

The minimum amount of solid material in solution that is pe tible to the taste varies greatly with the substance, and to less, th marked, degree with the individual. As small an amount as tv three parts per million of iron is distinctly perceptible to some pe but several times as much aluminum is only barely so. The alk (sodium and potassium) and the alkaline earths (calcium and n nesium) are much less easily detected by the taste. About 200 p per million of calcium or magnesium render a water notice "hard." It is probable that chloride and the carbonate and sulp radicles are the ones that give the distinctive tastes to most min waters. About 250 parts per million of chloride renders a water tinctly salty. Of dissolved gases that are present in some wate or 5 parts per million of hydrogen sulphide gives a perceptible like flavor.

Most of the analyses of the spring waters were made under cont by S. C. Dinsmore at Reno, Nev. Analyses of several were mad the laboratory of the United States Geological Survey by R. B. I and Alfred A. Chambers. Analyses of two waters (from Bara Hot Springs and Chena Hot Springs), made by the Bureau of Ch istry, United States Department of Agriculture, are also reprodu through the courtesy of that department.

The analyses of the Alaskan spring waters have been examined Mr. Chambers, and remarks on the character of each are included the descriptions of the individual springs.

An unusual feature of nearly all the waters is their high conte of silica. The available analyses indicate that in the springs sodium carbonate and calcium carbonate type the ratio of silica sodium plus potassium is considerably higher than it is in the s

Digitized by Google



PRINGS

Digitized by Google

Digitized by Google

phate and chloride waters. This characteristic seems to be reasonably explained by the fact that in solution the carbonates of the alkalies and alkaline earths hydrolize, producing alkaline solutions that tend to dissolve silica; whereas the sulphates and chlorides in hydrolizing produce solutions that tend to precipitate rather than to dissolve silica.

HOT SPRINGS.

SOUTHEASTERN ALASKA.

DISTRIBUTION.

Hot springs are fairly common on the islands that compose a large part of southeastern Alaska and on the adjacent mainland. Those reported (see Pl. II) may be divided into three geographic groups—those of Revillagigedo Island and the adjacent mainland, those along Stikine River, and those of Baranof and Chichagof islands.

Because of the lack of definite knowledge that hot springs are absent in the areas between these general groups, and because of the lack of detailed information as to the structural conditions in the region, an attempt to draw broad conclusions from the distribution of the springs is probably unwarranted. The springs seem, however, to be definitely related to intrusive masses of rock, principally of granitic material, in the schists, graywackes, and other more or less altered rocks of the region, and appear to issue along zones of fracturing or faulting in the intrusive rocks.

BELL ISLAND HOT SPRINGS.

Bell Island Hot Springs (102[1]) are on the western end of Bell Island, about 50 miles by water north of Ketchikan. (See Pl. III, *A*.) The property was taken up as a homestead in 1902 by George Roe, who erected a bathhouse and a number of cabins along a board walk extending to a landing place opposite the boat anchorage and developed the springs as a resort for the medicinal use of the water. On his death in 1914 the management of the place was continued by his two brothers.

The principal springs issue at the north edge of a small creek, about 400 yards from and 15 feet above high-tide limit in the narrow cove into which the creek empties. The water rises from a narrow fissure about 15 yards long in biotite granite cut by small veins of pegmatite. The rock surface at the springs has been concreted into five basins, each about 4 feet deep, the largest being about 3 by 10 feet in width and length. The observed temperatures of the water in the several basins range from 125° to 162° F. From the western-

[1] Numbers in parentheses correspond to locations indicated on Pl. I (in pocket).

Digitized by Google

most and hottest basin a part of the water is conducted to an adjacent bathhouse having two wooden tubs in separate rooms. Cool water for the bath is also obtained from the springs by conducting it first through a gratelike arrangement of pipe in the bottom of the cold-water creek.

The waters of all five basins are probably very similar in chemical character, though the coolest basin is locally considered to be less mineralized than the others. In taste and smell they are only mildly sulphureted. The analysis (tabulated on p. 25) of water from the hottest basin shows it to be high in mineral content and of the sodium chloride type, though sulphate is also present in amount secondary only to the chloride.

The total flow of the five basins, as nearly as could be estimated, is 8 or 10 gallons a minute.

About 125 yards downstream from the main group a sixth spring, having a temperature of 109° F. and a flow of about half a gallon a minute, issues in a small board-curbed pool at the base of a large granite boulder. This spring is seldom used, however, and only for drinking. Unlike the hotter springs, whose basins are clear, this cooler spring is lined with a white, jelly-like algal material, whose growth is probably favored by the lower temperature. No other hot or mineral springs were reported on the island.

Evidences of slickensiding in the rock near the springs give indication of some faulting in the vicinity; and this may allow the escape of deep-seated hot water along the well-marked fissure—presumably of fault origin—from which the springs rise. The island and neighboring mainland appear to be composed entirely of granitic material,[1] and no evidence of volcanic activity or of other plausible cause for the presence of the hot springs was noted.

The location of the springs in a sheltered cove near a good anchorage for small boats and within a fairly short run from Ketchikan makes them well situated for a pleasure and health resort in this southeastern part of Alaska, which is rapidly becoming recognized as ideal for summer cruising.

BAILEY BAY HOT SPRINGS.

Bailey Bay Hot Springs (100 on Pl. I) are best reached by launch to the head of Bailey Bay, from which they lie about 3 miles to the northwest, on a creek that empties into Lake Shelockum (Mirror Lake), whose surface stands about 330 feet above the bay. The Forest Service has built a trail from the shore of the bay up the steep

[1] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, pl. 2, 1908.

Digitized by Google



A. BELL ISLAND HOT SPRINGS, SOUTHEASTERN ALASKA.



B. MELOZITNA HOT SPRINGS, RUBY REGION.

Digitized by Google

Digitized by Google

slope to the south end of the lake. Thence the springs may be reached by rowboat to the west side of the lake and a quarter of a mile up the creek.

The hot water issues from at least nine springs on the steep slopes on the south side of the creek, the vents lying 40 to 150 feet above the stream. Their positions are shown in figure 1, which was prepared from the survey of the property made by the Forest Service.

Number of spring	Elevation in feet above creek July, 1914	Temperature, degrees Fahrenheit	Flow, gallons per minute
1	40	179	22.7
2	40	177	9.1
3	81	186	14.1
4	102	145	3.8
5	121	150	14.8
6	119	153	0.6
7	152	168	2.7
8	96	183	11.2
9	96	191	3.5
		Total	82.5



FIGURE 1.—Sketch map of Bailey Bay Hot Springs and vicinity, southeastern Alaska.

Digitized by Google

When visited in 1915 water from the lowest two springs was conducted to a wooden bathtub in a tent near by. The other springs were unused, though a quantity of wood-stave pipe had been brought as far as the lake, the intention having been to pipe the hot water down to a hotel to be built near the bay.

The individual flow of the springs is from about half a gallon to more than 20 gallons a minute, and the total yield, as measured by the Forest Service, is 82½ gallons a minute. The observed temperatures ranged from 145° to 191° F. The hottest spring had the relatively small flow of only 3½ gallons a minute, and the spring of largest flow, which is the lowest and the one used for bathing, had a medium temperature for the group of 179° F. Water for cooling the bath was obtained from an adjacent small cool-water stream. One of the central springs of the group (No. 3 in fig. 1), is the most interesting, as its water issues from a small fissure in a jet 12 inches high, under a pressure that is probably due to hydrostatic head from the slopes above. In 1905 F. E. Wright[1] noted that this jet spurted up 15 inches, and that the water had a temperature of 203° F. The lower temperature and less pressure of the jet in 1915 may represent positive though perhaps temporary decreases that were probably due, in part at least, to rain and the consequent saturation of the surface soil with cold water at the time of the writer's visit.

The rocks of the region are granitic,[2] with some marble-white phases in which mica is scarce, and with pegmatite veins carrying large flakes of black mica. As viewed from the north the springs appear to issue on a steep talus slope at the base of steeper slopes and cliffs of granite. When examined closely, however, each spring appears to issue from bedrock and, like the jet spring, from a crevice in the granite.

The water in each spring basin is clear and shows considerable bubbling of gas that is probably mainly carbon dioxide but that includes enough hydrogen sulphide to give a faint but characteristic odor of bad eggs. Reddish to green algal growths in the pools and overflow channels vary in color and texture apparently with the temperature of the water and the swiftness of its flow. They are probably Cyanophyceae, of which there are several varieties, which grow in natural hot waters up to a temperature of fully 180° F.—a temperature that will soft boil an egg in about 5 minutes.

Small amounts of carbonate, probably of calcium and magnesium, are deposited on stones along the run-off channels of the springs, presumably at the points where the escape of carbon dioxide from the water is sufficient to cause the precipitation of a portion of the material held in solution.

[1] Op. cit. [2] Idem, pl. 2.

Digitized by Google

The analysis of water from the jet spring (tabulated on p. 25) shows that it is a moderately concentrated water of the sodium carbonate type. The silica content is unusually high, constituting nearly one-third of the total mineral matter in solution. When present in such a large amount it seems probable that a portion of the silica is present as soluble silicate.

The issuance of the springs at such notably different elevations on a steep slope is unusual and indicates that the several fissures are not closely connected, because all the hot water would tend to flow from the lowest spring. No topographic or other suggestive evidence of faulting in the vicinity of the springs was noted; but the fractured character of the rock in the region suggests that, though actual faulting of considerable extent may not have taken place, deep fractures may be present, which permit the upward escape of the hot water.

HOT SPRINGS NEAR UNUK RIVER.

Hot springs are reported on the north bank of Unuk River (104) about 6 miles above its mouth,[1] but at the time the region was visited by the writer no guide was found who knew their location. They are believed, however, to be of rather small flow and neither very hot nor notably mineralized. The water probably issues from fissures in the granitic material that constitutes the country rock over large areas in the region.

HOT SPRINGS NEAR SAKS COVE.

A group of hot springs (103 on Pl. I) on the eastern side of Behm Canal, about 10 miles southeastward of the mouth of Unuk River (Burroughs Bay) and 5 miles southeast of Saks Cove, was reported to the writer by Mr. W. H. Babbitt, of the Forest Service.

The springs are said to be similar in general character to Bell Island Hot Springs, yielding approximately an equal amount of scalding water that is slightly sulphureted. The water issues in part at the rocky shore and in part directly from a fissure in granite 200 feet back from the shore. The springs are probably similar in mode of occurrence and chemical character to those on Bell Island, near Bailey Bay, and near Unuk River, and, like these, are probably best ascribed to the escape of deep-seated water along fissures in the faulted and fractured granitic rocks that cover an extensive area in the region.[2]

[1] Wright, F. E., and Wright, C. W., op. cit., p. 201 and pl. 2.
[2] Idem, pl. 2.

Digitized by Google

SHAKES HOT SPRINGS.

Hot springs that have long been claimed by the Indian Chief Shake, who lives at Wrangell, issue on the north edge of the valley of Stikine River, about 20 miles northeast of Wrangell (100 on Pl. I). During the summer the springs are easily accessible by boat up the river and a slough and tributary creek, from which last they are distant only 200 yards.

They issue at the base of a granite cliff that abruptly limits the valley. Their exact point of issuance is obscured by boulders and undergrowth, but the water seems to come forth in a single stream only a few feet above the valley alluvium. Very probably it rises through a fissure in the intrusive granitic material that forms the greater part of the coastal ranges.[1]

The water has a temperature of 125° F. and a flow of about 100 gallons a minute. It has no appreciable taste nor odor, and no evidence of escaping gas was seen. An abundant growth of green algae lines the run-off channel and pools. The analysis included in the following table (analysis 3) shows that it is a moderately concentrated sodium sulphate water. The content of chloride is notably low. Silica is an important constituent, forming about one-quarter of the total mineral matter in solution.

A part of the flow is conducted in a small trough to a wooden tub in a bathhouse a few yards away, and a cabin and woodshed have been built near by.

The springs are used to some extent by Chief Shake and his tribesmen for bathing and also occasionally by whites. They are easily reached only during the summer months, however, and at least one tragedy is connected with their use. In 1915 the hull of a small boat, half sunken in the slough near the springs, marked the place where two whites had perished while attempting to return to Wrangell after the winter freeze-up had started.

From the river a few miles below the springs an excellent view is obtained of Popof Glacier, clinging to the steep mountain side on the north.

[1] Wright, F. E., and Wright, C. W., op. cit., pl. 8.

Digitized by Google

Mineral analyses of waters from hot springs in southeastern Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2[a]	3
Silica (SiO_2)	105	142	108
Iron (Fe)	[b] 1.2	1.5	[b] 1.2
Aluminum (Al)		2.2	
Calcium (Ca)	4.6	13	13
Magnesium (Mg)	1.0	2.1	.4
Sodium (Na)	[c] 201	[c] 54	87
Potassium (K)			9.2
Carbonate radicle (CO_3)	13	53	18
Bicarbonate radicle (HCO_3)	37	27	43
Sulphate radicle (SO_4)	129	32	142
Chloride radicle (Cl)	188	11	6.5
Nitrate radicle (NO_3)	.....	Tr.	.....
Total dissolved solids at 180° C.	674	413	409
Temperature (° F)	162	186	125
Chemical character	Na-Cl	$Na-CO_3$	$Na-SO_4$

[a] Borax present. [b] $Fe_2O_3+Al_2O_3$. [c] Calculated.

1. Bell Island Hot Springs; lowest and hottest basin. Has slight odor of hydrogen sulphide. Sample collected June 6, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.
2. Bailey Bay Hot Springs; "jet" spring. Has slight taste and odor of hydrogen sulphide. Sample collected June 17, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
3. Shakes Hot Springs; principal spring. No perceptible odor or taste. Sample collected June 19, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.

MINOR HOT SPRINGS IN THE WRANGELL REGION.

Minor hot springs in the general region of Shakes Hot Springs are reported from three localities: F. Matheson, of Wrangell, reported small flows of hot water (99) in the valley alluvium a few miles westward from Shakes Springs, and K. J. Johansen, also of Wrangell, reported, on authority of the Indians, small hot springs (98) on the south side of Stikine River, 6 or 8 miles upstream from Wrangell. As the lowlands are covered with dense undergrowth and a guide who knew the locations of the springs was not readily found, no attempt was made to examine these minor springs. The third locality in the Wrangell region was reported by George Peterson, of the Forest Service, who had heard that hot water (97) issues at low-tide level near the light on the south end of Vank Island, about 8 miles west of Wrangell. A description of these springs was not obtained by the writer.

A fourth group, which probably contains the most notable hot springs in the neighborhood of Wrangell, is several miles within Canadian territory, on the eastern side of Stikine River, nearly opposite Great Glacier. These springs are remarkable both for their position, nearly opposite the glacier front, and for their large flow. F. E. Wright, who visited the region in 1905 for the United States Geological Survey, reports that a stream of hot water 10 feet wide is formed by about eighteen springs that issue within a space of 200 yards at the base of a granite mountain. A float measurement of the stream indicated a flow of about 150,000 cubic feet in

Digitized by Google

24 hours (nearly 800 gallons a minute). A green algal growth that forms along the stream indicates by its abundance and color that the water probably has a temperature of about 120° to 150° F. The water is believed by Mr. Wright to issue near or along a fractured zone between the schistose country rock and an intruded granite mass.



FIGURE 2.—Sketch map of Baranof Hot Springs and vicinity, Baranof Island, southeastern Alaska.

BARANOF HOT SPRINGS.

Baranof Hot Springs (91) issue on the slopes between Warm Springs Bay (a small bay on the eastern side of Baranof Island) and Lake Baranof, a small lake that lies near but more than 100 feet above the salt water. The sketch map (fig. 2), based on a sur-

Digitized by Google

vey by the Forest Service, shows the positions and elevations of the several springs, and the accompanying legend gives their respective temperatures and flows.

At each spring the water issues from among granite boulders or coarse granite gravel that overlie bedrock of the same material. The waters of all the springs appear to be similar in character, being distinctly sulphureted but not otherwise very noticeably mineral in taste. The two analyses (tabulated on p. 32) of water from these springs, although not collected from the same spring, are very similar in character. Each water is of the sodium carbonate type, of moderate total mineral content, with silica as an unusually large proportion of the total.

Considerable gas, that is probably carbon dioxide, is given off at several of the springs, and the usual green algae, in places coated nearly white with sulphur, grow along the run-off channels.

The springs have been locally used as a health resort for several years, and a number of cabins have been erected by local dwellers for rental to others who come to the springs. When visited in the summer of 1915 there were three bathhouses, the principal one, containing six wooden bathtubs, being erected near and supplied by spring No. 2. Springs Nos. 6 and 7 also supplied separate tubs in a cabin adjacent to them and spring No. 5 supplied a large wooden tub in a near-by cabin. Water from spring No. 8 was piped down to two or more cabins near the bay. Spring No. 9 issues from a crevice at the low-water edge of the stream that cascades from Lake Baranof to the bay and was not accessible.

The main country rock of the locality consists of intrusive granitic materials,[1] but in the vicinity of the springs dioritic and possibly more basic rocks appear. Prominent, straight, narrow, parallel gorges on the southern side of the bay indicate possible faulting. As was pointed out by Joseph McCoombs, who lives at the springs, the boulders on the north side of the stream in the immediate vicinity of the springs are rounded as if waterworn, whereas those in the present stream channel are angular. It would therefore appear that the stream has comparatively recently shifted its course, possibly owing to faulting. Although the evidence presented by the gorges and the boulders is by no means conclusive, the springs appear to be in a locality of some crustal movement, and may possibly be ascribed to fault fissures that allow the upward escape of deep-seated water.

The bay and lake are surrounded by snow-covered mountains, and the locality is reported to receive a considerably greater snowfall than the remainder of the island. The winter climate is fairly mild, however, and parties occasionally spend the winter at the springs.

[1] Knopf, Adolph, The Sitka mining district, Alaska: U. S. Geol. Survey Bull. 504, pl. 1, 1912.

Digitized by Google

SITKA HOT SPRINGS.

Sitka Hot Springs (92 on Pl. I), which lie 16 miles down the coast from Sitka, were perhaps the earliest of Alaska's mineral springs known to white men. (See Pl. IV, *A*.) They were visited in 1841 by Sir George Simpson, governor in chief of the Hudson Bay Co.'s territories in North America, who wrote of them as follows:[1]

> The establishment in the neighborhood consisted of three snug cottages, being kept in order by an old fellow of a Russian and his daughter. * * * This establishment is employed as a hospital for invalids from Sitka. * * * In the neighborhood there are four distinct springs. * * * At its source the principal spring possesses a temperature of 54° R., or 153½° F., being hot enough, as we found by experiment, to cook an egg in eight minutes. From this spring the two baths, one for the natives and the other for the whites, are fed, while by flowing about 50 yards through several channels the waters are reduced to an average temperature of 130° F., or 43½° R.
>
> As this natural "medicine" is held in high estimation by the surrounding tribes, the native bath enjoys no sinecure of it. When the country is sufficiently peaceable for moving about it safely, the savages think nothing of coming two or three hundred miles to benefit by the healing waters, while they do their best to take their traveling expenses out of them by lying in soak for hours at a time, with nothing but their heads visible, eating, drinking, and, I may add, sleeping in the bath.

Besides showing the early development of the springs by the Russians, the account of Sir George is of interest in stating that the natives used the springs extensively. So far as the writer could learn, no other hot springs visited by him had in early days received much attention from the natives. Of late years, however, springs that have been developed and used by the prospectors have come to be used to some extent by the natives.

The higher maximum temperature of 153½° F. recorded by Sir George in 1841, as compared with the maximum of 149° F. noted by the writer in 1915, possibly indicates a slight cooling of the water; but the point of observation, the depth of immersion of the thermometer and its accuracy, and the amount of cold water infiltrating from the rain-soaked ground may easily account for the small difference.

Dall,[2] writing of the history of the country, says that in 1861

> a hospital for skin diseases was opened at Sitka, near the sulphur springs. The water contained sulphur, iron, chlorine, and manganese, and had a temperature of 122° F. * * * Whitby records the existence of hot saline springs below high-water mark near Sitka.

The "sulphur springs" mentioned are very probably the Sitka Hot Springs, as no springs in the immediate vicinity of Sitka are

[1] Simpson, Sir George, Narrative of a journey round the world during the years 1841 and 1842, vol. 2, pp. 194–196, London, 1847.

[2] Dall, W. H., Alaska and its resources, pp. 353, 472, Boston, 1870.

Digitized by Google

A. SITKA HOT SPRINGS, BARANOF ISLAND, SOUTHEASTERN ALASKA.



B. TENAKEE HOT SPRINGS, CHICHAGOF ISLAND, SOUTHEASTERN ALASKA.

C. CIRCLE HOT SPRINGS, CIRCLE DISTRICT.

Digitized by Google

Digitized by Google

known to the writer. The locality of the "hot saline springs" is not given by Dall; hot water may issue alongshore at Sitka Hot Springs, but of late years such springs have not been recognized.

For several years the Sitka Hot Springs have been conducted as a health and rest resort, a hotel and several cottages furnishing accommodations for about 30 guests. The principal buildings are about 100 yards from and 50 feet above the beach, and the springs issue from slopes somewhat higher. The observed elevation, temperature, and flow of each of the four springs are as follows:

	Elevation above highest high tide.	Temperature.	Flow.
	Feet.	°*F.*	*Gals. per min.*
Main Spring	60	149	9½
Magnesia Spring	55	142	2½
Sulphur Spring	55	124	1½
Old Russian Spring	80	95	(a)

a No appreciable flow.

The flows of the several springs increase from the coolest to the hottest, the hottest spring yielding much more water than the total flow of the others. This is unusual; in most groups of hot springs the highest temperature is apt to be found in a spring of minor flow.

The Old Russian Spring was unused in 1915, and formed a pool that was still curbed with logs said to have been put in place many years ago. The Sulphur Spring, about 40 yards to the northwest, supplied a small bathhouse reserved for the natives. Water from the other two springs was piped down to the hotel, 30 yards away, and in addition to supplying several bathrooms was also used in a hot-water heating system for the building.

Analyses of waters from the two larger springs tabulated on page 32 show that they are almost identical in composition. Each is a highly mineralized sodium chloride water and is essentially a weak brine. Chloride constitutes more than one-half of the total solids. Relatively small amounts of carbonate and bicarbonate are present and magnesium is very low. Although the waters are saline they evidently are not derived from the near-by sea, for the relative proportions of the constituents are not the same as in sea water. For example, in the spring waters the ratio of calcium to sodium is about 1:3.6, and of sulphate to chloride the ratio is about 1:30; whereas in sea water these ratios are respectively about 1:30 and 1:7.

In the vicinity of the springs the granite from which the hot waters issue is cut by narrow dikes of darker rock, resembling diabase, that

Digitized by Google

is classed as a spessartite (garnet) lamprophyre.[1] In the numerous rocks and islets dotting the water northward between the springs and Sitka hard metamorphosed sandstones and other sediments of Mesozoic age[2] are penetrated by dikes and massive bodies of intrusive granite. Although the hot waters issue at the surface from granite they may owe their escape from considerable depths to



FIGURE 3.—Sketch map of hot springs near Fish Bay, Baranof Island, southeastern Alaska.

crevices or fissures along contact zones between the intrusive granite and the altered sedimentary rocks.

HOT SPRINGS NEAR GUT BAY.

E. W. Merrill, of Sitka, told the writer that a few years ago he found the water of the first creek on the northern side of Gut Bay, on the eastern coast of Baranof Island (93), to be warm and to taste

[1] Alaska, vol. 4, p. 18, Harriman Alaska Expedition, 1904.
[2] Knopf, Adolph, op. cit., pl. 1.

Digitized by Google

disagreeably, probably of hydrogen sulphide. Search was not made for the source of the warm water, but it very probably comes from springs near the creek channel and not far upstream.

The rocks in the vicinity of Gut Bay are of Paleozoic age, comprising limestone and schists as well as greenstones and other varieties of ancient lavas.[1] The hot water possibly rises along a fractured and fissured zone in the country rock.

HOT SPRINGS NEAR FISH BAY.

A number of hot springs (89 on Pl. I, in pocket) issue along a small stream about 3 miles east of the head of Fish Bay, 40 miles north of Sitka. These are possibly the springs that have been referred to as being in Cook Bay.[2] Evidence that Fish Bay has been known as Cook Bay is not at hand, however, nor is there any other bay on Baranof Island that is generally known as Cook Bay.

The positions of the several springs and their temperatures and approximate discharges are shown in figure 3. The waters of the several springs appear to be very similar; all are mildly sulphureted but not otherwise notably mineral in taste. More or less active bubbling is caused at the several vents by a gas which, when collected in a bottle, extinguishes a flame and is probably carbon dioxide.

The analysis of water from spring m (see fig. 3), included in the following table (analysis 5), shows that it is a sodium carbonate water of moderate concentration. Unlike most of the hot-spring waters the chloride content is very low. Silica is high, as it is in other of the Alaskan waters. The presence of 34 parts per million of the borate radicle (B_4O_7) is noteworthy and seems to indicate the presence of volcanic emanations of intrusive volcanic rocks carrying appreciable amounts of boron.

[1] Knopf, Adolph, op. cit., pl. 1.

[2] Wright, C. W., Nonmetallic deposits of southeastern Alaska: U. S. Geol. Survey Bull. 284, p. 60, 1906.

Digitized by Google

Mineral analyses of waters from hot springs in the Yukon River basin, Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2 [a]	3	4	5
Silica (SiO_2)	96	71	96	122	110
Iron (Fe)	[b] 1.8	[b] .60	.75	.5	.7
Aluminum (Al)			1.6	2.1	1.6
Calcium (Ca)	4.6	2.4	378	378	13
Magnesium (Mg)	1.1	.2	7.2	2.6	2.4
Sodium (Na)	[c] 58	55	1,440	1,365	[c] 69
Potassium (K)		2.3	60	57	
Carbonate radicle (CO_3)	.0	35	.0	.0	62
Bicarbonate radicle (HCO_3)	98	30	29	31	43
Sulphate radicle (SO_4)	49	43	88	97	24
Chloride radicle (Cl)	9.8	2.8	2,745	2,740	4.5
Nitrate radicle (NO_3)		Trace.	.0	.0	Trace.
Borate radicle (B_4O_7)		.0	Trace.	Trace.	34
Total dissolved solids at 180° C.	268	[d] 228	4,877	5,046	388
Temperature (°F.)	122		149	142	117
Chemical character	$Na-CO_3$	$Na-CO_3$	Na-Cl	Na-Cl	$Na-CO_3$

[a] Contains 0.1 part per million of lithium; negative tests obtained for phosphate, arsenate, manganese, and strontium.
[b] $Fe_2O_3 + Al_2O_3$.
[c] Calculated.
[d] By summation, with bicarbonate computed as carbonate.

1. Baranof Hot Springs; uppermost spring (No. 7 of fig. 2). Sample collected June 22, 1915, by G. A. Waring; analyzed by R. B. Role and Alfred A. Chambers.
2. Baranof Hot Springs; probably from spring No. 8 of fig. 2. Sample collected Aug. 13, 1913, by W. G. Weigle; analyzed by F. B. Furber, Bureau of Chemistry, U. S. Dept. Agriculture.
3. Sitka Hot Springs; principal spring. Tastes salty and distinctly of hydrogen sulphide. Sample collected June 25, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
4. Sitka Hot Springs, "Magnesia Spring." Tastes distinctly salty and has faint odor and taste of hydrogen sulphide. Sample collected June 25, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
5. Hot Springs near Fish Bay; principal spring. Has slight odor and taste of hydrogen sulphide. Sample collected June 26, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

Algal growths, the usual accompaniment of thermal sulphureted water, form greenish leathery coatings along the run-off channels. At two or more places along the small creek there are deposits of black muck, similar to that at Kruzgamepa Hot Springs (13), which A. F. Rogers, of Stanford University, examined microscopically and found to consist of opaque, black colloidal ferrous sulphide, diatoms, and earthy matter.

Fish Bay Hot Springs were first made accessible to white men by William Hanlan, of Sitka, who was told of their approximate location by Indians. After two unsuccessful trips, he found them about 1905, cut a trail to them through the dense forest, and constructed the log bathing pool at spring m (fig. 3). Within recent years they have been frequently visited by the men from the logging camp of W. R. Eubanks, at the head of the bay. Several of the springs have been excavated and used either as clear-water or as mud baths.

A considerable area east of Fish Bay and also the higher slopes to the south and west are occupied by Paleozoic schists and associated rocks, but the bedrock in the vicinity of the bay is composed of later granitic materials, intruded into the older formation. The eastern border of the intrusive belt is in the neighborhood of the springs.[1]

[1] Knopf, Adolph, op. cit., pl. 1.

Digitized by Google

Rock is not well exposed at the springs, being covered by soil and loose material, but the fragments examined are of schist, with quartz veins. On the northern shore at the head of the bay a coarsely crystalline hornblende-feldspar rock is exposed. The steep, forested slopes along the northern shore are scarred by numerous landslides, which suggest a broken or crushed condition of the underlying rock. The small creek, along whose western side almost all of the hot springs issue, may also follow either a crushed zone in the bedrock or possibly even the contact zone between the schist and the hornblende rock.

The shore at the head of Fish Bay is flat and covered with subangular stones, the largest about 6 inches in longest dimension. The normal tides here have a range of about 10 feet and alternately cover and expose the beach for about a quarter of a mile. While the tide is coming in bubbles issue at many places in the water near the shore, suggesting that carbon dioxide or other gas may be escaping from the ground. A test with a flame indicated, however, that it is air, which has probably been trapped in the porous gravelly beach by the rapidly rising tide.

HOT SPRINGS ON NORTH ARM OF PERIL STRAIT.

On the north shore, about three-quarters of a mile eastward from the head of North Arm of Peril Strait (Hooniah Sound), heated water (87) issues at about half-tide level from the mussel and kelp covered rocks. As the warm water rises beneath or flows into the cold sea water, its presence is betrayed by convection currents, which give an oily appearance to the surface; but when examined at low tide the warm water has no noticeable taste nor odor. There is only a little bubbling, as of gas, and a small amount of dark-green vegetable growth, either algae or a seaweed.

The three principal springs found issue from fissures in the rock, separated by spaces of 5 and 2 feet, about 100 yards northwest of a small cold-water stream. The temperature of the springs was 101° F., and their flow per minute, as near as it could be measured, was, respectively, about 1½ gallons, a quarter of a gallon, and three-quarters of a gallon, but the discharge appeared to diminish as the tide fell, perhaps in part because of the draining off of contaminating sea water from the adjacent rocks above the springs, but probably in greater part because of the lowering of the hydrostatic pressure by the falling tide and the escape of the warm water from lower crevices.

The analysis of the water of the largest of the three springs (analysis 1, p. 40) shows that it has a high total mineral content

Digitized by Google

and is of the sodium sulphate type. Although the sample collected contained considerable chloride it seems not to have been greatly contaminated with sea water left in the moss and gravel by the receding tide, for if it had been so contaminated it would have contained more chloride than sulphate.

Beneath a low cemented gravel bank, near a large boulder 100 yards northwest of the principal group of springs, slightly warmer water (temperature 103° F.) forms oil-like convection currents over an area of several square yards in the adjacent bay water, but the outlet of this spring lowers with the tide, so that its discharge is not measurable. No other warm springs were found in a search extending from the head of the bay to a point a quarter of a mile east of the cold-water stream near the main spring group.

Cliffs of massive granitic material rise from the narrow bouldery talus slope along the shore. In the main the rock seems to be comparatively unaltered, but near the springs there is a zone, possibly a dike, of fractured and altered dioritic rock. In the hand specimen this material shows considerable epidote and chlorite, products of the alteration of the original hornblende, and F. L. Hess, of the United States Geological Survey, noted that it contains much sphene. The escape of the spring water, probably heated either by the depth from which it rises or by chemical reactions in the altered rock, is apparently facilitated by the presence of this fractured mass of rock in the larger mass of intrusive crystalline material of the region.[1]

Because of their inconspicuous issuance and their inaccessible location for bathing the springs are little known, and no attempt has been made to improve them.

HOONIAH WARM SPRINGS.

Hooniah Warm Springs (86) are on the oceanward coast of Chichagof Island, about 70 miles northwest of Sitka. They may be reached by launch in calm weather, but as the coast is rocky and there is usually a heavy surf they have not been often visited. A log bathhouse or sweat chamber has been built over the principal spring, however, and the locality is the occasional camping place of hunters and trappers. The springs are in a small rock cove, in which much driftwood is cast up, on a beach of large rounded stones.

The principal spring issues at the edge of the forest, a few feet above the limit of drift logs and about 25 yards from and 15 feet above normal high-tide level. The water issues at a temperature of 111° F. from a vertical opening the size of one's hand, in dark hard schistose rock. After flowing through a natural rock pool, over

[1] Knopf, Adolph, The Sitka mining district, Alaska: U. S. Geol. Survey Bull. 504, pl. 1, 1912.

Digitized by Google

which the bath chamber has been built, the discharge—30 gallons a minute—cascades down to tidewater.

The spring water tastes only faintly sulphureted, and there appears to be no escape of gas. A noticeable bubbling in the water below a small cascade in the run-off channel is probably due to air trapped in the cascade, rather than to gas escaping from the water. Much pale salmon-colored to white, stringy algal growth forms along the run-off channel, as is usual at sulphureted warm springs.

The analysis of water from this spring, tabulated on page 40, shows that it is a moderately concentrated sodium chloride water containing considerable sulphate. Silica forms more than a third of the total content, possibly in part as a soluble silicate.

A second spring, with a temperature of 110° F. and a discharge of about a gallon a minute, issues among the cobbles 20 yards east of and 7 feet lower than the main spring; and vapor, possibly from the same spring or fissure, issues from openings in the forest soil 15 yards shoreward. A third spring, with a temperature of 84° F. and a flow of half a gallon a minute, rises with slight bubbling in the muck of a small stream channel 50 yards west of the principal spring.

Conditions at the main spring, where the water appears to issue directly from a fissure in the schist, indicate that the thermal water rises along such seams in the rock, which dips 80° S. 20° W. The abnormal temperature of the water may be due solely to the depth from which it rises, but it seems probable that it is due, in part at least, to the presence of intrusive rocks, which form a wide zone east of the springs.[1] The schist from which the warm water issues is a common alteration phase of the Paleozoic or Mesozoic sediments near their contact with intrusive rocks throughout southeastern Alaska.

TENAKEE HOT SPRINGS.

Tenakee Hot Springs (88 on Pl. I), formerly known as Hooniah Hot Springs, form one of the best-known of the Alaskan spring resorts. In 1891 there was a small native village near the springs,[2] which were probably locally used to some extent much earlier.

For 20 years or more the place has been used as a bathing resort by whites, and within the last 10 years a considerable settlement has been built up here, with post office (established in 1903) and supply stores. (See Pl. IV, *B*.)

[1] Knopf, Adolph, op. cit., pl. 1.
[2] Pacific Coast Pilot, Alaska, pt. 1, p. 163, Washington, 1891.

Digitized by Google



FIGURE 4.—Sketch map of Tenakee Hot Springs and vicinity, Chichagof Island, southeastern Alaska.

Digitized by Google

The springs are on the north shore of Tenakee Inlet, approximately halfway by steamer route between Juneau and Sitka—about 100 miles from either place by the rather tortuous course necessitated by the several islands. The weekly steamer between Juneau and Sitka stops there regularly, going and returning.

In 1915 the Forest Service improved the property, which is within the Tongass National Forest, constructing a plank walk and moving the various cabins into alignment along it. These cabins have been erected by individuals, who pay a nominal lease to the Forest Service for the land and rent the cabins to visitors. The several springs and the improvements in 1915 are shown on the sketch map (fig. 4), prepared from a survey of the property by the Forest Service.

The principal spring (D, fig. 4) issues a few feet above high-tide level in a cemented bathing pool in a long building. The water rises through a fissure in the rock bottom of the pool, which continually overflows. This pool has been the only bathing place, certain hours being specified for its use by men and by women, but in 1915 it was the intention to provide better accommodations. The observed discharge was 7 gallons a minute and the temperature was 106° F. The temperature is said to vary with the stage of the tide from about 104° to 109° F., being warmest at high tide.

A noticeable increase both in temperature and discharge may be possible at high tide, owing to greater hydrostatic pressure and consequent shutting off of the escape of warm water through lower fissures in the rock; but the presence or absence of such a phenomenon was not satisfactorily determined by the writer.

Other springs issue in the vicinity of the principal spring. Spring F (fig. 4) was formerly piped down to the bathhouse for drinking, but it has been allowed to become choked with vegetation since a nearer spring, E, has been opened and the water conducted to the board walk as a drinking supply. Its warm temperature and distinctly sulphureted taste render it unpalatable to many persons, however. A cool sulphur spring, A, which has been surrounded by a cylindrical concrete wall 6 feet high and thus forced to overflow above the reach of the tide, is to some people a less unpleasant drinking water, though it tastes more strongly of hydrogen sulphide. Spring H issues only a short distance above low-tide limit and hence is covered by salt water most of the time. Its flow and temperature are, however, nearly the same as those of the principal spring. In 1915 a wooden spout a foot high had been securely placed over the vent, which gave off considerable gas as well as water. This gas repeatedly extinguished a flame and was probably carbon dioxide. Smaller springs, G, I, and J, in the vicinity, also actively bubbled, presumably with the same gas. Several other minor springs are said to be exposed at extreme low tide.

Digitized by Google

Analyses of water from the principal spring and from the cool sulphur spring are tabulated on page 40. The two waters are of the sodium sulphate type and the proportions of the several substances are nearly the same in each, though the cool water is only about one-half as concentrated as the hot water. The presence of borax in each water is worthy of note, especially as no source of borate is evident in the vicinity.

The rock formation in the vicinity of the springs appears to consist of dark gneiss, intruded by light-gray granite, both of which are phases of an intrusive crystalline area in Paleozoic sediments. Small amounts of schist are also present near the springs, apparently in the contact zone between the old sediments and the crystalline rocks.[1] The principal spring rises from a fissure in the gneiss. The other springs possibly also rise along fissures, either in the gneiss or in the granite, but the bedrock surface near them is covered by a layer of gravel, cemented by the deposition of lime from the spring water.

As was pointed out to the writer by Ed. Snyder, merchant and postmaster at Tenakee, springs C, D, E, and F lie nearly in a line that trends northeastward, and possibly they issue along the same fissure. The crevice in the bathing pool at D also trends northeastward.

The abnormal temperatures of the springs may be due to local crushing, caused by the intrusion of lighter-colored granitic material into the more gneissic rock, or it may, perhaps, be due merely to the rise of the water from a considerable depth along the zone of fracturing, though not necessarily of appreciable faulting, at the contact of the crystalline and sedimentary rocks.

HOT SPRINGS NEAR HEAD OF TENAKEE INLET.

About 4 miles above the mouth of a large creek that enters the head of Tenakee Inlet (84), scalding water issues at several points at the right-hand edge of the stream canyon. The hottest water rises with a temperature of 179° F. in a shallow algae-lined pool about 50 feet long and 3 to 8 feet wide, on the border of a gravel flat at the base of a steep forested slope. When visited in July, 1915, the discharge from this pool, together with that from an adjacent minor pool, was only about 4 gallons a minute, and it sank into the gravel after flowing only a few yards northeastward parallel with the base of the canyon side. Near the edge of the creek, however, 75 yards distant along a well-defined channel from the main pool, hot water of a considerably lower temperature issued at several

[1] Knopf, Adolph, op. cit., pl. 1.

Digitized by Google

small vents. Minor warm pools without surface discharge were also noted along the high-water margin of the gravelly stream channel. The positions of the several springs and pools with respect to each other and the canyon sides are shown in figure 5.



FIGURE 5.—Sketch map of hot springs and vicinity, near head of Tenakee Inlet, Chichagof Island, southeastern Alaska.

Although the positions of the minor hot springs suggest that their water may come from the principal spring, the three northernmost springs issue directly from seams in a low cliff at the creek edge. The conditions indicated that all six northern springs issue from a small fissure that extends about S. 70° W. The water of these cooler springs is without noticeable odor and taste, but that of the hottest pool, which is apparently supplied from another fissure, is distinctly sulphureted and also tastes noticeably mineralized. A thin white coating that probably consists chiefly of lime carbonate is deposited on pebbles in its overflow channel. An analysis of the water of the hottest spring, given in the following table (analysis 5), shows that it is a sodium sulphate water of fairly high mineral content, similar to the water of Tenakee Hot Springs. Like the water of other hot springs of Alaska it has an abnormally high content of silica.

Digitized by Google

Mineral analyses of waters from hot springs in southeastern Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2	3	4	5
Silica (SiO_2)	40	96	94	57	119
Iron (Fe)	1.4	3.1	1.0	.5	2.1
Aluminum (Al)	5.3	.....	2.4	Trace.	4.6
Calcium (Ca)	37	8.5	35	11	21
Magnesium (Mg)	11	Trace.	2.8	.6	2.3
Sodium (Na)	206	59	201	111	137
Potassium (K)	3.8		4.0	2.8	4.1
Carbonate radicle (CO_3)	.0	25	24	28	7.2
Bicarbonate radicle (HCO_3)	35	18	26	2.4	48
Sulphate radicle (SO_4)	329	35	302	166	226
Chloride radicle (Cl)	133	42	99	31	33
Nitrate radicle (NO_3)	1.0	.3	.0	1.0	.0
Borate radicle (B_4O_7)	Present.	.....	Present.	Present.	Present.
Total dissolved solids at 180° C.	786	276	787	431	592
Temperature (°F.)	101	111	106	56	179
Chemical character	$Na-SO_4$	Na-Cl	$Na-SO_4$	$Na-SO_4$	$Na-SO_4$

1. Hot springs on North Arm of Peril Strait; northernmost spring of main group. Has no noticeable taste or odor. Sample collected June 29, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
2. Hooniah Warm Springs; principal spring. Has faint taste and odor of hydrogen sulphide. Sample collected June 28, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.
3. Tenakee Hot Springs; principal spring. Sample collected June 23, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
4. Cool mineral spring at Tenakee Hot Springs. Has distinct odor and taste of hydrogen sulphide. Sample collected June 23, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
5. Hot springs near head of Tenakee Inlet; spring at pool. Has noticeable odor and taste of hydrogen sulphide, and deposits small amounts of calcium carbonate. Sample collected July 1, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

The rock exposed in low cliffs on each side of the creek, near the springs, is dioritic, much altered on the surface, and is traversed by white veinlets of material that has been examined chemically by W. T. Schaller, of the United States Geological Survey, and found to consist chiefly of a zeolite whose optical properties indicate that it is probably heulandite. This mineral may have been derived from the decomposition of plagioclase feldspars in the dioritic rock. The rock appears to form a ledge trending N. 60° E. through the more prevalent granitic material. Its presence in the larger area of granite suggests that its intrusion is the main cause for the issuance of the hot water. The relation of the springs to the two varieties of rock is not clearly evident, however, and the geologic structure to which the issuance of hot water is due may be the larger one of a contact zone between the intrusive crystalline rocks and Paleozoic sediments.[1] Along the creek channel, near the springs, there are fragments of white crystalline limestone, which become more common and more angular toward the head of the creek, indicating that the limestone (a member of the Paleozoic sedimentary series) crops out not far upstream.

At the time of the writer's visit no trail had been cut to the springs through the dense forest and undergrowth, and their loca-

[1] Knopf, Adolph, op. cit., pl. 1.

Digitized by Google

tion was known to only a few whites and Indians. It would, however, be comparatively easy to clear a road to them along the creek from the head of the inlet and to pipe the water a few hundred yards downstream to a suitable place for a bathhouse and other buildings.

OTHER HOT SPRINGS NEAR TENAKEE INLET.

Several hot springs in addition to those at Tenakee and near the head of Tenakee Inlet were reported to the writer, but no attempt to visit them was made, as a guide could not be found and search for such small springs in the dense undergrowth was not practicable.

Hot springs (85) near Nika Bay, a small bay on the west side of Port Frederick, southwest of the village of Hooniah, and hot springs (82) on a creek near the head of Mud Bay, northwest of the same village, were reported by George Peterson, of the Forest Service.

Hot springs (83) on the north shore of Lisianski Inlet, west of Hooniah, were reported by W. G. Weigle, of the Forest Service, but only their approximate location was learned.

Tom Starr, of Tenakee, the native guide who conducted the writer to the hot springs near the head of Tenakee Inlet, reported a warm spring (81) near Lituya Bay, on the coast of the mainland, about 80 miles northwest of Hooniah, but he had not personally visited this spring.

A "hot spring near Hooniah" reported to the Geological Survey may be one of the thermal springs already mentioned, but there are possibly several other springs of warm or hot water in the region. The northern part of Chichagof Island consists of a series of Paleozoic sediments, intruded by later crystalline rocks,[1] all more or less fractured; so that conditions favoring the presence of thermal springs probably exist at a number of places. The springs that are now known are all near tidewater, where they have been easily discovered. As the interior of the island is penetrated more and more other springs, now hidden in the dense undergrowth, will probably become known.

HOT SPRING ON TWELVEMILE CREEK.

A hot spring on Twelvemile Creek (51, Pl. I) near the head of Kiagna River, a tributary of upper Chitina River, was reported to F. H. Moffit, of the United States Geological Survey, by James Barkley, who has prospected extensively in the region. In 1906 or 1907 Mr. Barkley found a small stream of heated water beside the creek, but on revisiting the place about 1913 could find only a small

[1] Knopf, Adolph, op. cit., pl. 1.

Digitized by Google

area of warm mud at its site. During the intervening years the spring had apparently been either partly buried by slide material or had been destroyed by other changes in surface or underground conditions. The spring is in a region of altered sediments that are believed to be chiefly of Paleozoic age.[1]

SOUTHWESTERN ALASKA.

DISTRIBUTION.

Hot water doubtless issues in many localities on the Alaska Peninsula and its extension in the Aleutian Islands, especially in the vicinity of the numerous volcanoes, active or quiescent.

Russell[2] says of the region:

> The conspicuous and in fact the only well-characterized volcanic belt in Alaska begins in the east, at the head of Cooks Inlet, and extends westward throughout the Alaska Peninsula and Aleutian Islands. This belt of igneous activity is nearly 1,600 miles long, with a width in general of less than 40 miles. It is so narrow and well defined that two parallel lines drawn on a map of Alaska, 25 miles apart, may be made to include nearly every volcano in the belt that is known to have been active in historic times. This may, for convenience, be termed the Aleutian volcanic belt.
>
> The numerous volcanic vents that mark the course of this long narrow belt, the many earthquakes that have been felt at intervals since the discovery of Alaska in its vicinity, and many changes of level recorded by terraces, as well as by the observations of white men, all indicate that a fracture or perhaps a series of intersecting breaks in the earth's crust there exists, along which marked changes have taken place in recent times and are probably still in progress. The sea to the south of the Aleutian Islands is deep. The deepest soundings obtained previous to 1896 were in that region in what is known as the Tuscarora deep. North of the Aleutian Islands lies Bering Sea, for the most part shallow, which corresponds with the submerged continental border along the Atlantic coast of North America. The conditions are such as to favor the view that the Aleutian volcanic belt is not only a belt of fracture, but that differential movements of the rocks of a pronounced character on the two sides of the belt have occurred—that is, it is a belt of faulting.

The statement of Grewingk[3] that there is definite information of volcanic activity on 25 of the Aleutian Islands, on which 48 craters have been enumerated, with at least 4 more on the Alaska Peninsula and 2 on the shore of Cook Inlet, has been quoted by Russell[4] and others. Later observers have found a few volcanoes that were not known to Grewingk, and several of the localities indicated by him have been found to be of lavas but not volcanic within historic times.

---

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

[2] Russell, I. C., Volcanoes of North America, pp. 268–269, New York, 1897.

[3] Grewingk, C., Beitrag zur Kenntniss der orographischen und geognostischen Beschaffenheit der nordwest-Küste Amerikas mit den anliegenden Inseln: Russ. k. mineral. Gesell. Verh., 1848–49, p. 195, 1850.

[4] Op. cit., p. 270.

Digitized by Google

Mount Calder, at the north end of Prince of Wales Island, mentioned by him as being a volcano, is composed of limestone. There are, however, at present 33 volcanoes of actual or relatively recent activity recognized in Alaska, all being in its southern portion. These volcanoes have been indicated on Plate I (p. 12), by G. C. Martin, of the United States Geological Survey.

During recent years the most notable eruption has been that of Mount Katmai, June 6 to 8, 1912.[1]

Grewingk[2] specifically mentions hot springs in the following places, concerning only a few of which additional information is at hand: Hot springs (92) on Baranof Island (Sitka Hot Springs, see p. 28); hot springs (75) near Balboa (Portage or Parenosa) Bay; hot springs (74) on a little island at the entrance of Morzhovoi Bay, probably Amagat Island; hot springs (73), called by the Russians "Goratschuch Kljutschei," on the inlet of the same name;[3] hot springs (76) at Port Moller (see p. 45); hot springs (72) and hot marshes near Pogromni Volcano, on Unimak Island; hot springs (70) on a little island on the northwest side of Akun Island; hot springs (69) near the crater on Agutan Island; hot springs (68) near Makushin Volcano, on Unalaska Island;[4] hot springs on Umnak Island, both at the base of Vsevidof Volcano (64) and northeast from it (65);[5] hot springs (67) on Bogoslof Island (see p. 47); hot springs (63) and exhalations of gases on Kagamil Island; hot springs (62) at the base of the volcano on Chuginadak (Tanach-Angunach) Island; hot springs (61) and mud craters on Seguam Island; hot springs (58) and mud craters on Conical Volcano[6] on

[1] For detailed descriptions of this eruption see Dailey, I. M., Report of the eruption of Katmai Volcano: Am. Geog. Soc. Bull., vol. 44, No. 9, pp. 641–644, 1912. Clark, G. A., The Katmai eruption: Seismol. Soc. America Bull., vol. 2, No. 4, pp. 226–229, 1912. Martin, G. C., The recent eruption of Katmai Volcano in Alaska, an account of one of the most tremendous volcanic explosions known in history: Nat. Geog. Mag., vol. 24, No. 2, pp. 131–181, 1913.

[2] Op. cit., pp. 204–208.

[3] These are probably the springs which Petrof (Tenth Census, vol. 8, p. 19, 1884) says are less than half a mile from the village of Protassof or Morshevoi [Morshovoi]. Of these springs he says: "There is a series of warm sulphur springs and ponds, which would afford the sickly natives partial or permanent relief could they only be induced to bathe therein; but, while there is not one man, woman, or child in the village free from cutaneous disease of some kind, not one of them can be induced to make the exertion necessary to try the efficacy of the waters."

[4] These are possibly the springs which Dall (Alaska and its resources, p. 472, 1870) mentions as being near Port Levashef or Captains Harbor and having a temperature of 94° F., though hot springs may formerly have issued nearer to the crater of Makushin. N. O. Lawton (Makushin sulphur deposits: Min. and Sci. Press, vol. 98, pp. 259–260, 1909) says there are only solfataras, exhaling hydrogen sulphide and sulphurous acid, within the crater of Makushin.

[5] Dall (Alaska and its resources, p. 472, 1870) states that the water in one of these springs rises 2 feet and falls again four times an hour. This water is boiling. It does not issue from a well-defined vent.

[6] Dall (Op. cit., p. 473) says that these craters are funnel-shaped, about 2 feet in diameter at the top, and frequently full of mud in a state of ebullition, and that sulphurous odors and subterranean noises, like the escape of steam, are always noticeable.

Digitized by Google

Atka Island;[1] hot springs (59) near Kliuchef Volcano on Atka Island; hot springs (56) near White Volcano on Adak Island; hot springs (55) at the base of Kanaga Volcano on Kanaga Island. Grewingk also says (p. 160) that, according to Bragin, 20 versts westward from Amchitka Island there lies Sitignak, a small rocky island with fire-spitting peak and several hot springs.[2] This islet is not shown on more recent maps, however, and the report of its existence may have been erroneous.

Dall[3] mentions the following hot springs in addition to those listed by Grewingk: Hot springs (71) that issue between tide marks on a small island southeast of Akun Island; hot springs (66) near Inanudak Bay or Deep Bay, on Umnak Island, ranging in temperature from boiling to lukewarm, in some of which he says the Aleuts are accustomed to bathe; and hot springs (60) 5 miles from Korovin Bay, Atka Island. He also speaks of hot springs in a verdant valley between Korovin and Kliuchef volcanoes, on the same island, which are possibly the same as those mentioned by Grewingk near Kliuchef Volcano (59).

In addition to springs mentioned by Grewingk and by Dall, Petrof[4] reports that hot springs (57) emerge from the rocks in many places on Great Sitkin Island. He also states that there are hot springs on nearly every island of the Rat Island group, though smoking craters (very probably accompanied by hot springs) exist only on Semisopochnoi (54) and on Little Sitkin (53). He adds that the Little Sitkin crater is probably the westernmost active volcano in the Aleutian chain. Little Sitkin has not more recently been referred to as a volcano, however, and it is probable that its activity, if notable, is solfataric rather than truly volcanic.

Near the head of Stepovak Bay there is said to be an area known as "Kupreanof Volcano," where steam and other vapors rise through many fissures.[5] The true character of this area appears, however, not to be definitely known.

In the fall of 1916 Charles H. McNeil wrote to the United States Geological Survey stating that natives report a large hot spring on West Fork of Douglas River. This stream enters Cook Inlet between Cape Douglas and Kamishak Bay. The spring is probably about 25 miles west of Cape Douglas.

Analysis of water from only one of these springs on the Alaska Peninsula—the group on Akutan Island (69 on Pl. I)—is available.

[1] Petrof (Tenth Census, vol. 8, p. 93, 1884) says that at two or three places on Atka Island "the natives report mud craters throwing up liquid masses varying in color from red to green, blue, and a brilliant yellow."

[2] Dall (Alaska and its resources, p. 473, 1870) also mentions these hot springs.

[3] Idem, pp. 472–473.

[4] Petrof, Ivan, Alaska, its population, industries, and resources: Tenth Census U. S., vol. 8, p. 93, 1884.

[5] Underwood, J. J., Alaska, an empire in the making, p. 330, New York, 1913.

Digitized by Google

The following analysis of this spring, presented through the courtesy of the Bureau of Chemistry, shows that the water is of the sodium chloride type, rather high in concentration and content of silica and bicarbonate.

Mineral analysis of water from springs on Akutan Island, southwestern Alaska.[1]

[Parts per million except as otherwise designated.]

Silica (SiO_2)	84	Sulphate radicle (SO_4)	24
Iron (Fe)	.6	Chloride radicle (Cl)	157
Calcium (Ca)	9.1	Nitrate radicle (NO_3)	.4
Magnesium (Mg)	1.6	Lithium[2]	.25
Sodium (Na)	136		
Potassium (K)	12	Total solids[3]	535
Carbonate radicle (CO_3)	.0	Chemical character	Na–Cl
Bicarbonate radicle (HCO_3)	110		

PORT MOLLER HOT SPRINGS.

Port Moller Hot Springs (76 on Pl. I) were visited in 1908 by H. M. Eakin, of the Geological Survey, who has furnished the following notes concerning them.

The springs issue on the southwest side of the bay, near the shore and only a few feet above high-tide level, in one principal and several minor pools. The water is scalding, being probably at a temperature between 150° and 180° F. It has a "slick" alkaline taste but no noticeable odor, though there is much bubbling of carbon dioxide or other odorless gas. No algal growths are formed in the pools or run-off channels, and the water can be plainly seen rising from the gravelly or muck-covered bottoms of the pools. The absence of algal growths is an additional indication that the gas is carbon dioxide and not hydrogen sulphide. No mineral deposits were noticed, however, a fact that indicates the absence of notable amounts of carbonates in solution.

The hot water issues at the northern base of hills of recent volcanic rock, practically at the contact of this material with limestone that underlies it and forms the lowland thence to the beach.[4] The issuance of the hot water is probably connected with the recent lava, though it may issue along a minor fault. A number of such breaks have been observed in a small coal field a few miles to the southwest. Knowledge of the materials in solution might furnish suggestive evidence as to whether the water rises through the limestone or is confined to the volcanic rocks in its underground course, but so far

[1] Sample received by Bureau of Chemistry, U. S. Department of Agriculture, Aug. 13, 1914. Analyzed by W. F. Baughman.

[2] Spectroscopic determination.

[3] By summation, with bicarbonate computed as carbonate.

[4] Atwood, W. W., Geology and mineral resources of parts of the Alaska Peninsula: U. S. Geol. Survey Bull. 467, pl. 8, 1911.

Digitized by Google

as is known to the writer, no analysis of the hot-spring water has been made.

There seems to have been a large native village near the springs at one time, for ruins of huts still remain, half buried by heaps of clam shells 6 to 8 feet thick. A wide tidal flat near the springs furnishes an abundant supply of these shellfish, and they probably afforded an easy means of livelihood until the settlement was perhaps attacked by disease or by more aggressive natives and was abandoned. When visited by Mr. Eakin the place was the site of a temporary camp of Eskimo hunters.

It is doubtful whether the bay has ever been much visited for the sake of the hot springs, for the Alaskan natives, especially those of the northern part of the country, seem to have made little use of hot springs until they were shown their possibilities for bathing by the whites.

HOT SPRINGS NEAR PORT HEIDEN.

Hot springs (77 on Pl. I) have been reported near the shore on or near the bay of Port Heiden, but no definite statement of their temperature or other characteristics is at hand. The settlements along the peninsula are chiefly native villages, seldom visited by steamer or launch, and little information of any kind concerning the neighborhood of Port Heiden is at hand.

The lower lands in the vicinity of Port Heiden are covered largely with Quaternary gravels and sands that overlie rocks, reported to be coal bearing, which may be of Cretaceous age.[1] The hot water possibly issues in the lower (Quaternary) lands from the underlying older deposits.

HOT SPRINGS ON SHORE OF BECHAROF LAKE.

On the southwest shore of Becharof Lake, near the base of Mount Peulik (Smoking Mountain), hot springs (78) have been reported to members of the Geological Survey, but no description of them is at hand. The issuance of hot water here is possibly connected directly with volcanic activity in the region, for, as is indicated by its name, Mount Peulik is a volcano in which activity has not entirely ceased. The rock formation near the springs, however, consists of sandstone, probably of Jurassic age, through which the lava of Mount Peulik has been erupted.[2]

[1] Atwood, W. W., Geology and mineral resources of parts of the Alaska Peninsula: U. S. Geol. Survey Bull. 467, pl. 6, 1911.

[2] Martin, G. C., The petroleum fields of the Pacific coast of Alaska: U. S. Geol. Survey Bull. 250, pl. 6, 1905. Also, Atwood, W. W., op. cit., pl. 6.

Digitized by Google

HOT SPRINGS NEAR KATMAI PASS.

The following brief description of hot springs near Katmai Pass (79) has been published:[1]

> The pass lies between two volcanoes, the one on the right having a cone scarcely modified by erosion, while that on the left is somewhat furrowed but carries no glaciers. Below the pass, on the Katmai side, streams of very hot water burst out of the ground in many places and, joining together, form a considerable rapid stream. This water contains much sulphureted hydrogen and makes copious precipitates of iron and sulphur, so that the earth through which it oozes is colored a brilliant yellowish red.

It is reported that during the eruption of Mount Katmai, in June, 1912, a crater was opened near these springs, and they were buried by volcanic material. It is probable, however, that hot water still issues at some point in the vicinity.

HOT SPRINGS ON BOGOSLOF ISLAND.

A. G. Cameron, who spent several months among the Aleutian Islands with the Fisheries Commission about 1914, told the writer that at that time hot water issued at several places (67 on Pl. I) on Bogoslof Island, a volcanic rock mass in the Aleutian group, 30 miles north of Umnak Island. No large vents were noted by Mr. Cameron, the water appearing to issue from numerous crevices in the rock around the lower part of the island.

Bogoslof Island is very interesting to the geologist. Its history up to 1899 is described in detail, so far as the available records give it, by Merriam,[2] who characterizes it as having been in recent years the seat of more violent volcanic activity and as having undergone greater changes in form than any other part of North America. According to the accounts and reports that Merriam has brought together the first land recorded was a great rock, seen in 1768 or 1769, which later became known as Ship Rock or Sail Rock. Early in May, 1796, amid earthquake shocks and the ejection of volcanic material (both noted by natives on Umnak Island) Old Bogoslof Island, about a quarter of a mile in diameter, arose near Ship Rock. The forces that produced the island also ejected great quantities of steam and sulphurous vapor, but volcanic action gradually subsided until in 1820 vapor issued only from the highest peak. A waterfall then issued from a fissure near the base of the island—a "bow-shaped spring," presumably of hot water, though its temperature appears not to have been observed. By 1832 the notable issuance of vapor seems to have ceased. The island then appears to

[1] Spurr, J. E., A reconnaissance in southwestern Alaska in 1898: U. S. Geol. Survey Twentieth Ann. Rept., pt. 7, p. 146, 1907.

[2] Merriam, C. H., Bogoslof, our newest volcano: Alaska, vol. 2, pp. 291–336, Harriman Alaska Expedition, New York, 1902.

Digitized by Google

have undergone rapid disintegration, until in 1873, when the next definite observations were made, it had been reduced considerably in height and shortened to about three-quarters of its original length.

In 1883, probably rather late in the year, New Bogoslof Island arose about two-thirds of a mile northwest of the older islet, though its advent was not accompanied by disturbances that were noticed on Umnak or the other neighboring inhabited islands. In May, 1884, members of the Revenue Service landed at the islet group and made some observations. According to measurements made by them New Bogoslof Island was about 500 feet high (100 feet higher than the older islet) and about twice as long, its greatest diameter at the base being about half a mile. A large fissure and many smaller crevices in New Bogoslof gave off great quantities of steam and sulphurous vapors. The sea water near the base of the island bubbled as if boiling, but the thermometer showed little difference between the surface and bottom temperatures. The water in the anchorage southwest of the island was also bubbling up vigorously, probably because of the escape of carbonic acid gas, which is a common accompaniment of volcanic disturbances.

During the next few years New Bogoslof Island rapidly disintegrated, until in 1891 it had decreased notably in height and Ship Rock, which had been a prominent crag beside it, had fallen. Old Bogoslof was cold, but on New Bogoslof great quantities of steam and other vapors still issued from thousands of crevices, around which needle-like crystals of sulphur were deposited. Most of the rock of this islet was hot, and pools of hot water were found along the beach. Four years later the activity of the vapor vents had greatly diminished, though they still steamed vigorously, and the islet had become flat-topped.

In 1896 there was no longer evidence of volcanic activity on New Bogoslof, but warm water is reported to have issued from crevices in its sides.

The Harriman Expedition (1899) did not land on the islands, but photographs that were taken by members of the expedition indicate that the steaming had almost if not entirely subsided.

In 1906, about the time of the San Francisco earthquake, there was renewed activity at Bogoslof, though this activity is believed to have been only coincident with and not related to the earthquake. Two new peaks, McCulloch and Metcalf, were uplifted between the older islets, but on September 1, 1907, McCulloch Peak was destroyed by an explosion, ashes from it falling at Unalaska, 60 miles away. In 1908 the position of this peak was marked by a lagoon and the remaining rock masses were united into a single island by strips of gravel. Old and New Bogoslof had long been cold, but Metcalf

Digitized by Google

Peak was hot, and steam and sulphur vapors issued from many crevices in its sides.[1]

During March and April, 1909, the island showed renewed activity, observers at sea having noted great clouds of vapor.[2]

On September 19, 1910, a new islet was shoved up from beneath the ocean. Several weeks later this islet was visited by officers of the Revenue Service, who found that it was an area of hot volcanic ash and baked mud, from which spouted up a column of scalding water.[3] Definite records of this or later periods of activity have not been found by the writer. During 1914, at the time of Mr. Cameron's trip in the region, the island appears to have been quiescent, and the hot water reported by him is probably a phase of the less active stages of the volcanic mass.

The rock of the several peaks is practically all volcanic, consisting of hornblende andesite, basalt, basaltic agglomerate, and pumice. Some of the rock contains much disseminated pyrite,[4] which is probably the source of at least a part of the sulphur and the sulphurous gases.

WARM SPRINGS ON ATTU ISLAND.

Attu Island (51), the westernmost of the Aleutian chain, is about 20 by 40 miles in extreme width and length. Upon it there are several small lakes, which Mr. Cameron reports to be warm enough in summer for comfortable bathing. Although he did not observe direct evidence of warm springs it seems probable that thermal water does issue, for there is said to be a small, mildly active volcano, or more probably an area of solfataras, on the island.[5]

---

[1] The following articles relate to the condition of Bogoslof Island about this time:
Jordan, D. S., and Clark, G. A., The Bogoslofs: Pop. Sci. Monthly, vol. 69, pp. 481–489, 1906.
Eakle, A. S., Recent volcanic eruptions in Bering Sea: Min. and Sci. Press, vol. 96, p. 353, 1908.
Smith, P. S., Notes on recent changes in the Bogoslof Islands: Science, vol. 27, p. 695, 1908.
Jaggar, T. A., jr., The evolution of Bogoslof Islands in Bering Sea: Science, vol. 28, p. 575, 1908.
Jaggar, T. A., jr., The evolution of Bogoslof Volcano: Am. Geog. Soc. Bull., vol. 40, pp. 385–400, 1908.

[2] Greeley, A. W., Handbook of Alaska, p. 171, New York, 1909.

[3] Underwood, J. J., Alaska, an empire in the making, pp. 334–335, New York, 1913.

[4] Jaggar, T. A., jr., The evolution of Bogoslof Islands in Bering Sea: Science, vol. 28, p. 575, 1908.

[5] Underwood, J. J., op. cit., p. 340.

86182°—WSP 418—17——4

Digitized by Google

YUKON BASIN.

DISTRIBUTION.

Hot springs are known at a number of places in Yukon basin. The principal springs occur in three fairly well defined areas, comprising, respectively, the region between Circle and Fairbanks, the Hot Springs-Eureka district, and the Tanana-Ruby region. Several scattered springs lie outside of these principal groups, however, to the north in the slopes of the Endicott Range, to the south toward Mount McKinley, and in the region of lower Yukon and Kuskokwim rivers.



FIGURE 6.—Map showing location of mineral springs, Circle district, Alaska.

The springs do not seem to be related to great structural features, but most of them appear to be associated with intrusive rocks. The geologic conditions in the vicinity of each spring, in so far as they were observed or have been reported, will be mentioned in the description of each locality.

Digitized by Google

CIRCLE HOT SPRINGS.

Circle Hot Springs (30) have been developed and used for a number of years both as a bathing resort and for vegetable growing. (See fig. 6.) They are southwest of the town of Circle, at the base



FIGURE 7.—Sketch map of Circle Hot Springs and improvements in 1915, Circle district, Alaska.

of mountains that form the southern border of the wide flat valley of Yukon River. In 1915 they were best reached by wagon road to Central House, 34 miles from Circle, and thence southward by trail 8½ miles. In summer the roads are soft, owing to the thawing of the marshy lowland, but at the time of the writer's visit an

Digitized by Google

One of the two principal springs is on the north bank, about 10 feet above the creek; the other is on the south bank, about 20 feet above the creek. Several smaller springs issue on the north bank and others possibly in the creek itself. The water appears to be not so hot as that of the Circle Hot Springs, though it is said that by digging in the springs hotter water is found. The water gives off considerable gas, having the characteristic odor of hydrogen sulphide, and tastes more strongly mineralized than that of the Circle Hot Springs.

The flow of the several springs is difficult to estimate, but the total flow is not large. It is sufficient, however, to keep open throughout the winter a large pool 10 feet deep, which is visited by moose, bears, and other animals.

The rock of the vicinity consists of massive intrusive granitic material.[1] These springs, therefore, like the Circle Springs, may be due to the intrusion of granite into the schistose country rock.

HOT SPRINGS NEAR FLAT CREEK.

C. H. McCartney, who has prospected in the region southeast of Circle, stated to the writer that there are probably springs of hot water (36 on Pl. I) on the slopes above Flat Creek, a tributary of Charley River, for during the winter Flat Creek remains open along part of its upper course, about which considerable vapor rises. No definite vents were observed by Mr. McCartney, however, nor did he note odors of hydrogen sulphide—a common accompaniment of hot springs.

The rock near the springs is probably an ancient schist, which occupies a considerable area near the headwaters of Flat Creek. though other ancient sediments, as well as granitic and other igneous rocks, are found in the neighborhood.[1] The heated water possibly rises along the contact zone between one of the intrusive igneous rock masses and the older sediments.

[1] Prindle, L. M., op. cit., pl. 2.

Digitized by Google

A. CHENA HOT SPRINGS, FAIRBANKS DISTRICT.



B. BAKER HOT SPRINGS, HOT SPRINGS DISTRICT.



C. LITTLE MELOZITNA HOT SPRINGS, TANANA REGION.

Digitized by Google

Digitized by Google

CHENA HOT SPRINGS.

Chena (locally pronounced shenáw) Hot Springs (29), near a tributary of Chena River, have for several years been improved as a resort, with cabins and bathhouse, and during the winter have been the objective of sleighing parties from Fairbanks. (See fig. 8.)



FIGURE 8.—Map showing location of mineral springs in Fairbanks district, Alaska.

The distance up the river valley and canyon is about 62 miles and is easily traversed, when the ground is snow covered, in runs of a few hours each between the two roadhouses on the way. In summer, however, the lowland trail becomes so miry as to be almost impassable, and the trip may be made by saddle horse as quickly and more easily by way of Fairbanks Creek and Olympia Creek, though the Olympia Creek trail is 20 miles longer.

The springs rise in a small flat (see Pl. V, *A*) on the south side of Monument Creek beside a small cold-water stream that empties into the creek half a mile below. The hot water formerly issued mainly in the stream channel, but the stream has been diverted by a ditch so as to make the hot springs more accessible. In the summer of 1915 the principal springs and the improvements were as indicated in figure 9. The log bathhouse contained a dressing room, a sweat room, and a bathroom containing five wooden clear-water tubs and a mud-bath tub. Hot water was supplied by springs b and c (fig. 9), and cold water was also piped in from the stream, for the spring water is too warm (126° F. at the tubs) to be endurable by many

Digitized by Google

people. The vapor constantly rising from the water causes the logs to decay rapidly and necessitates their renewal every three or four years.

Slight differences in the taste and odor of the water from the several springs may be noted but appear to indicate no difference in character, all being sulphureted in varying degrees but not otherwise notably mineralized to the taste.

Analyses of water from two springs of the group (see table on p. 62) indicate that there is very little difference in the character of the water from the different vents. Both are moderately mineral-



FIGURE 9.—Sketch map of Chena Hot Springs and improvements in 1915, Fairbanks district, Alaska.

ized waters of the sodium carbonate type. They contain very little calcium and magnesium but considerable sulphate and silica.

Some of the vents give off much gas, which a test with a flame indicates to be carbon dioxide. Algal growths, ranging in color from bright green and copper-colored in the hotter water to a dark green in the cooler portions, lined the run-off channels to their junctions with the cold-water stream. Patches of algae also persisted in the cold-water stream, the temperature of which was from 70° to 66° F. down to its junction with Monument Creek, whose water was 55° F. The creek water contained no noticeable algal growths. During the early part of the summer extensive deposits of native sulphur were reported to have been formed near several of the hot springs. A freshet a couple of weeks prior to the writer's

Digitized by Google

visit had removed these, but deposits were again forming at several places. The deposition of sulphur at these springs appears not to be dependent directly on the temperature, as it was noted at spring b (fig. 9) at a temperature of 149° F. and near spring e, where the water registered only 120° F. The sulphur is probably produced by the oxidation of hydrogen sulphide and other sulphides present in the water. The chemical reactions are not simple, however, and the change is not due to simple oxidation and release of the sulphur from combination.

The total flow of the hot springs, as determined by careful float measurements in the run-off channels, is about 220 gallons a minute. A nearly equal amount of warm water may seep into the cold-water stream along its channel and banks, however, for measurements of discharge just above the uppermost springs and a short distance below the junctions of the hot-water channels with the cold-water stream showed an accession of about 500 gallons a minute within this distance. A part of this increase doubtless comes from marshy lands south of the creek, but the greater portion is believed to rise as thermal water.

The springs are locally believed to have formerly issued farther south, at the edge of the valley. A warm seepage still issues 200 yards southeast of the present uppermost spring (h, fig. 9) in the rocks a few feet above the creek flat, and the valley border is peculiarly pitted by depressions a few feet in diameter and depth that are lined with angular stones as if the earth and softer rock had been removed from below and the talus stones had settled down. These pits have possibly been formed by the thawing action of the hot water, which has shifted its points of issuance from time to time.

The rock in the vicinity of the springs is all granitic so far as seen.[1] On the higher slopes to the southeast the granite is replaced by schist, into which the granite appears to be intrusive, as it is believed to be at Circle Hot Springs. Probably Chena Hot Springs, like Circle Hot Springs, are due to the rise of deep-seated thermal water along fissures in the intruded schist.

HOT SPRINGS NEAR TOLOVANA RIVER.

Near the summit of hills on the western side of the valley of Tolovana River (see fig. 10) issue hot springs (27), which are reported to taste slightly alkaline and to have a mildy sulphureted odor. There is considerable bubbling from the several small vents a few yards apart on the hillside, but the gas is probably in the

[1] The intrusive area of granite shown on the east side of West or North Fork of Chena River (see A geologic reconnaissance of the Fairbanks quadrangle, Alaska: U. S. Geol. Survey Bull. 525, pl. 8, 1913) extends farther east than mapped, and includes the locality of the hot springs.

Digitized by Google

main carbon dioxide, not hydrogen sulphide, or a stronger odor the latter gas would be evident. It is said that the hand can hard be held in the water, indicating a temperature of 120° or 130° F.

According to studies of the United States Geological Surve the springs are in an area of intrusive granitic rock, close to contact with old slates and other altered materials.



FIGURE 10.—Map showing location of mineral springs in Hot Springs district, Alaska.

Although the springs are only 4 or 5 miles directly west of the head of steamer navigation at a log jam in Tolovana River, they are said to be best reached in summer by a prospectors' trail from a point 30 miles farther upstream along the very crooked river; for the lowland is marshy and dotted with lakes. The springs are not well marked and are not easily found except by following the trail.

An unconfirmed report was received of other hot springs which are said to lie about 20 miles in a direct line northeast of those just described, in the lowland along Tolovana River where it flows for a number of miles in a general westward course. This report may, however, relate to the springs west of the river.

[1] Prindle, L. M., A geologic reconnaissance of the Fairbanks quadrangle, Alaska: U. S. Geol. Survey Bull. 525, pl. 8, 1913.

Digitized by Google

HOT SPRING NEAR LITTLE MINOOK CREEK.

Frank Conway, a prospector in the Tolovana district, told the writer that while crossing the divide between Little Minook Creek and a tributary of Hess Creek he came upon a spring (25) that was fairly hot and yielded a stream of water several inches wide. Special attention was not paid to it at the time, and its precise location can not be stated, but it is probably one of a number of small thermal springs that will become known and receive local attention when the more inaccessible parts of the region have been better explored.

The spring is in a region where the rocks are mainly ancient conglomerate, sandstone, and other sediments, but in the neighborhood of the divide between Little Minook and Hess creeks there are small areas of intrusive granitic rock.[1] As other hot springs in the region are near the borders of similar areas of intrusive rocks it seems reasonable to suppose that the hot spring near Little Minook Creek also issues in the contact zone near one of the intrusive masses.

HUTLINANA HOT SPRING.

Hutlinana Hot Spring (24) issues at the edge of the creek of the same name, 8½ miles by trail east of Eureka post office, which is 23 miles by wagon road northeast of Hot Springs.

There appears to be only one spring, which issues from a fissure at the base of a cliff that terminates the steep canyon side down to the west edge of the creek. When visited, a bathing place was formed by a pool, rudely square, about 6 feet across and 1 foot deep, excavated in the partly disintegrated rock and covered by a tent. The water is clear, with no noticeable taste and only a faint odor of hydrogen sulphide, though there is a constant bubbling, probably of carbonic acid gas. A temperature of 114° F. was recorded—about as hot as is comfortable for bathing—and the discharge was measured as approximately 50 gallons a minute.

The analysis of the water (analysis 4 in table on p. 62) shows that it is a rather highly concentrated sodium carbonate water containing minor amounts of sulphate and chloride.

At the time of the writer's visit, in August, 1915, a cabin stood 75 yards below the spring on a small alluvial flat, where potatoes and other vegetables were maturing well. Two older, unoccupied cabins stood on the opposite side of the creek.

The spring has been used to some extent by the placer miners of the Eureka Creek district for bathing, but it is almost too far from the placers for this use, especially as the trip involves a descent of 1,000 feet from the divide between the two streams and the return climb up the steep trail.

[1] Prindle, L. M., op. cit.

Digitized by Google

The rock at the spring is quartzitic and has nearly vertical bedding or shearing planes that strike N. 25° E. It is a phase of the altered sediments, probably mainly of lower Cretaceous age, that cover a considerable area in the region.[1] Faulting has not been noted in the vicinity, but the presence of the spring indicates at least deep fracturing and fissuring that permit the escape of water of abnormally high temperature.

BAKER HOT SPRINGS.

Baker Hot Springs (23 on Pl. I) are near Tanana River, 103 miles by trail or 200 miles by the river below Fairbanks. They have long been known to the whites, as they are only 5 or 6 miles from Baker Creek, an early placer-gold district. In 1902 the place was homesteaded by J. M. Karshner, and for several years the springs were known by his name. In 1906 they were leased by F. G. Manley, who built here a large and well-appointed hotel, constructed cement bathing tanks, and developed the place as a resort, and for a time they were known as the Manley Hot Springs. Mr. Manley also established a dairy and started to raise vegetables and poultry on an extensive scale, using the hot water to heat a greenhouse and the poultry houses. The enterprise was not entirely successful, however, and the improvements were not kept in repair, and in April, 1913, the hotel was destroyed by fire. Since that date the springs have received little attention as a resort, though one cement pool, 10 by 12 feet, 4 feet deep, has been kept in repair. The water reaches this pool at a temperature of 114° F. and forms a much-appreciated bathing place.

Since the property was first occupied by Mr. Karshner the land has been cultivated and the hot water has been successfully used in growing potatoes, cabbages, and other vegetables. In 1910 about 150 tons of potatoes were shipped from the ranch to the Iditarod mining district, 700 or 800 miles downstream. In 1915 about 60 acres of land was under cultivation. About half of this area is kept permanently thawed by warm seepage water that does not issue as springs. The erosion of the slopes in this thawed area, as noted by A. H. Brooks, is like that of the land in a more temperate climate, probably because the ground is permanently thawed, and possibly also in late years because it is cleared and cultivated.

The positions of the springs and the improvements are shown in figure 11, prepared mainly from the Land Office survey of the Karshner homestead. Two principal springs (see Pl. V, *B*), each issuing in a small rock-walled basin, rise 50 yards apart, near a small creek. The observed temperatures were 136° F. for the eastern

[1] Eakin, H. M., A geologic reconnaissance of a part of the Rampart quadrangle, Alaska: U. S. Geol. Survey Bull. 535, pl. 4, 1913.

Digitized by Google

and 125° F. for the western spring, and the respective discharges were approximately 35 and 110 gallons a minute. The water has been used for irrigating a garden on adjacent land, and part of the



FIGURE 11.—Sketch map of Baker Hot Springs and improvements in 1915, Hot Springs district, Alaska. Based on Land Office survey of Karshner homestead.

flow from the eastern spring was formerly used in heating the poultry houses. Water from the western (larger) spring is piped to a hothouse and to the bathing pool at the hotel site. Warm water also issues in a small spring near the largest one and in a marshy area

Digitized by Google

at the head of a small creek between the main springs and the hot site.

The water has no noticeable odor or taste. There is a sma amount of bubbling, probably of carbon dioxide, and thin coating of a white brittle substance, probably lime carbonate, are deposite on stones along the run-off channels. The water is said to eat u iron vessels rapidly. The original iron pipe from the springs wa so much corroded that it was taken out and replaced by galvanize pipe. This corrosion is probably due to the rather high proportio of chloride in the water, which is shown in the analysis of wate from the largest spring (analysis 5 in table below). The analysi shows, however, that the water carries only a moderate amount o mineral matter in solution, other constituents being present in mino amounts relative to sodium and chloride.

Hard rock is not well exposed near the springs, the material bein a variety of granitic rock containing quartz, feldspar, and mica technically classed as monzonite.[1]

The cause for the hot water can not be definitely stated, but pre sumably the rock is faulted or fractured and deep-seated therma water reaches the surface along the resultant fissures.

Mineral analyses of waters from hot springs in the Yukon River basin, Alaska

[Parts per million except as otherwise designated.]

Constituents.	1	2	3 [a]	4	5
Silica (SiO_2)	82	77	72	44	59
Iron (Fe)	1.3	[b] 1.2	.....	.09	[b] .9
Aluminum (Al)	3.7		.....		
Calcium (Ca)	29	2.3	2.9	22	9.1
Magnesium (Mg)	2.1	1.2	.2	6.0	.9
Sodium (Na)	248	[c] 94	107	208	121
Potassium (K)	8.6		Trace.		8.2
Carbonate radicle (CO_3)	.0	.0	.....	.0	.0
Bicarbonate radicle (HCO_3)	173	118	116	494	86
Sulphate radicle (SO_4)	98	78	89	67	48
Chloride radicle (Cl)	252	26	35	38	120
Nitrate radicle (NO_3)	.0	.....	Trace.	.....	.....
Total dissolved solids at 180° C.	816	388	[d] 363	634	417
Temperature (°F.)	134	149	124	114	125
Chemical character	Na–Cl	$Na–CO_3$	$Na–CO_3$	$Na–CO_3$	Na–Cl

[a] Trace of lithium.
[b] $Fe_2O_3+Al_2O_3$.
[c] Calculated.
[d] By summation with bicarbonate computed as carbonate.

1. Circle Hot Springs; northernmost spring. Gives off carbon dioxide; deposits small amounts of sulphur, calcium carbonate, and alum. Rapidly corrodes iron vessels. Sample collected July 12, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
2. Chena Hot Springs; spring that supplies bathhouse. Sample collected Aug. 5, 1915, by Robert Chamberlain; analyzed by R. B. Dole and Alfred A. Chambers.
3. Chena Hot Springs; probably spring a of figure 9. Sample collected in 1912, by P. J. B. LeBlanc; analyzed by J. B. Reed, Bureau of Chemistry, U. S. Department of Agriculture.
4. Hutlinana Hot Spring. Gives off considerable gas, probably carbon dioxide; has no noticeable odor or taste. Sample collected Aug. 6, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.
5. Baker Hot Springs; western of the two principal springs. Has no noticeable odor or taste. Rapidly corrodes iron vessels. Sample collected Aug. 5, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.

[1] Eakin, H. M., op. cit., p. 28.

Digitized by Google

WARM SPRINGS WEST OF GLACIER.

J. D. Courtney, who for several years resided at Glacier, in the upper Kantishna River basin, southwest of Fairbanks, reports that warm springs (40) probably rise 6 or 8 miles west of Glacier. At this place there are many areas of a few acres, sunken 50 feet or more below the general level, which contain dead trees standing in water that remains unfrozen throughout the winter. These areas of open water are resorted to by ducks and other waterfowl during the autumn and by larger game during the winter.

The region has not been examined in detail by a geologist, but the surface materials consist chiefly of Quaternary deposits, and ancient gneiss is exposed in the higher lands to the south.[1] The sunken areas described by Mr. Courtney are probably depressions in the uneven surface of the glacial gravels and clays that cover parts of the region. Distinctly thermal water may issue from springs in some of these depressions, though it is possible that the water is cold but is prevented from freezing by local protection.

WARM SPRINGS NORTH OF GLACIER.

Mr. Courtney, who reported unfrozen ponds in the country west of Glacier, also told the writer that similar open ponds (39) are found about 20 miles to the north, between the site of Diamond camp and Toklat River. In this region the waters of both Toklat River and Moose River sink for stretches of a mile or two and reappear apparently warmed, for the streams remain unfrozen throughout the winter for short distances below these sunken stretches.

Ponds and streams that remain open throughout the year are reported at several other places in Alaska. Thermal waters may cause this phenomenon, or local conditions may be such as to protect the ordinary surface waters from freezing.

The surface in the region of these open waters is largely covered by porous glacial gravels,[1] which may prevent freezing in the same way that very porous gravels in some of the placer workings are kept unfrozen by circulating underground water.[2]

According to Dall[3] many springs along the coast near St. Michaels and some to the northeast, near the village of Ulukuk remain unfrozen all winter. He says that many of those near St. Michaels

[1] Brooks, A. H., The Mount McKinley region, Alaska: U. S. Geol. Survey Prof. Paper 70, pl. 9, 1911.

[2] Eakin, H. M., The Iditarod-Ruby region, Alaska: U. S. Geol. Survey Bull. 578, p. 17, 1914.

[3] Dall, W. H., Alaska and its resources, 1870, pp. 33 and 36, Boston, 1870.

Digitized by Google

have a temperature of 28° to 30° F. [sic], even when the air is several degrees below zero. He also notes that the water of those near Ulukuk, though not very warm, retained a temperature of 32° to 34° F. in extremely cold weather.

HOT SPRINGS ON RAY RIVER.

According to the statements of several men who have visited them, hot springs issue from gravel at the edge of Ray River, about 35 miles above its mouth (22 on Pl. I). They are reached by a difficult trail that leads through a narrow gorge to a more open canyon above.

In cold weather the position of the springs is indicated by much vapor, but the points of discharge are masked by the river gravel. The water is too warm for bathing, but it is cooled by running it into basins dug in the gravel and adding to it some river water. It has no strong taste but has a noticeable odor of hydrogen sulphide.

The warm water has been used by prospectors in the vicinity for raising lettuce, radishes, and other quick-growing vegetables, and it was reported, though not very credibly, that one prospector had hatched eggs by burying them in the warm, dry gravel close to the springs.

A description of the rock formation of the locality is not at hand, but reconnaissance studies in the region[1] and knowledge of the rocks observed at other hot springs in the interior indicate that the rock at the springs is probably part of a granitic mass that is intrusive in the older volcanic and sedimentary materials composing the country rock.

LITTLE MELOZITNA HOT SPRINGS.

Little Melozitna Hot Springs (Pl. V, *C*) are so known locally because they are on a tributary of Little Melozitna River, though they are about 2½ miles from that stream. The springs (21) are best reached by trail that leads northward from Hub roadhouse, which is on the north bank of Yukon River 30 miles below Tanana. The distance from Hub to the springs is about 27 miles, according to pacing traverse. (See fig. 12.)

The springs are on a small flat on the east side of Hot Springs Creek, a stream about 30 feet wide. Their location is indicated from

[1] Prindle, L. M., A geologic reconnaissance of the Fairbanks quadrangle, Alaska: U. S. Geol. Survey Bull. 525, pl. 8, 1913.

Eakin, H. M., A geologic reconnaissance of a part of the Rampart quadrangle, Alaska: U. S. Geol. Survey Bull. 535, pl. 4, 1913.

Digitized by Google

a distance by a group of trees that are notably taller than those of the surrounding slopes.

The hot water issues chiefly from one spring on the left bank of the creek, in a log-curbed bathing pool that measures 3 by 7 feet and is 2 feet deep. This spring is on the gravelly flat only 5 or 6 yards from the edge of the creek and is about 18 inches above its level when it is at medium stage.

Although they are called hot springs, the recorded temperature of the largest and warmest spring was only 99½° F. Its flow is about 60 gallons a minute. A small seep just north of the main spring registered 90° F., and three other small springs 30 to 55 yards upstream, at the edge of the creek, registered temperatures of 96°, 82°, and 82° F. The water tastes mildly of hydrogen sulphide and the odor of this gas is noticeable for 100 yards or more down the wind from the springs. Gases bubble up actively in the springs, possibly both hydrogen sulphide and carbon dioxide, and the usual green algal growth that accompanies thermal sulphur waters lines the run-off channels. An incomplete analysis of water from the principal spring indicates that it is moderately high in mineral content, containing about 350 parts per million of solids in solution. It is of the sodium carbonate type, though its content of chloride is relatively high. Silica forms nearly a quarter of the total solids. In such a water, which is of rather high temperature and contains considerable sodium, part of the silica may be present as soluble silicate (SiO_3).



FIGURE 12.—Sketch map showing location of Little Meloxitna Hot Springs, Tanana region, Alaska.

Digitized by Google

A small cabin was built near the principal spring in 1913 by two French trappers, but it has been occupied for only short times, as there has not been much game in the region in recent years.

The rock exposed in the steep slopes at the edge of the valley 50 yards west of the springs and also in a small cliff at the edge of the creek 300 yards to the south (upstream) is granitic. The granitic area, however, seems to be small and to be confined to the slopes southward to Hub roadhouse is mainly quartz schist, with which are associated ancient metamorphic rocks.[1] Along the crest of the ridges forming the limits of the basin of Hot Springs Creek there are prominent crags that probably are also of schist. One bare rocky patch several hundred feet in diameter, on top of a wide tundra-covered ridge on the trail 10 miles from the springs toward Hub, is dioritic, however, and is probably a small intrusive area in the country rock.

The presence of the small area of granitic rock at the springs strongly suggests that the rise of the warm water is due to the intrusion of this rock in the schist, and the consequent development of fissures or a zone of fracturing along which the thermal water rises from a considerable depth.

MELOZITNA HOT SPRINGS.

Melozitna Hot Springs (20 on Pl. I) are so known locally because they are on a tributary of Melozitna (or Big Melozi) River, though they are fully 10 miles from the main stream. The springs are best reached by trail that leads northward from Kokrines, a small trading point and post office on the north bank of Yukon River 100 miles below Tanana. The distance from Kokrines to the springs is about 16 miles (see fig. 13). The trail is easily traversed by dog team in winter, but in summer the thawed tundra makes heavy traveling for horse or man.

The hot water rises, practically all in one spring, in a shallow pool 6 feet in diameter on top of a cemented gravel mass that has been cut by Hot Springs Creek—a fair-sized river—into a remarkable bank (Pl. III, *B*, p. 20). The overflow from the pool cascades 17 feet over this bank to the creek at normal stage. Hot water also breaks out, apparently from the same spring, at points about 3 and 14 feet below the edge of the bluff.

The temperature of the water as it rises in the pool is 131° F. The overflow, as nearly as could be measured, is about 100 gallons a

[1] Eakin, H. M., A geologic reconnaissance of a part of the Rampart quadrangle, Alaska: U. S. Geol. Survey Bull. 535, pl. 3, 1913.

Digitized by Google

minute, and the discharges of the two streams from the face of the cliff, as measured with a bucket, are about 25 and 5 gallons a minute for the upper and lower, respectively, making a total visible discharge of about 130 gallons a minute, or 14½ miner's inches. The gas that rises in the pool extinguishes a flame, indicating that it is principally carbon dioxide. The water tastes mildly but distinctly of hydrogen sulphide, and a distinct odor of this gas is perceptible at a distance of several yards from the pool. Small amounts of native sulphur are deposited along the borders of the pool, probably by the oxidation of the sulphide gas and other sulphides present. The reactions that take place can not be expressed by simple chemical equations, however. A thin white coating, probably of lime carbonate, is also formed on some of the pebbles along the run-off channels and gives good indication of the source of the lime carbonate that has cemented the gravel bluff.



FIGURE 13.—Sketch map showing location of Meloxitna Hot Springs, Ruby region, Alaska.

An analysis of the water (analysis 1 on p. 74) shows that it is moderately mineralized and of the sodium chloride type, though sulphate is also an important constituent.

In August, 1915, the water in the pool had a clear dark hue similar to that of "black sulphur" waters. This appears, however, to have been due to a thin, slimy, dark-brown layer, presumably an algal growth, on the stones in the bottom of the pool and not to the presence of notable amounts of sulphides in the water. The margins of the pool and of the discharge channels were lined with pale salmon-pink algae, which in only a few spots showed the more usual greenish hues.

In December, 1911, a two-room cabin and a dog house were built on the gravel bank near the springs. Two small log bathhouses, apparently of somewhat earlier construction, on either side of the

Digitized by Google

spring, have furnished bathing facilities by means of wooden tubs and sweat chambers. The springs are visited for several days at a time during the winter, both by parties of whites and of natives, but in summer the difficult trail causes them to be used only rarely.

The country rock in the vicinity of the springs, so far as observed, is of granite or similar crystalline rocks. In the beds of two creeks one-quarter and three-quarters of a mile south of the springs water-worn pebbles of white crystalline limestone were noted. This material probably comes from the steep mountains 2 or 3 miles eastward, which appear to consist of bedded sedimentary rocks, probably of Paleozoic age.[1] Somewhere in its underground course the hot-spring water probably traverses limestone and absorbs from it calcium, carbonates, and carbon dioxide gas. The cause for the abnormal temperature of the water is not evident; it may be due either to faulting or to the intrusion of granite into the sedimentary rocks, either of which would produce a high temperature gradient and furnish fissures for the upward escape of deep-seated water.

The springs evidently issued at their present location and formed the cemented gravel knoll or bank at a time when the creek channel was somewhat farther away. The stream has, however, apparently within comparatively recent years, attacked the cemented bank, and at present is undercutting it. Within a few decades the present pool may therefore be destroyed and the hot water allowed to issue at the river level.

HORNER HOT SPRINGS.

Horner Hot Springs (19 on Pl. I), although only three-quarters of a mile from Yukon River, appear to have been unknown to the whites until about 1913, when they were shown by an Indian to F. G. Horner, who has built a cabin and planted a small garden near them.

The springs issue at several points along a small creek that enters Yukon River 5 miles below Kokrines, all but one of the springs noted being on the right (west) side of the creek.

The principal spring issues from a granitic cliff 100 feet from and 40 feet above the creek. Part of the discharge, which is about 25 gallons a minute, at a temperature of 117° F., is piped to a wooden bath tub in the cabin immediately below. (See Pl. VII, *C*.) In 1915 the remainder of the discharge had not yet been utilized, but a narrow alluvial strip along the creek was available for use as an irrigated garden. The water has a faint taste and odor of hydrogen sulphide but is not otherwise noticeably mineralized. Pale salmon-colored to green algal growths, common in thermal sulphur waters, line the run-off channel.

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

Digitized by Google

An analysis (tabulated on p. 74) shows that the water is of moderate mineralization and of the sodium chloride type, though carbonate and sulphate constitute large portions of the total of acid radicles.

The other springs, of which seven were noted, issue at intervals from about 175 to 350 yards upstream from the principal spring and at heights of 2 to 20 feet above the creek. Like the principal spring they come from a fractured and partly disintegrated granitic rock, and the water is aparently under some pressure, as it issues with an upward current from each vent. These minor springs seem to be very similar to the main one. Their temperatures range from 86° to 120° F., and their discharges are from about one-quarter of a gallon to 8 gallons a minute, the total flow of the seven springs being about 20 gallons a minute, or less than the flow of the principal spring alone. The usual algal growth is seen at each spring, and it varies in color with the temperature of the water.

The geology of the region has not been studied in detail and the rock structure has not been worked out. The granitic rock from which the springs issue is fractured, however, so the heated water may rise along a fissure in a zone of faulting that is possibly followed in part by the stream channel. This fissure would provide a means of escape upward for deep-seated hot water. The area covered by the granitic material is believed to be only a few square miles at most, and it probably represents a mass intruded into the old sedimentary rocks that cover the greater part of the region.[1]

WARM SPRINGS ON ALATNA RIVER.

C. E. Giffin, of the Geological Survey, reports that the stream water along a considerable stretch of the upper Alatna River (4 on Pl. I) is too warm to be pleasant for drinking, a fact which indicates that a large quantity of warm water enters the river in that part of its course, but no definite springs were observed during the reconnaissance of the region.

The rocks along Alatna River are mainly of Paleozoic age and are chiefly limestones and metamorphic schists.[2] The warm water possibly issues at a number of places from fractured zones in these rocks, but geologic studies in the vicinity have shown neither extensive faulting nor the intrusion of granitic materials into the old sediments near the river, though there is an intrusive granitic mass, several square miles in area, on the higher slopes west of the river.

[1] Brooks, A. H., op. cit.

[2] Smith, P. S., The Noatak-Kobuk region, Alaska: U. S. Geol. Survey Bull. 536, pl. 2, 1913.

Digitized by Google

WARM SPRING NEAR REED RIVER.

In 1886 the Kobuk River basin was penetrated by an exploring expedition under the direction of Lieut. G. M. Stoney, of the United States Navy. Reed River, a small tributary of the upper Kobuk, was examined and a warm spring (3) near its headwaters visited by Ensign M. L. Reed, after whom the stream was named by Stoney. Of this spring Stoney says in his report:[1]

> There was but one hot spring there, a pool 20 feet in circumference and 2 feet deep, full of water of blood-warm temperature that wells up quietly from the bottom without bubbles or disturbances of any kind and fills the pool with a clear, tasteless, odorless water; the overflow runs into and fills smaller pools lying lower down the mountain side. The bottoms of all the pools are covered with green moss, on which is a limelike deposit, and the ground and rocks about the pools are similarly coated. About the edges of the main spring were thousands of small snails. The atmosphere is not affected in temperature, nor are the rocks and ground about. The natives say the temperature of the spring varies; that sometimes it is so hot they can cook meat in it.

The mention of snails is a feature that was not observed at any hot spring by the writer. The statement of the natives that the spring varies in temperature is another unusual feature of this spring, if it is true. Such springs are almost universally very constant in both temperature and flow, however, and the statement of the natives should be verified instrumentally before being accepted.

The spring probably issues from the ancient metamorphic schists that form the country rock of the region.[2] Intrusive granitic material is present 20 or 30 miles to the east, however, and other intrusive masses may exist in the vicinity of the spring.

HOT SPRINGS NEAR SELAWIK RIVER.

There is said to be a group of hot springs (2 on Pl. I) near the headwaters of Selawik River, but no definite information concerning them is at hand. They probably issue from Mesozoic or older sedimentary rocks, as these ancient sediments (overlain by Quaternary gravels) cover large areas in the region.[2] Whether the rise of the heated water is due more probably to faulting or to the intrusion of granitic or other crystalline rocks into these sediments can not be stated.

HOT SPRINGS ON A TRIBUTARY OF INNOKO RIVER.

In the summer of 1915 a prospector told C. E. Giffin, of the United States Geological Survey, that he had found hot springs (18 on Pl. I) on a tributary of the upper Innoko River. He stated that the flow of water was considerable and that it was decidedly hot, but gave no details concerning other features of the springs.

---

[1] Stoney, Lieut. G. M., Naval explorations in Alaska, p. 47, Annapolis, 1900.
[2] Smith, P. S., op. cit., pl. 2.

Digitized by Google

The rocks of the region consist chiefly of Mesozoic sandstones and other sediments, into which at many places igneous rocks are intruded.[1] From the conditions noted at other springs in Alaska it seems probable that those in the upper Innoko Basin are directly related to an igneous intrusion.

WARM SPRINGS NEAR IDITAROD.

A. G. Maddren, of the Survey, reports that springs (38 on Pl. I) near the north bank of Otter Creek, about a mile above Discovery, or 10 miles southeast of Iditarod, stay open all winter. The temperature of the water was not observed but is presumably several degrees above normal. The water issues near the contact of granite and slate,[1] where fissures or seams extending to considerable depths very probably furnish means of escape for deeper thermal waters. No noticeable deposit is formed by the springs, but the rock is considerably stained as if by iron.

HOT SPRING NEAR WHITEFISH LAKE.

The following information concerning a hot spring (47 on Pl. I) near Whitefish Lake, which lies near Tulusak River, a tributary to the lower Kuskokwim, is furnished by A. G. Maddren, of the United States Geological Survey.

On the headwaters of a tributary of Ophir Creek, which flows into Whitefish Lake, a hot spring is used for bathing by prospectors and by Lapp reindeer herders.

The water bubbles up with considerable force through a heavy mantle of moss among willows 1½ or 2 miles above the limit of timber, forming a stream 2 to 3 feet wide and a foot deep. The spring is about 750 feet above Whitefish Lake, which is believed to be about 250 feet above sea level. Its water is clear and of nearly scalding temperature. There is possibly a slight odor of hydrogen sulphide, but no algal growth was apparent when the place was visited by Mr. Maddren. A couple of tents erected over the run-off stream 200 to 300 yards below the spring have formed bathing places at points where the water is of an endurable temperature.

The water issues in a small area of granite that is intrusive in a region of volcanic tuffs of Carboniferous age.

Mr. Maddren also reports that about 13½ miles in a direct line east of south from the spring there is a siliceous sinter cone 150 feet high, at the east edge of Myrtle Creek, at the contact of an area of shales on the east with granite on the west. The cone is evidently an old hot-spring formation, but the creek has cut into its base so that any warm water that still issues probably seeps directly into the stream.

[1] Eakin, H. M., The Iditarod-Ruby region, Alaska: U. S. Geol. Survey Bull. 578, pl. 3, 1914.

Digitized by Google

HOT SPRINGS NEAR TULUKSAK RIVER.

Mr. Chase, storekeeper at Anvik, told the writer that his partner, F. H. Kruger, visited hot springs near Tuluksak River (46 on Pl. I), in the vicinity of Whitefish Lake, and found there much "green slime," doubtless algal growth, and noted a distinct sulphurous odor but did not especially observe the temperature and flow of the water.

From the specific mention of algal growths and of hydrogen sulphide the locality is believed to be different from that near Whitefish Lake which was visited by Mr. Maddren, but here, as at the spring examined by Mr. Maddren, the rock is probably granitic, consisting of an intrusive mass in the sedimentary rocks, probably of Cretaceous age.[1]

SEWARD PENINSULA.

DISTRIBUTION.

Hot springs are reported to occur at several points on Seward Peninsula. (See Pl. VI.) The geologic conditions at all of them are not known in detail; but examinations made of those whose rock structure has been determined indicate that all are directly related to areas of granitic rocks, intruded into older sedimentary or metamorphic materials. The springs do not seem to be connected either with extensive faulting or with volcanic activity.

KRUZGAMEPA HOT SPRINGS.

Kruzgamepa Hot Springs (Pl. VII, *A*) are 70 miles north of Nome, in the wide flat valley of Kruzgamepa River, one-third of a mile south of the stream. The property (13 on Pl. I) was homesteaded a number of years ago and has produced considerable amounts of potatoes, cabbages, turnips, and other vegetables, which have found ready sale in Nome, where they have been sent by the trains of the Seward Peninsula Railway, which passes within 8 miles of the springs, and, since the discontinuation of train service, by light cars pulled by dogs. In the summer of 1915 these dog cars furnished the easiest and quickest means of reaching the springs. In winter a shorter route by dog team is found through Goldengate Pass, about 10 miles west of the railroad.

Several years ago the property was kept up as a resort, and was often visited by parties from Nome and other mining centers of the region; but the roadhouse and saloon building was burned in 1908 and since that date the bathhouse has not been kept in repair. The locations of the several springs and the improvements on the property are shown in figure 14.

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

Digitized by Google



Digitized by Google

Digitized by Google

An area perhaps 100 yards wide and half a mile long, bordering a small creek that is at times a flood-water channel of Kruzgamepa River, appears to be permanently thawed by the hot water, and as this ground is loose and sandy, not dense and peaty, as are the moss-covered hillsides of the region, it has been especially adapted to growing vegetables.



FIGURE 14.—Sketch map of Kruzgamepa Hot Springs and improvements in 1915, Seward Peninsula, Alaska.

Hot water is visible only in small quantities, as it tends to seep off below the surface through the loose alluvial valley materials. In the fall of 1915 the total visible discharge of hot water at the springs was only about 8 gallons a minute. The hottest spring, which has a temperature of 156° F., issues in a small curbed pit in a greenhouse near the bathhouse. The water was carried in a box

Digitized by Google

flume through a sweat chamber to two bathing pools in a bathhouse, one pool for men and the other for women. A stand box in the flume afforded a place to dip out water for drinking and was known as the "medicine chest."

The water is clear, has only a slight odor of hydrogen sulphide, and tastes distinctly salty. It deposits small amounts of rust-colored iron oxide. A slight deposit of alum was seen at the principal spring. An analysis of the water (analysis 3, below) shows that its content of solids is high. It is a sodium chloride water that is practically a weak brine. Although the springs are not very far above tide limit, the ratio of sulphate to chloride in the spring water is so low that the high salinity seems not to be due to an admixture with sea water. In the spring water the ratio of sulphate to chloride is about 1:138, whereas in sea water it is about 1:7. The calcium-sodium ratios also are markedly different, being 1:2.9 in the spring water and about 1:30 in sea water.

Mineral analyses of waters from hot springs in the Yukon River basin and Seward Peninsula, Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2	3
Silica (SiO_2)	78	29	87
Iron (Fe)	.75	2.7	.7
Aluminum (Al)		.2	4.1
Calcium (Ca)	11	10	545
Magnesium (Mg)	2.8	3.0	7.4
Sodium (Na)	[a] 107	[a] 58	1,587
Potassium (K)			61
Carbonate radicle (CO_3)	31	32	.0
Bicarbonate radicle (HCO_3)	32	22	21
Sulphate radicle (SO_4)	61	45	25
Chloride radicle (Cl)	92	39	3,450
Nitrate radicle (NO_3)	Trace.	Trace.	.0
Borate radicle (B_4O_7)	Present.	.0	Present.
Total dissolved solids at 180° C.	442	292	5,955
Temperature (° F.)	131	117	156
Chemical character	Na-Cl	Na-Cl	Na-Cl

[a] Calculated.

1. Melozitna Hot Springs; principal spring. Has distinct odor and taste of hydrogen sulphide. Deposits small amounts of sulphur and calcium carbonate. Sample collected Aug. 12, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
2. Horner Hot Springs; principal spring. Has slight taste and odor of hydrogen sulphide. Sample collected Aug. 10, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
3. Kruzgamepa Hot Springs; spring in hot house. Has distinct salty taste, and slight taste and odor of hydrogen sulphide. Deposits small amounts of sodium chloride, calcium carbonate, and alum. Sample collected Sept. 2, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

The two bathing pools have been excavated in the alluvium beside the small creek, and some hot water probably rises in them. The temperature in these pools was only 110° F., however, a comfortable temperature for bathing. A bathhouse was first constructed 30 or 40 yards east of the present one, and small amounts of water, 100° F. in temperature, still issue at this earlier-used spring.

Digitized by Google

A. KRUZGAMEPA HOT SPRINGS, SEWARD PENINSULA.



B. CARBONATED SPRINGS NEAR BERING, SEWARD PENINSULA.



C. HORNER HOT SPRINGS, RUBY REGION.

Digitized by Google

Digitized by Google

The stream channel eastward, upstream from the original spring, contained in 1915 a long narrow strip of practically dead water, somewhat turbid as if from small amounts of carbonates in suspension, and covered in part by an iridescent film of iron oxide. From a point about 50 yards below the bathhouse to nearly 300 yards downstream the creek was also very sluggish and contained turbid water about 80° F. in temperature. This was partly covered by a film of iron oxide and supported a growth of green algae. At the lower end of the sluggish stretch a stream of about 60 gallons a minute flowed over a gravelly riffle to another sluggish stretch. The increase in flow of the creek is doubtless due to warm water seeping into it from the lowland along its course. A heavy stand of oats, well filled out and shoulder high, covered part of this permanently thawed and warmed lowland on September 2, 1915. Snow may cover this ground during the winter, but turnips and other root vegetables may be left in it without danger of freezing, and pulled only as needed.

Along the creek channel about 30 to 40 yards below the bathhouse there was, in 1915, a deposit of black ooze, which A. F. Rogers, of Stanford University, on microscopic examination, found was an opaque black ferrous sulphide,[1] containing several species of diatoms, as well as fine grains of quartz, biotite mica, muscovite mica, garnet, chlorite, tourmaline, and hornblende.

As the springs are in an alluvial river valley, the underlying rock formation is not visible. The nearest slopes on the south, 2 or 3 miles away, expose schists and gneisses, intruded by small areas of granitic rocks.[2] It would appear plausible, therefore, that beneath the river alluvium at the springs the bedrock may be gneiss, intruded by a granitic mass; and that, as is apparently true at several other Alaskan hot springs, the heated water rises along the fractured contact zone between the two kinds of rock.

ARCTIC HOT SPRINGS.

Arctic Hot Springs (12), on Hot Spring Creek, a tributary of Serpentine River, were not visited by the writer but have been described by Collier.[3]

Along Spring Creek for a distance of about half a mile there are hot sulphur springs. Two of these, the upper and lower ones, were visited by the writer. The upper spring is on the banks of the creek, probably above any except the

[1] Mr. Rogers stated in a letter to the writer that the ferrous sulphide is probably similar to the mineral hydrotriolite, described by Siderecks (in a Russian article abstracted by Doss in Neues Jahrb., 1902, Band 2, p. 397), from Hadishibey, Limau, Russia.

[2] Collier, A. J., and others, The gold placers of parts of Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 328, pl. 10, 1908.

[3] Collier, A. J., A reconnaissance of the northwestern portion of Seward Peninsula, Alaska: U. S. Geol. Survey Prof. Paper 2, pp. 55–56, 1902.

Digitized by Google

highest floods. The spring is in the center of a broad mound, 10 feet in diameter and perhaps 2 feet high, built up from material precipitated by the spring water. The temperature of the water is about 212° [probably only approximately]. The lower springs are below the high-water mark of the creek. The amount of water is not over 1 miner's inch. For some distance around the spring the ground is warm, making it an ideal place for wintering in that climate.

H. B. Barnett, of Teller, and Arthur Drewer, of Davidsons Landing, furnished the writer with the following additional information:

A distinct odor of hydrogen sulphide is present, but the water does not taste very noticeably mineralized. In addition to the mound described by Collier, small amounts of a hard, white deposit, probably lime carbonate, are also deposited on stones along the hot-water stream.

A few years ago prospectors built a cabin near the upper spring and a bathhouse over a bathing pool 10 to 12 feet in diameter. Cold water from the creek is admitted to lower the temperature sufficiently for bathing.

The springs issue at the west border of an intrusive granitic area about 5 miles in length and width, in a region of schists, slates, and other altered rocks.[1] As is believed to be true at other hot springs, the heated water of Arctic Hot Springs probably rises from a considerable depth along the fractured contact zone between the instrusive granite and the country rock.

WARM SPRINGS NEAR INMACHUK RIVER.

Warm springs near the upper course of Inmachuk River (15), in the northern portion of Seward Peninsula, have been visited by F. H. Moffit, of the United States Geological Survey. The springs remain unfrozen throughout the winter, but the temperature of the water is probably less than 100° F. It issues from crystalline limestone[2] and forms a shallow stream 3 or 4 feet wide. (See Pl. VIII, *B*.) No odor of hydrogen sulphide was noted, and the water did not appear to Mr. Moffit to be perceptibly mineralized.

The relation of these springs to the rock structure is not evident, but the water possibly is heated by contact with rocks that have been warmed by friction in a zone of minor faulting. The heat may be due in part to chemical reactions, but in the absence of an analysis of the water, the probability of such a source of heat can not be stated.

[1] Collier, A. J., op. cit., pl. 3. See also more detailed map in Moffit, Fred. H., The Fairhaven gold placers, Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 247, pl. 3, 1905.

[2] Moffit, F. H., The Fairhaven gold placers, Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 247, pl. 3, 1905.

Digitized by Google



A. CARBONATED SPRINGS, REVILLAGIGEDO ISLAND, NEAR NEW EDDYSTONE ROCK, SOUTHEASTERN ALASKA.

B. WARM SPRINGS NEAR INMACHUK RIVER, SEWARD PENINSULA.

Digitized by Google

Digitized by Google

HOT SPRINGS NEAR KWINIUK RIVER.

Hot springs whose waters are distinctly sulphureted are reported at two neighboring localities near Kwiniuk River (16 on Pl. I), which enters Norton Bay a few miles west of the larger and better-known Tubutulik River. So far as learned these springs are rather inaccessible, have seldom been visited by whites, and have not been developed or improved for bathing.

The rocks of the region have not been examined in detail but are believed to consist of Paleozoic sediments, including metamorphic schists and other altered materials.[1] As their character and structure are so little known, their probable relation to the springs can not be stated.

HOT SPRINGS NEAR SWEEPSTAKE CREEK.

Sweepstake Creek, a tributary of Koyuk River, enters the latter 30 or 40 miles by trail above the river's mouth. On a small tributary to the creek there are said to be hot springs (17 on Pl. I), which in winter make picturesque carvings in the ice of the creek. Like a number of other Alaskan springs, they have not yet become well known, and in 1915 no detailed description of them was obtainable.

The rocks of the locality are probably the same Paleozoic sediments and metamorphic schists[2] that are believed to be present at the springs to the southwest near Kwiniuk River.

CARBONATED SPRINGS.

SOUTHEASTERN ALASKA.

DISTRIBUTION.

Carbonated or "soda" springs issue at a few scattered points in southeastern Alaska. (See Pl. II.) All of them seem to be assignable to the local geology and not to any general structural features. In some places the production of carbon dioxide seems to be associated with the presence of lava of a fairly recent period of effusion, but sufficient information concerning all the localities is not at hand to warrant a general statement to this effect.

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906. Collier, A. J., and others, The gold placers of parts of Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 328, pl. 10, 1908. Smith, P. S., and Eakin, H. M., A geologic reconnaissance in southeastern Seward Peninsula and the Norton Bay–Nulato region: U. S. Geol. Survey Bull. 449, pl. 6, 1911.

[2] Brooks, A. H., op. cit., pl. 21. Smith, P. S., and Eakin, H. M., op. cit., pl. 6.

Digitized by Google

CARBONATED SPRINGS NEAR NEW EDDYSTONE ROCK.

Strongly carbonated or "soda" springs (109) issue on the eastern side of Revillagigedo Island, opposite New Eddystone Rock, a prominent islet crag in Behm Canal. The springs rise almost wholly between high and low tide limits on a rocky shore near the mouth of a large creek. One of the principal springs issues among the rocks 2 to 3 feet above low tide. In 1915 its discharge issued mainly through a piece of 1-inch pipe with elbow coupling that had been driven into the vent. (See Pl. VIII, *A*.) Owing to the large amount of carbon dioxide given off the water is discharged in spurts one-half to one second apart. The total discharge of this spring, as nearly as could be measured, was 4 gallons a minute, and the temperature was 50° F., while that of the adjacent salt water was 57° F. The water tastes strongly carbonated and also distinctly sulphureted, and the rocks over which it flows are deeply iron stained. An analysis of water from this spring (analysis 1 on p. 87) shows that it is a highly mineralized calcium carbonate water. The small amount of chloride (which forms only one-tenth of the total solid contents) indicates that there is very little, if any, admixture of sea water in the sample collected. The reported absence of sulphate shows that this radicle, if present at all, is in solution in only very small amount.

Water from this spring is said to have been bottled and sold locally for a short time a few years ago, as "Eddystone Water." The iron content would probably stain the bottles and injure its extensive sale.

A few yards offshore from the main spring large numbers of bubbles continually rise. Considerable carbonated water may also escape at this place, but it looked as if only gas was given off. Numerous minor gas vents are indicated just offshore, northward from the main spring, by groups and strings of bubbles, and probably much gas escapes also along the rocky shore above tide limit.

Near the mouth of the creek, 500 yards northward from the main spring, there is another group of bubbling springs, the principal one of which is 4 or 5 feet below high-tide level. The water issues directly from a rock fissure, in a deeply iron-stained basin 10 inches in diameter and 2 or 3 inches deep. The recorded temperature here was 49° F., and the discharge was about a quart a minute. This water is strongly carbonated, like that of the spring analyzed, but instead of a sulphureted taste it has a slightly bitter or puckery taste, probably due to iron. When visited, the location of this spring was pointed out by a signboard, and it probably was the favorite drinking spring for the former residents in a cabin near the southern group of springs. As at the southern group there are minor bubbling vents in

Digitized by Google

the tidewater near shore, and there is at least one other small spring, which rises in an iron-stained rock basin a few yards from the drinking spring.

The rock formation at the springs has been described in an earlier report of the Survey as "a banded schist complex cut by pegmatite dikes."[1] Lava of Quaternary (relatively recent) geologic age has been observed along the shore for about 5 miles southward from the springs. Small areas of lava are also exposed along the canal shore opposite the springs,[2] and other areas may be present on the densely forested slopes behind the springs. New Eddystone Rock is also of lava, possibly a volcanic neck which rises 234 feet high, according to the Coast Survey chart of the region.

It was reported that carbonated springs issue at New Eddystone Rock itself, but careful search around the islet at about half tide failed to disclose any evidence of such springs.

The extrusion of lava upward through the schist of the region may be the cause of the issuance of the carbon dioxide gas and carbonated water, for in other regions of volcanic rocks carbonated springs are fairly common. Much carbonic acid gas is given off from active volcanoes, and apparently the escape of the gas continues long after volcanic activity has ceased.

CARBONATED SPRINGS NEAR UNUK RIVER.

Carbonated springs near Unuk River (105) have been visited and described briefly by F. E. Wright.[1] Several small springs, having a total flow of about 1,000 gallons daily (nearly a gallon a minute), issue on the west side of the river about 2½ miles below the international boundary. The temperature of the water is 44° F. It gives off sufficient carbon dioxide to extinguish a candle, and some hydrogen sulphide is perceptible by its taste and odor. Small amounts of native sulphur are deposited, and much iron as a rusty coating of the oxide forms along the run-off channels. A travertine deposit of lime carbonate is also formed at each of the several small springs.

A small area of crystalline schist[2] is included in the greater mass of intrusive granite of the region near the locality of the springs, and the issuance of the mineralized water is perhaps due to this contact of different rock materials.

CARBONATED SPRINGS NEAR SODA BAY.

Carbonated springs (107) issue near Soda Bay, on the western side of Prince of Wales Island. These springs were visited in 1915 by

[1] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, p. 201, 1908.
[2] Idem, pl. 2.

Digitized by Google



FIGURE 15.—Sketch map of carbonated springs and vicinity near Soda Bay, Prince of Wales Island, southeastern Alaska.

Theodore Chapin, of the Geological Survey, who furnished the following description of them:

Carbonated springs are present on the west coast of Prince of Wales Island, at Soda Creek, a small stream that enters the head of Soda Bay, 7 miles east of the north end of Dall Island and about the same distance northwest of Hydaberg. A number of springs issue on each side of the creek and have built up deposits of tufa in places 30 feet or more in height. These deposits extend along the creek for one-quarter of a mile and back from the creek for several hundred feet. The tufa is dominantly yellow in color, but in some places it is a conspicuous brilliant red. Three forms of it were examined chemically by A. A. Chambers, of the United States Geological Survey, for gold, mercury, antimony, and arsenic, but no trace of any of these metals was found. The tufa is deposited in several forms. Stratified deposits line the banks of the creek, and mounds from a few inches to 8 feet high have been built up in the stream (see Pl. IX, *B*). As a rule a main vent is found at the top of each mound, and smaller streams of carbonated water issue from the base and sides. At the base of one yellow mound is a spring that deposits bright-red tufa. Springs issuing from below the surface of the creek were evidenced in a number of places by a vigorous bubbling. The springs are not large and generally do not flow as a stream but spread out in all directions, trickling down the sides of the mounds, which are continually building outward and upward. The positions of the

Digitized by Google

main springs are shown on the sketch map (fig. 15), and there are many other minor vents.

A partial analysis of water from one of the largest springs indicates that it is of the calcium carbonate type and rather highly mineralized, having about 2,600 parts per million of solid matter in solution.

The flow of the spring from which the water sample was taken was roughly approximated as about 5 gallons an hour by the length of time it took to fill a quart bottle. The water of the various springs ranges in temperature from 48° to 71° F. It has a pleasant taste and is free from disagreeable odor. It is used locally for drinking but has never been marketed.

The rocks in the immediate vicinity of the springs are chiefly slates, graywackes, and other old, more or less altered materials. Limestone outcrops not far from the springs, however, and may supply the relatively large amounts of calcium and of carbonate and carbon dioxide that the water contains. The rocks are probably all of Carboniferous age and are believed to form large portions of Prince of Wales Island.[1]



FIGURE 16.—Sketch map of carbonated springs and vicinity near Trocadero Bay, Prince of Wales Island, southeastern Alaska.

CARBONATED SPRINGS NEAR TROCADERO BAY.

Carbonated springs (106) near Trocadero Bay were visited by Theodore Chapin during his geologic studies in the region, and the following description of them has been prepared by him:

Carbonated springs issue about a mile above the mouth of an unnamed creek that flows into an arm of Trocadero Bay, locally known as Big Harbor. They are 4 or 5 miles north of the Soda Bay springs and 10 miles southeast of Craig. A large number of individual springs issue on the west side of the creek, where they have built up tufa deposits over a considerable area. (See fig. 16.) The individual vents are small, but in several places the combined flow of a

[1] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, pl. 1, 1908.

Digitized by Google

number of them form streams of appreciable flow. One of the largest springs bubbles up in a pool 2 or 3 feet in diameter, the overflow of which makes a trickling streamlet. Most of the water from the springs is soon lost in the porous tufa over which it flows.

The temperatures of the several springs range from 53° to 59° F. The water effervesces freely, has a sharp, pleasant taste, and is free from disagreeable odor.

An analysis (tabulated on p. 87) of water from one of the principal springs shows that it is of high mineral content and calcium carbonate in type. The various other substances are present in moderate amounts.

The spring deposits are composed of red and yellow tufa and are similar in appearance to those near Soda Bay, but the mounds are less well developed. The tufa deposits form two terraces, 12 and 15 feet in height, from which the springs issue. The general character of these terraces is shown in Plate IX, *C*.

The Trocadero springs are not well known, having been visited only by the local prospectors. They are a mile from the beach, in a region covered by a dense growth of underbrush through which no trail to them has been cut, though one could be easily opened.

The carbonated water issues from a series of graywackes and other altered sedimentary rocks of Carboniferous age[1] that are very probably of the same series as those near the Soda Bay springs. Limestone is, however, present in the vicinity and may be the source of the calcium and carbonate constituents of the water.

ZAREMBO SPRINGS.

Zarembo Springs (95) issue near the shore of St. Johns Harbor, on the northwest side of Zarembo Island, 23 miles west of Wrangell. The carbonated water rises, apparently at only one place, in the tidal flat of the south side of the harbor, about 45 yards from the shore.

Several years ago the water was bottled and marketed for a short time. In order to render it available for this purpose a small building and a concrete box, 5 feet square and 10 feet high, were constructed over the spring, thus keeping out the tide water and forming a pool of the spring water inside. A wharf that connected the spring house with a cabin on shore (Pl. IX, *A*) has been broken in two since the abandonment of the place.

At low tide the water escapes from beneath the concrete box in a stream of about one-half gallon a minute. Its observed temperature was 47° F., while the tide water registered 63° F.

[1] Wright, F. E., and Wright, C. W., op. cit., pl. 1.

Digitized by Google

A. ZAREMBO SPRINGS, ZAREMBO ISLAND, SOUTHEASTERN ALASKA.



B. CARBONATE MOUND FORMED BY SPRINGS NEAR SODA BAY, PRINCE OF WALES ISLAND, SOUTHEASTERN ALASKA.

C. CARBONATE TERRACES FORMED BY SPRINGS NEAR TROCADERO BAY, PRINCE OF WALES ISLAND, SOUTHEASTERN ALASKA.

Digitized by Google

Digitized by Google

Only a moderate amount of gas rises in the spring, but the water is effervescing with carbon dioxide. It deposits small amounts of iron and forms an iron film in the concrete box. The iron is not present in solution in sufficient amount to give the water a perceptible taste but is said to be enough to stain bottles and to injure the sale of the bottled water. Analyses (tabulated on p. 87) show that the water is of high mineral content consisting chiefly of calcium and carbonate. The proportion of sodium is fairly large, but the amount of sulphate is remarkably small for a water of such high concentration.

In the bay, about 700 yards N. 10° W. of the spring, large bubbles were noted continually rising to the surface. On testing with a flame they appeared to be of air, not of carbon dioxide, and probably were due to air trapped by the rising tide in the porous gravel of the harbor, under the same conditions as at the head of Fish Bay (p. 33). Smaller groups of bubbling vents, probably of the same character, were noted at a few places along the shore northwest of Zarembo Springs.

There is reported to be another minor carbonated spring in the forest half a mile south of Zarembo Springs, but its exact location was not learned.

Rock in place is not exposed on shore immediately opposite the springs, but 200 yards to the northwest there is a low point of greenstone, with schistose to coarsely crystalline phases, which continues for several miles to the west. East of the springs the rocks are slates, schists, and other altered materials.[1] The springs apparently issue in the contact zone between the two formations.

The greenstone lava is in places interbedded with slate. The relation of the carbonated springs to the lava is not clearly evident, but it seems plausible that the production of carbon dioxide is connected more or less closely with the lava flows.

CARBONATED SPRINGS ON SOUTH END OF ZAREMBO ISLAND.

George Peterson, of the Forest Service, reports that, in addition to Zarembo Springs, carbonated springs (96) are said to issue at the south end of the island near the shore. This latter group appears not to have been developed, however, nor visited, except by an occasional hunter or prospector. So far as reported their waters are cold and similar in taste to that of Zarembo Springs.

The rock formation in the vicinity of the springs is probably composed of the same series of greenstone lava flows that is present near Zarembo Springs.[1]

[1] Wright, F. E., and Wright, C. W., op. cit., pl. 8.

Digitized by Google

YUKON BASIN.

DISTRIBUTION.

Only four cool carbonated-spring localities in the Yukon basin were reported. Two of these are near together, near Yukon River in the region of Circle; the third is in the Nenana coal fields; and the fourth is near the lower course of the Yukon. The apparent scarcity of carbonated springs in the region is remarkable, but this scarcity may be partly due to lack of detailed knowledge of the region. The tendency of cool carbonated water to issue chiefly in areas of comparatively recent volcanic activity may in part explain their scarcity in the interior of Alaska, however, as areas of recent lava are not plentiful in the region.

CARBONATED SPRINGS NEAR WOODCHOPPER CREEK.

Fred Brentlinger, of Circle, reports small carbonated springs (33) of very good drinking water, about 45 miles southeastward from Circle, beside the trail up Woodchopper Creek. The principal spring is about half a mile below the mouth of Mineral Creek, or 3 miles from Yukon River. (See fig. 6.) Others issue at two or more points farther up Woodchopper Creek. None of these springs appear, up to 1915, to have been developed in any way, and they have been known only to prospectors in the region.

According to reconnaissance studies of the Survey[1] the springs are in a belt of conglomerates, sandstones, and shales of Eocene age, flanked on the north and the south by older, more-altered sediments. From the description obtained of the positions of the springs they may issue near the contact of the older and newer rocks, but this relation was not definitely learned.

CARBONATED SPRINGS ON COAL CREEK.

Fred Brentlinger, who is personally familiar with the springs on Woodchopper Creek, has also visited carbonated springs (34) on Coal Creek, about 12 miles by trail from the steamer landing at Woodchopper Creek. The trail follows up Woodchopper to Mineral Creek, up Mineral for a couple of miles, then across the divide, and up Coal Creek for about a mile. The water normally issues in considerable flow on the canyon side about 75 feet above the right bank of the stream, but in winter the spring glazes over and the water emerges from beneath the ice lower down, at times being forced by the ice to the left edge of the creek. The water is strongly carbonated and the channel is somewhat stained with iron.

The rock formation, as indicated by reconnaissance studies of the Survey,[1] probably consists of sedimentary rocks of Paleozoic age.

[1] Prindle, L. M., A geologic reconnaissance of the Circle quadrangle, Alaska: U. S. Geol. Survey Bull. 538, pl. 2, 1913.

Digitized by Google

though the springs may issue near the contact of these older rocks with the belt of conglomerates and other sediments of Eocene age on the north, in which the carbonated springs near Woodchopper Creek (p. 84) are believed to be situated. From the reconnaissance geologic work and the reported locations of the springs it seems that the springs on Coal Creek and the upper ones near Woodchopper Creek may issue along the same contact zone, trending northwest-southeast between the belt of Eocene and the wider areas of older rocks.

CARBONATED SPRING ON HOSEANNA CREEK.

In the summer of 1916 G. C. Martin visited a cool carbonated spring (42) in the Nenana coal fields and furnished the following notes concerning it:

The water issues near the south side of Hoseanna or Lignite Creek about 3 miles above its junction with Nenana River. According to surveys by the General Land Office the spring is in the NW. ¼ sec. 3, T. 12 S., R. 7 W., Fairbanks meridian, at an elevation of about 1,400 feet. A pool about 18 inches in diameter had been excavated at the spring and the water apparently was used to some extent for drinking. The overflow was perhaps 2 gallons a minute, and the channel for some distance downstream was iron stained. The temperature of the water was about that of other springs of the region, or about 50° F. There was no noticeable effervescence, but the water tasted distinctly carbonated. The spring issues on a gravel bench about 10 feet above the creek. The bedrock exposed near by consists of schists and altered volcanic materials, but the sedimentary rocks of the coal measures are also present in the vicinity, possibly being exposed by faulting.

There are several other small mineralized springs farther upstream, in the NE. ¼ sec. 3; and A. G. Maddren reports that about 6 miles farther upstream a small mineralized creek enters Hoseanna Creek in the SW. ¼ sec. 34, T. 11 S., R. 6 W.

CARBONATED SPRINGS NEAR MARSHALL.

About 7 miles east of Marshall (Fortuna Ledge post office), an important supply point on the tundra lowland on the north bank of Lower Yukon River and half a mile from the landing at the slough from which the trail to Willow Creek starts, there is a group of carbonated springs (45) in the lowland between Spruce and Wilson creeks. These springs were visited in 1916 by G. L. Harrington, of the United States Geological Survey, who furnishes the following notes:

Several mounds up to 4 or 5 feet in height have been built by the spring deposit, which consists chiefly of lime carbonate and iron

Digitized by Google

oxide. Two or three of the mounds no longer yield an appreciable flow, but the others supply streams of perhaps 1 to 2 gallons a minute of cool carbonated water. Several of the springs have slight flow, but the water issues in pools in which bubbles of gas, probably carbon dioxide, intermittently rise. Along the flat to the south, over which these springs drain, there is an area fully one-quarter of a mile long, having very little vegetation but covered in large part by a thin layer of lime carbonate.

In 1916 a saloon had been built over one of the principal springs and a pool 2 or 3 feet deep excavated, from which water was dipped for serving at the bar. An analysis of a sample from this spring (tabulated on p. 87) shows that the water is calcium carbonate in type with a high content of total solids. It is supersaturated with free carbon dioxide, and 1,340 parts per million of this gas was found on analysis three months after the sample was collected. The other constituents are present in relatively small amounts compared with the total content. Similar springs are also reported to issue at points about 6 and 10 miles farther east, in the lowland bordering Yukon River.

The nearest bedrock exposures are of greenstones on the north and Quaternary lavas on the south. The geology of the region has not been worked out in detail, but the presence of carbonated water is possibly connected with the intrusion of the volcanic rocks upward through Cretaceous sediments, which cover large areas in the region.[1]

SEWARD PENINSULA.

DISTRIBUTION.

Carbonated springs have not been reported from the southern portion of Seward Peninsula but have been from seven places in the northern half. (See Pl. VI.) Five of these spring localities are within a few miles of Teller and form one general group. The other two are about 35 miles northeast and 65 miles north of east of Teller. They seem, from their geographic positions, to be unrelated to the others, though they may be due to similar geologic conditions.

Satisfactory evidence in the matter was not obtained, but it seemed that those near Teller may be related, directly or indirectly, to the issuance of small masses of lava through the old limestones and other altered sediments of the region.

CARBONATED SPRINGS NEAR BERING.

A group of carbonated springs (6) issues about a mile northwest of Bering, on the east shore of Port Clarence. The water issues

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

Digitized by Google

mainly on the north edge of Willow Creek, a small stream, at the base of a steep hillside, about a half mile from the beach.

In a marshy area of about 40 by 75 feet the carbonated water rises at several points, with a total flow of perhaps 30 gallons a minute. Temperatures of 35° to 41° F. in the springs were noted on August 31, 1915, the creek water having a temperature of 49° F. The spring water is strongly but not effervescingly charged with carbon dioxide and is very palatable. Considerable flocculent iron oxide is deposited on sticks and roots in the marshy pools, and small amounts of white brittle material that is probably lime carbonate is deposited in a few places on the muck. The springs have often been visited by people from Teller, 5 miles to the north, who have taken away demijohns of the water for drinking. The springs are also occasionally visited by the natives, and sometimes they attract the reindeer herds of the region as a sort of salt lick.

An analysis (included in the following table) shows the water to be very highly mineralized, of the calcium carbonate type, though chloride is also present in large amount.

Mineral analyses of waters from carbonated springs in Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2	3	4[a]	5	6
Silica (SiO_2)	75	71	69	68	40	19
Iron (Fe)	1.3	5.2	2.5	67	6.2	2.2
Aluminum (Al)	3.7	7.0	4.1	2.3	4.0	14
Calcium (Ca)	273	484	353	375	366	477
Magnesium (Mg)	117	45	70	80	58	118
Sodium (Na)	110	63	208	218	32	186
Potassium (K)	9.6	7.0	10	11	14	7.0
Carbonate radicle (CO_3)	.0	.0	.0	.0	.0	.0
Bicarbonate radicle (HCO_3)	1,439	1,854	1,939	2,249	1,456	1,805
Sulphate radicle (SO_4)	.0	4.5	2.8	1.2	18	41
Chloride radicle (Cl)	132	13	31	28	3.1	380
Nitrate radicle (NO_3)	.0	Trace.	Trace.	Trace.	Trace.	.0
Borate radicle (B_4O_7)	.0	.0	Trace.	.0	.....	.0
Total dissolved solids at 180° C	1,362	1,582	1,653	[c]1,958	1,270	2,077
Temperature (° F.)	50	59	47	.....	[b]50	35
Chemical character	$Ca-CO_3$	$Ca-CO_3$	$Ca-CO_3$	$Ca-CO_3$	$Ca-CO_3$	$Ca-CO_3$

[a] Negative tests obtained for phosphate, arsenate, nitrite, bromine, and iodine. A trace of manganese, 0.3 part of lithium, 1.0 part of ammonium, and 2.0 parts of strontium reported.

[b] Approximate.

[c] By summation, with bicarbonate computed as carbonate.

1. Carbonated springs near New Eddystone Rock; spring issuing from pipe below high-tide level. (See Pl. VIII, *A*.) Supersaturated with carbon dioxide. Also has slight taste of hydrogen sulphide. Deposits iron. Sample collected June 16, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

2. Carbonated springs near Trocadero Bay; principal spring. Supersaturated with carbon dioxide. Sample collected Sept. 14, 1915, by Theodore Chapin; analyzed by S. C. Dinsmore.

3. Zarembo Springs; principal spring. Supersaturated with carbon dioxide; deposits iron. Sample collected June 18, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

4. Zarembo Springs; principal spring. Sample received June 1, 1911, by the Bureau of Chemistry, United States Department of Agriculture; analyzed by J. W. Sale.

5. Carbonated springs near Marshall; spring in saloon. Supersaturated with carbon dioxide; contained 1,340 parts of free CO_2 when tested in the laboratory 3 months after collection. Sample collected by G. L. Harrington Aug. 25, 1916; analyzed by R. B. Dole and Alfred A. Chambers.

6. Carbonated springs near Bering; principal spring. Supersaturated with carbon dioxide; deposits considerable calcium carbonate and iron. Sample collected Aug. 31, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

Digitized by Google

Besides the principal springs on the north side of the creek, considerable carbonated water probably escapes along the southern bank of the creek; for sloughlike pools along this side are cloudy, probably due to finely divided iron carbonate in suspension; and an iridescent film of iron oxide covers the quieter surfaces.

The rocks of the bluff north of the springs consist of laminated slate and limestone, assigned provisionally in reconnaissance studies of the Geological Survey to the Silurian and Ordovician geologic ages.[1] These old sedimentary rocks are intruded by small areas of volcanic rocks (greenstones) that in places form typical flat-topped, cone-shaped hills, which in the field strongly resemble volcanic cones. In the geologic mapping, the greenstones coincide fairly well with the tops of the hills. Two of these hills rise southeast of the carbonated springs. (See Pl. VII, *B*, p. 74.) The intrusion of the volcanic rock into the older rocks containing limestone might plausibly account for the production of carbon dioxide, either by heat alone or by chemical reactions that release this gas from the limestone. No close relation between the volcanic intrusives and the position of the carbonated springs was observed, though such a relation may exist.

OTHER CARBONATED SPRINGS ON SEWARD PENINSULA.

Carbonated springs similar to those near Bering were reported at six other places in the region—near Coyote Creek (7), near Igloo Creek (8), near Agiapuk River (5), near Dese Creek (9), near Budd Creek (10), and near Noxapaga River (14).

The carbonated springs near Coyote Creek (7) are 4 miles southeast of Teller. Their flow is said to be small but strongly carbonated. This water is locally considered to be less palatable than that of the springs near Bering.

Near Igloo Creek, 1½ to 2 miles above its mouth and about 7 miles northeastward across Grantley Harbor from Teller, small carbonated springs (8) are reported, but no details concerning them are at hand.

A group of carbonated springs (5) of fairly large flow issues near the south or west fork of Agiapuk River, 1½ to 2 miles above its junction with the main stream, or 10 miles in a direct line north of Teller. The springs have been seldom visited, however, and little attention appears to have been paid to them.

Some carbonated springs (9) about 8 miles southeast of Teller, near Dese Creek, 2 miles above its mouth, are locally considered to be as large and to yield as palatable drinking water as those near

[1] Collier, A. J., and others, The gold placers of parts of Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 328, pl. 10, 1908.

Digitized by Google

Bering, but on account of their greater distance and less accessibility from Teller they have been seldom visited.

A small group of mineral springs (10) is reported near Budd Creek, a tributary of American River, 35 miles in a direct line northeast of Teller. In an area about 10 feet in diameter there are said to be several cool springs, noticeably different in taste, though the characteristic tastes of carbon dioxide, hydrogen sulphide, and iron are said to be the most prominent.

About 65 miles in a direct line north of east from Teller, near Turner Creek a mile above its junction with Noxapaga River, a tributary of the Kuzitrin, there are carbonated springs (14) that are said to be similar to those near Bering.

So far as is known from reconnaissance geologic studies on the peninsula, all of these carbonated springs issue from the same general series of Silurian and Ordovician limestones, slates, and schists as do the carbonated springs near Bering.[1]

SULPHUR SPRINGS.

DISTRIBUTION.

Cool sulphur springs seem to be uncommon in Alaska, and the few that are reported are widely scattered. Those mentioned in the following pages are the only ones learned of by the author. Probably numerous other mildly sulphureted springs exist in various parts of the territory but they have received little attention from prospectors or trappers.

SULPHUR SPRINGS ON REVILLAGIGEDO ISLAND.

The only developed cool sulphur springs (108) of which information was obtained are situated west of George Inlet of Behm Canal, about 10 miles north of east from Ketchikan.

The springs are on the Peterson lode claim, in an area of crystalline schist.[2] The water issues mainly from a fissure in schist that dips 80° N. 65° E., at a point about 100 yards from and 50 feet above the shore, on the side of a small creek, 25 feet above the stream. Minor seepages of water issue from the banks a few feet away. In 1915 a small bathhouse with a wooden tub stood near the springs. One pipe conducted a part of the water directly to the tub, and another was connected with a coil in a small furnace beside the

[1] Collier, A. J., and others, The gold placers of parts of Seward Peninsula, Alaska: U. S. Geol. Survey Bull. 328, pls. 10 and 11, 1908.

[2] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, pl. 2, 1908. Smith, P. S., Lode mining in the Ketchikan region: U. S. Geol. Survey Bull. 592, p. 90, 1914.

Digitized by Google

house for heating the water for bathing. Two prospectors' cabins stood near the shore below the springs.

The total flow of the springs was about 4 gallons a minute, and the recorded temperature was 57° F. This temperature is probably 10° or 12° above the mean annual temperature of the region.[1] It may be due in part to the fact that the water rises from a considerable depth, where the earth's crust is considerably warmer; or it may be due wholly or in part to the heat of chemical reaction, principally the oxidation of pyrite (iron sulphide), a mineral which the schist contains in abundance.

The water is clear, with no bubbling. It tastes noticeably of hydrogen sulphide; and a white sulphur-secreting algal growth, a common accompaniment of cool sulphur springs, lines its run-off channel.

The following analysis shows the water to be of low mineral content, calcium carbonate in type, with an amount of silica that is high in proportion to the total solids:

Mineral analysis of water from principal sulphur spring on Revillagigedo Island, southeastern Alaska.[2]

[Parts per million except as otherwise designated.]

Silica (SiO_2)	31
Iron (Fe)	.5
Calcium (Ca)	15
Magnesium (Mg)	2.6
Sodium and potassium (Na+K)	[3]8.3
Carbonate radicle (CO_3)	.0
Bicarbonate radicle (HCO_3)	51
Sulphate radicle (SO_4)	16
Chloride radicle (Cl)	5.5
Nitrate radicle (NO_3)	.0
Borate radicle (B_4O_7)	.0
Total dissolved solids at 180° C	122
Temperature (°F.)	57
Chemical character	Ca–CO_3

The sulphate constituent in the water is probably derived largely from the pyrite in the schist. The reaction is not simply one of oxidation of the pyrite (iron sulphide) to iron sulphate; it probably involves not only the change of the pyrite to iron sulphate but also the reduction of part of this sulphate to soluble sulphides, which are pres-

[1] According to tables published by the Wrights (U. S. Geol. Survey Bull. 347, p. 29. 1908), the mean at Port Angeles, Wash., is 46.1° F., and at Wrangell, Alaska, 43° F. The mean near Ketchikan is probably between the two, or about 45° F.

[2] Tastes distinctly of hydrogen sulphide but has no appreciable odor. Sample collected June 15, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.

[3] Calculated.

Digitized by Google

ent in the water, together with sulphates, as it issues at the spring. During the time intervening between the collection of the water sample and its analysis, however, original sulphides may have become oxidized to sulphates and possibly some sulphate changed to sulphide. On this account the separate laboratory determination of sulphide was not made, all sulphur being reported as sulphate.

SULPHUR SPRINGS ON PRINCE OF WALES ISLAND.

W. G. Weigle, of the Forest Service, reports that sulphur springs (94) issue on the northwest shore of Prince of Wales Island, bordering El Capitan Passage. The flow is said to be about 15 gallons a minute of strongly sulphureted water. No spring deposits are reported, nor is the water believed to be notably mineralized except by the sulphide gas.

The rock formation of the locality has not been examined in detail by the United States Geological Survey, but reconnaissance studies show that the region consists of limestones, slates, schists, and other rocks of Carboniferous and older geologic age, intruded by masses of granitic rocks.[1] Such an intrusive mass occupies a considerable area on each side of El Capitan Passage, and may account for the issuance of the sulphur water. The position of the springs with respect to the contact zone between the old sediments and the intrusive granite was not learned.

SULPHUR SPRINGS NEAR MOUNT EDGECUMBE.

George Willett, of the United States Biological Survey, reports that there is a seepage of mineralized water (90) on the rocky beach near the base of Mount Edgecumbe, at the southern end of Kruzof Island, about opposite the islet of St. Lazaria.

The springs are covered by the highest tides, however, and the flow is too small to make it of more than local interest. The water has the characteristic odor of sulphureted hydrogen, but it appears not to be strongly mineralized.

The springs issue from the recent lava and volcanic tuff of Mount Edgecombe, which covers the southern portion of Kruzof Island.[2] The sulphide constituents in the water may be derived from sulphur compounds in tuffaceous phases of the rock, or it is possible that hydrogen sulphide gas is given off in small quantities and is taken directly into solution by the spring water.

[1] Wright, F. E., and Wright, C. W., The Ketchikan and Wrangell mining districts, Alaska: U. S. Geol. Survey Bull. 347, pl. 1, 1908.

[2] Knopf, Adolph, The Sitka mining district, Alaska: U. S. Geol. Survey Bull. 504, pl. 1, 1912.

Digitized by Google

SULPHUR SPRINGS ON BERING RIVER.

G. C. Martin,[1] of the United States Geological Survey, has noted cool sulphur springs (50) of moderate flow, which issue for a distance of nearly a mile along the north bank of Bering River near its mouth. W. G. Weigle, of the Forest Service, also reported to the writer the presence of a number of sulphureted springs in the neighborhood of Bering River and Bering Glacier. None of these springs appears to have received special notice from either the whites or the natives, and little if any use has been made of the mineralized waters.

The rock formation of the locality is composed of shales and sandstones of Tertiary geologic age that yield seeps of oil at some points.[2] In such rocks in other regions sulphur waters are fairly common, so their presence in the neighborhood of Bering Glacier is not unusually remarkable.

SULPHUR SPRINGS NEAR ILIAMNA LAKE.

Cool sulphur springs (80) have been observed by C. E. Giffin, of the United States Geological Survey, on a small creek near the eastern end of Iliamna Lake, in the eastern part of the Alaska Peninsula. The water is rather strongly sulphureted, but special attention was not paid to the other characteristics of the springs.

According to reconnaissance studies of the geology of the region, the springs issue in an area of basaltic lava of Tertiary age, which covers a number of square miles near the eastern end of the lake.[3] The relation of the sulphur water to the basalt is not clear, though it is possible that exhalations of hydrogen sulphide, representing a final stage in the volcanic activity, may supply the sulphide constituents in the water.

SULPHUR SPRING NEAR LITTLE SUSITNA RIVER.

A strong-smelling sulphur spring (49) near Little Susitna River has been visited by C. E. Giffin, of the United States Geological Survey. The water bubbles up from a hole perhaps an inch in diameter, in a marshy area near the river. Its temperature was not measured, but it is cool, and no algal growths nor deposits of mineral matter were observed.

The rocks of the region consist mainly of a series of sandstones and shales of Tertiary geologic age, which in places contains beds of

[1] Martin, G. C., The petroleum fields of the Pacific coast of Alaska: U. S. Geol. Survey Bull. 250, p. 22, 1905.

[2] Idem, pl. 3.

[3] Martin, G. C., and Katz, F. J., A geologic reconnaissance of the Iliamna region, Alaska: U. S. Geol. Survey Bull. 485, pl. 2, 1912.

Digitized by Google

coal.[1] Sulphureted waters are fairly common in such sedimentary rocks, and sulphur springs probably issue at other places in the basin of the Little Susitna.

SULPHUR SPRINGS NEAR SKILAK LAKE.

F. H. Moffit, of the Geological Survey, has observed seepages (48) of cool sulphur water on the western portion of the southern shore of Skilak Lake, on Kenai Peninsula. The springs were found by whites largely because they have been resorted to by moose as drinking springs or mineral licks. Hunters have built a small cabin near by, in which to wait for the game.

The water probably issues from glacial and terrace gravels overlying lignite-bearing clays and soft sandstones of Tertiary age.[2]

"Sheep licks," where mineralized earth is found, are reported at a number of places on the mainland of Alaska. One such locality is about 70 miles south of Nenana, near the line of the Government railroad that is being built from Seward to Fairbanks. This lick has afforded a good place to shoot wild sheep, but so far as reported there is no appreciable amount of sulphureted or other mineralized water.

SULPHUR SPRING ON ELDORADO CREEK.

J. D. Courtney, who formerly resided at Glacier, in the Kantishna River basin, southwest of Fairbanks, reports that cold sulphur water (41) issues 21 miles south of Glacier, on Eldorado Creek 1½ miles above its junction with Moose River. A large flow of water rises on the right edge of the creek. The run-off channel is rust-colored with iron oxide, and the water is therefore probably carbonated as well as sulphureted, for iron is commonly deposited in this manner from carbonated waters, on the escape of carbon dioxide.

The region is known from reconnaissance studies to be largely covered by deposits of gravel of Quaternary geologic age, but south of Glacier a considerable area of schist is exposed.[3] It is probable that the sulphureted and carbonated water rises through a fissure in the schist, though the surface may be covered by glacial gravels.

SULPHUR SPRING NEAR NENANA RIVER.

F. H. Moffit, of the United States Geological Survey, has noted a small mildly sulphureted spring (43) near Yannert Fork of

[1] Martin, G. C., and Katz, F. J., Geology and coal fields of the lower Matanuska Valley, Alaska: U. S. Geol. Survey Bull. 500, pl. 3, 1912.

[2] Martin, G. C., Johnson, B. L., and Grant, U. S., Geology and mineral resources of Kenai Peninsula, Alaska: U. S. Geol. Survey Bull. 587, pl. 3, 1915.

[3] Brooks, A. H., The Mount McKinley region, Alaska: U. S. Geol. Survey Prof. Paper 70, pl. 9, 1911.

Digitized by Google

Nenana River. The water is cool and not unpleasant for drinking, and the spring is regularly used as a drinking place by animals.

The spring is in an area of glacial gravels overlying conglomerate, graywacke, and shale of Eocene geologic age.[1] The water probably rises through a shaly bed, as such rock usually contains more or less sulphur-bearing material.

SULPHUR SPRING NEAR PLATINUM CREEK.

A spring (44) similar to that near Nenana River, that is more easily found as the trails of wild sheep and other large animals lead to it, has been noticed by Mr. Moffit near Platinum Creek, a tributary of Nabesna River. The temperature of this spring is not unusual, but the water appears to be rather strongly mineralized, possibly by sulphates and other alkaline constituents rather than by sulphides, and it was discovered largely because it is used as a lick by the sheep.

The spring issues in a locality of slates and other sediments of Carboniferous geologic age.[2] The water comes forth from the rock, well above the creek channel, probably from slaty material.

SULPHUR SPRINGS ON COAL CREEK.

Fred Brentlinger, of Circle, reports sulphur springs (35) about 50 miles southeast of Circle, on Coal Creek, 4 miles above its junction with Yukon River. The flow of water is small, but the sulphureted odor is very evident for a distance of 50 yards or more down the wind.

Reconnaissance studies of the geology along the lower portion of Coal Creek[3] indicate that the water probably issues from the rocks of Paleozoic geologic age that border the northwest side of the stream.

SULPHUR SPRINGS SOUTH OF CIRCLE.

C. H. McCartney, who has prospected in the region south of Circle, reports small, distinctly mineralized springs on the east side of Yukon River, about 15 miles above the town. The water issues on the slope near the river, half a mile below a prominent exposure of yellow material that is probably volcanic tuff. From the description given by Mr. McCartney of the taste of the water, it is probably rather strongly sulphureted, and may also contain unusually high

[1] Moffit, F. H., The Broad Pass region, Alaska: U. S. Geol. Survey Bull. 608, pl. 2, 1915.

[2] Moffit, F. H., and Knopf, Adolph, Mineral resources of the Nabesna-White River district, Alaska: U. S. Geol. Survey Bull. 417, pl. 2, 1910.

[3] Prindle, L. M., A geologic reconnaissance of the Circle quadrangle, Alaska: U. S. Geol. Survey Bull. 538, pl. 2, 1913.

Digitized by Google

amounts of alkaline salts. The substances in solution may be derived directly from the volcanic tuff, as such material often contains sulphates and other soluble salts.

SULPHUR SPRINGS NEAR IGNAK RIVER.

E. de K. Leffingwell, who has spent several years in exploration along the Arctic coast of Alaska, has noted two small sulphur springs (1) near Ignak River, about 6 miles above its junction with Canning River and 50 miles from the coast.

The springs issue respectively on the north and the south sides of a small drainage divide in a swale at the west end of Sadlerochit Mountains, at an elevation of 600 or 700 feet. The waters of these two springs are probably appreciably above the normal summer temperature of the surface waters, for they emerge beneath snow banks and keep narrow strips of ground bare of snow for several yards below their points of issuance.

The springs are in a region that is probably composed largely of Cretaceous sediments.[1] The sulphureted water possibly issues from a shaly bed in the Cretaceous sediments, for such rocks in many places contain sulphur compounds and yield sulphur waters.

IRON SPRINGS.

Although iron waters, or waters in which there is either a considerable precipitate of rust-colored iron oxide or a growth of the iron-secreting vegetable organisms, *Crenothrix* and its allied forms, are common in Alaska, only three springs of cold water containing notable deposits of iron oxide were observed by or reported to the writer.

Richard Creighton, of Fairbanks, told the writer that springs (37) yielding water "red as blood" issue from conglomerate on Michigan Creek opposite Nation River, on the south side of Yukon River 50 miles below Eagle. The water has been used to a slight extent by prospectors as a mineral water, but it tastes so strongly of iron as to be unpalatable.

Near the right bank of Chena River, about 6 miles above the mouth of Colorado Creek, a small creek or slough (28) contains a thick deposit of iron oxide. It is beside the trail between Fairbanks and Chena Hot Springs (29), and has been observed to remain unfrozen throughout the winter. The summer temperature of the water, however, is not abnormal.

John Vachon, merchant at Tolovana, reports a spring (26) of bad-tasting water one-quarter of a mile above the village, on the

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pl. 21, 1906.

Digitized by Google

opposite bank of Tanana River. (See fig. 10, p. 58.) The spring is accessible only at low-water stages of the river, when a brown scum and deposit form that are very probably of iron hydroxides. This water doubtless issues from the clay and fine sand of the river valley, and the iron may be derived directly from an iron-bearing clay.

Iron-water seeps, or pools containing iron deposits, were noted by the writer at several places, but they appeared to be more common in the northern moss-covered regions than in the southern timbered sections. Iron water seemed to be especially common on Seward Peninsula along small creeks in the tundra area between Iron Creek and Nome. Iron Creek was so named, however, because of the abundant nodules of iron ore in its upper course, and not because it contains flocculent deposits of iron oxide. The presence of iron in the surface waters at and near Nome is shown by deposits of the brown hydroxide and by iridescent films of the oxide in pools and along the gutters. Iron pipe and other iron articles seem to rust very quickly at this place. In the early days, before a water supply was brought down to the town from "Moonlight Springs," a small lake 3 or 4 miles away (see analysis 4, p. 108), domestic water was obtained from shallow pools in the tundra. It is said that a prospector who left his water pail partly filled while away from his cabin for a week or two on prospecting trips was often surprised on returning to find that a pale rust-colored, stringy or slimy growth (of iron-secreting *Crenothrix*) had been formed in the pail during his absence. *Crenothrix* develops especially well in waters that contain iron and organic matter, and the tundra water near Nome apparently contains both of these substances in amounts amply suited to the needs of the organism.

In the more northerly part of Seward Peninsula iron water is found at many places. A small stream 2 miles south of Teller contained a considerable deposit of iron in the summer of 1915. The iron deposits at the carbonated springs near Bering (6), 3 miles farther south, have already been mentioned, and also a deposit of iron at Kruzgamepa Hot Springs (13), a number of miles to the east.

The gravelly shore of Yukon River near Kokrines is in places cemented into a conglomerate by iron oxide that is evidently deposited by iron-bearing waters that seep from the adjacent banks.

Along small stream channels near the trail that leads northward from Kokrines to Melozitna Hot Springs (20) many seepages of iron water were seen issuing from the black muck and fine alluvium of the creek valleys.

On Little Chena River near Charles Main's roadhouse, 13¼ miles east of Fairbanks (see fig. 8, p. 55), the river gravel is deeply iron stained, apparently by water that seeps from the nearly vertical banks between which the stream has entrenched itself.

Digitized by Google

At several places along the margins of Tatalina River a short distance above its junction with Tolovana River (see fig. 10, p. 58) there are also iron seepages from the bordering gravel banks.

Three wells have been sunk at Tanana, 10 or 15 yards back from the bank of Yukon River. All yield very cold water (33° to 34° F. in August, 1915). Each well is housed, equipped with a hand pump, and used for domestic supply. Two of the wells yield good water, but the central one, in front of the Tanana Commercial Co.'s store, furnishes water that is locally considered very hard. The analysis of water from this well (analysis 1, below) and analyses of water from a well at Anvik and from Yukon River show that the Tanana well water, although it resembles the river water in being of the calcium carbonate type, is very different in mineral content. The well water contained about four times as much mineral matter as the river water taken a few miles upstream on the same date, and chloride was a fairly large constituent of the well water, though a very small one in the river water. The well water was similar in character and mineral content to the water of a well at Anvik mission, 400 miles downstream. The Anvik water contained a considerably greater proportion of chloride, which may have been derived in part from salt water that infiltered from the river bank, where salmon were being salted and packed. The presence of borax in the Tanana well water and its reported absence from the Anvik water are worthy of mention.

Mineral analyses of waters from Yukon River basin, Alaska.

[Parts per million except as otherwise designated.]

Constituents.	1	2	3
Silica (SiO_2)	23	72	8.8
Iron (Fe)	2.7	5.0	.20
Aluminum (Al)	1.5	2.3	.....
Calcium (Ca)	116	128	30
Magnesium (Mg)	33	38	6.0
Sodium (Na)	9.4	25	5.4
Potassium (K)	2.4	10	
Carbonate radicle (CO_3)	.0	.0	Trace.
Bicarbonate radicle (HCO_3)	387	456	103
Sulphate radicle (SO_4)	7.8	4.3	14
Chloride radicle (Cl)	69	78	Trace.
Nitrate radicle (NO_3)	1.5	Trace.	.....
Borate radicle (B_4O_7)	Present.	.0	.....
Total solids at 180° C	458	553	124
Suspended matter at 180° C	.....	.....	235
Temperature (° F.)	35	38	62.5
Chemical character	$Ca-CO_3$	$Ca-CO_3$	$Ca-CO_3$

1. Well in front of Tanana Commercial Co.'s store, Tanana. Deposits iron. Sample collected July 19, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
2. Well at Anvik Mission, Anvik. Sample collected Aug. 21, 1915, by G. A. Waring; analyzed by S. C. Dinsmore.
3. Yukon River 12 miles above Tanana. Sample collected July 19, 1915, by G. A. Waring; analyzed by R. B. Dole and Alfred A. Chambers.

Digitized by Google

SALT SPRINGS.

Only one locality (11) of salt springs in Alaska was reported to the writer. This is between 3 and 5 miles downstream from Arctic Hot Springs (12), where W. S. Thompson, of Kokrines, says there are a number of salt-water springs. This region is known to consist of altered rocks, largely limestones, slates, and schists of Silurian and Ordovician age.[1] The salt springs probably issue from slates, as these altered sedimentary rocks are more apt to contain salt than are the other known rocks of the vicinity.

Only two other springs were noted whose waters are notably salty. These are Kruzgamepa Hot Springs (13), on Seward Peninsula, and Sitka Hot Springs (92), in the southeastern part of the Territory. At the former spring the water contains 3,450 parts per million of chloride and tastes distinctly salty; and several patches in the lowland near the creek below the springs are whitened by a saline efflorescence. (See Pl. VII, *A*, p. 74.)

At Sitka Hot Springs, though the water is distinctly salty to the taste and contains 2,740 parts per million of chloride, no deposit was noted, nor is one probably formed, as the rainfall in the vicinity is so abundant as to keep the surface well washed.

The Kruzgamepa Hot Springs are in a flat river valley, about 12 miles in a direct line from tide water and perhaps 100 feet above sea level. Sitka Hot Springs are only 75 to 125 yards from salt water, but issue 55 to 80 feet above high-tide limit. In neither place does it appear probable that the salt is derived from sea water, however, as the chemical composition of the spring waters does not admit of such an hypothesis.

[1] Collier, A. J., A reconnaissance of the northwestern portion of Seward Peninsula, Alaska: U. S. Geol. Survey Prof. Paper 2, pl. 3, 1902.

Digitized by Google

CHEMICAL CHARACTER OF SOME SURFACE WATERS OF ALASKA.

By Richard B. Dole and Alfred A. Chambers.

GENERAL CHARACTER OF SURFACE WATERS.

This short report brings together the available analyses of Alaskan surface waters in order that they may serve as a nucleus for amplifying the rather meager knowledge now at hand regarding the chemical composition of streams in a subpolar region. Most of the analyses represent samples collected by exploring parties of the United States Geological Survey in 1914 and 1915. Seventeen spot samples from different points in Yukon River and several others from large or potentially important tributaries of that stream were collected in the summer of 1915 by G. A. Waring. The surface waters of Seward Peninsula were sampled by H. M. Eakin in 1914, and a few other waters from widely separated localities have been examined. Samples of water were collected daily from Yukon River at Anvik, from August 23, 1915, to April 19, 1916, and from June 14, 1916, to August 16, 1916, and the analyses of these samples will form part of a special report on the quality of the surface waters of Alaska.

The few analyses available for this report show a favorable condition of the surface waters. They indicate that the streams in general yield supplies moderate in mineral content, low in chloride and sulphate, and essentially calcium carbonate in character. All the supplies tested are low enough in mineral matter to be useful for domestic and industrial use, and they resemble in composition the least mineralized waters of the United States.

YUKON RIVER.

CHARACTER OF THE BASIN.

The climatic and geologic conditions in the basin of Yukon River are particularly interesting in a study of the quality of the water.

Digitized by Google

The basin[1] is bounded on the north, southwest, and east by ranges of high mountains, some glacier covered, all generally above the timber line. The mountains west and south of the upper basin consist largely of granitic, volcanic, and other slightly soluble silicate rocks. So far as is known the sedimentary rocks of these ranges are arenaceous rather than calcareous. The mountains on the north consist of sedimentary rocks with perhaps a greater proportion of limestone than those on the south.

Approximately two-thirds of the drainage basin between the bordering ranges is a dissected plateau that is deeply covered by mica schists, quartz schists, quartzite, some limestone, and considerable areas of granitic intrusives. The annual precipitation is relatively low. At White Horse, Yukon Territory, it is 8 to 10 inches; at Eagle, Alaska, about 12 inches, more than half of which occurs in June, July, and September; and at St. Michael, near the mouth of the Yukon, about 22 inches. The mean annual temperature at Eagle is 24° F. and the mean monthly temperature ranges from 24° below zero in January to 58° in June.[2]

As a result of the high elevation and the paucity of the rainfall timber is not abundant on this plateau. The surface is generally covered with a dense growth of moss, grass, and similar vegetation, which readily absorbs and retains much of the precipitation, thereby reducing the immediate run-off and the water available for slow percolation into the deeper strata. In addition to this the subsoil and alluvium throughout the basin and on Seward Peninsula are permanently frozen to bedrock. Excavations made at Fairbanks, for example, have shown that permanent frost exists to depths of more than 300 feet. Though there are small areas in which ground water circulates to some extent, these peculiar frozen conditions result in a general absence of the circulating ground water that contributes so markedly to the mineral content of streams in regions of higher temperature and more humid conditions. Consequently, the perceptible effects of erosion are largely confined to the exposed bedrock on the crests of ridges and mountains and to the local deposits along the rivers. The smaller streams have cut to bedrock, which they are now eroding, but the beds of the larger streams are filled with alluvium, and bedrock is exposed in but few places along them.

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, 1906.

[2] Porter, E. A., and Davenport, R. W., The discharge of Yukon River at Eagle, Alaska: U. S. Geol. Survey Water-Supply Paper 345, pp. 68–70, 1915.

Digitized by Google

MINERAL ANALYSES OF WATER OF YUKON RIVER.

The following table gives the results of analyses by R. B. Dole and A. A. Chambers, in the laboratory of the United States Geological Survey, of 17 samples of water from Yukon River, collected by G. A. Waring during July and August, 1915. The analyses were made in accordance with the methods outlined in Water-Supply Paper 236.[1] Though great accuracy could not be attained in some of the determinations, as each sample measured less than 2,000 cubic centimeters, the results are reasonably precise and concordant.

[1] Dole, R. B., The quality of surface waters in the United States: Part I, Analyses of waters east of the one hundredth meridian: U. S. Geol. Survey Water-Supply Paper 236, pp. 9–26, 1909.

Digitized by Google

Mineral analyses of water of Yukon River, Alaska, in 1915.

[Parts per million except as otherwise designated. R. B. Dole and Alfred A. Chambers, analysts.]

Location.	Date.	Temperature of water.	Condition of current.	Stage of river.	Suspended matter at 180° C.	Silica (SiO_2).	Iron (Fe).	Calcium (Ca).	Magnesium (Mg).	Sodium and potassium (Na+K)	Carbonate radicle (CO_3).	Bicarbonate radicle (HCO_3).	Sulphate radicle (SO_4).	Chloride radicle (Cl).	Dissolved matter at 180° C.
		°F.													
At Whitehorse, Yukon Territory	July 5	61.5	Swift	High	11	8.0	Tr.	14	2.0	3.4	0.0	49	6.0	Tr.	59
3 miles below mouth of Teslin River, Yukon Territory.	July 6	60.5	...do	...do	10	10	0.08	14	1.6	4.2	.0	55	6.0	Tr.	66
1 mile below Fivefinger Rapids, Yukon Territory.	July 7	61.0	Moderate	Medium	26	10	Tr.	17	3.8	3.7	.0	65	6.5	Tr.	74
Near Selwyn, Yukon Territory	...do	61.5	...do	...do	32	11	.02	18	4.5	3.9	.0	71	9.6	Tr.	84
One-half mile above mouth of Stewart River, Yukon Territory.	...do	61.5	...do	...do	1,100	15	.10	31	6.4	6.8	Tr.	113	17	Tr.	137
10 miles below Stewart River, Yukon Territory	...do	62.0	...do	...do	510	9.7	.13	26	6.0	4.8	Tr.	100	18	Tr.	116
1 mile below Dawson, Yukon Territory	July 8	61.0	...do	...do	685	8.6	.09	28	5.8	5.5	Tr.	107	16	Tr.	123
At Eagle, Alaska	...do	63.0	...do	...do	770	9.6	.19	27	6.2	6.2	Tr.	98	16	Tr.	121
At Circle, Alaska	July 9	63.5	Sluggish	...do	680	8.8	.10	26	5.8	5.0	Tr.	98	16	Tr.	117
Do	July 17	62.0	Moderate	...do	590	8.7	.06	28	6.4	5.2	Tr.	104	16	Tr.	125
About 15 miles below Fort Yukon, Alaska, above mouth of Chandalar River.	July 18	63.0	...do	...do	615	9.7	.11	27	6.7	6.7	Tr.	102	17	Tr.	120
About 20 miles above Dall River, Alaska	...do	62.0	Sluggish	...do	260	9.2	.04	29	5.6	5.2	Tr.	107	14	Tr.	122
6 miles above Rampart, Alaska	July 19	61.5	Moderate	...do	236	11	Tr.	29	6.6	.....	Tr.	102	15	Tr.	127
12 miles above Tanana, Alaska	...do	62.5	...do	...do	235	8.8	.20	30	6.0	5.4	Tr.	103	14	Tr.	124
30 miles below Tanana, Alaska	Aug. 17	59.0	.....	Rising	285	7.1	.10	23	5.4	6.1	Tr.	90	17	0.5	113
100 miles above Anvik, Alaska	Aug. 19	60.0	.....	.....	360	6.0	.12	29	5.4	7.1	Tr.	108	16	.8	120
20 miles below Andreafski, Alaska	Aug. 23	58.0	.....	.....	610	7.6	.10	30	6.3	6.6	Tr.	105	18	.8	.....

Digitized by Google

The analyses are arranged by source in consecutive order downstream and represent the general character of the river water from Whitehorse, near the headwaters in Yukon Territory, Canada, practically to tidewater below Andreafski, Alaska, a distance of more than 1,800 miles by river. (See Pl. I.) As the samples were collected in midsummer within a period of 50 days, they represent fairly well the various changes that the water undergoes because of the entrance of large tributaries and seepage from rocks of different character. From Whitehorse to Selwyn the suspended matter in the water ranged from 10 to 32 parts per million, and was organic and rather flaky. The content of dissolved matter ranged from 59 to 84 parts per million, with a progressive increase downstream, and the type was essentially calcium carbonate, with very little sulphate and almost no chloride. The water in this upper stretch closely resembled that of many mountain streams in New England, northern Minnesota, and western Washington and Oregon, where hard, crystalline, difficultly soluble rocks, such as granite, gneiss, and basalt, abound. Below Selwyn the mineral content of the water was materially changed by the entrance of White River, a large, muddy stream draining part of western Yukon Territory, and the first tributary that contributes a large volume of drainage from glaciers. The suspended matter jumped to 1,100 parts per million, and calcium, carbonate, sulphate, and dissolved matter each increased as much as 60 per cent. These amounts were maintained in fairly regular manner thereafter to the mouth of the river. This striking alteration in mineral content indicates the entrance of water from areas subject to increased erosion. So far as the geology has been studied there is nothing to indicate that the lower part of the basin contains any greater proportion of limestone than the upper part. The deposits of volcanic ash that exist throughout the upper basin[1] and are especially thick in the basin of White River may have an important influence on the suspended and dissolved matter of these streams. Though the entrance of Stewart River from the east above Dawson reduced somewhat the effect of White River, little change was apparent from the entrance of Porcupine River at Fort Yukon and Tanana River at Tanana. Tanana River has many tributaries in the higher ranges and contributes water from glacial sources. The content of suspended matter regularly increased below the mouth of Tanana River from 285 parts near Tanana to 610 parts per million below Andreafski.

The 14 samples collected above the mouth of Tanana River contained too little chloride to titrate in 250 cubic centimeter samples

[1] Capps, S. R., An ancient volcanic eruption in the upper Yukon basin: U. S. Geol. Survey Prof. Paper 95, pp. 59–64, 1915.

Digitized by Google

concentrated to 25 cubic centimeters. The presence of a trace of chloride was demonstrated, however, by a slight cloudiness with silver nitrate in a 1,000 cubic centimeter composite sample concentrated to 100 cubic centimeters. The content of chloride increased progressively downstream below the mouth of Tanana River, and the increase doubtless represents the effect of cyclic or wind-borne salt from the ocean. The last three stations at which samples were collected are, respectively, 250, 85, and 35 miles in a direct line from Bering Sea, and the chloride contents of the river water at these stations were, respectively, 0.5, 0.8, and 0.8 part per million.

Much of the suspended matter is very fine and difficult to remove by filtration. It is gray and sticky and fuses in the blast to a brown glass. Rough analyses of the suspended matter, apparently clay, in three samples gave the approximate percentage composition: Silica (SiO_2), 40; ferric oxide (Fe_2O_3), 10; aluminum oxide (Al_2O_3), 18; calcium oxide (CaO), 12; loss on ignition and undetermined, 20.

CHEMICAL COMPOSITION OF WATER OF YUKON RIVER.

The chemical composition of the water of Yukon River in its headwater and lower sections is shown in the following table by figures computed by averaging the results, respectively, of the first 4 and the last 13 analyses in the preceding table. For comparison the analysis by George Steiger, of the U. S. Geological Survey, in 1905, of a sample from Yukon River at Eagle, is added.[1]

Average chemical composition of water of Yukon River.

Constituents.	Parts per million.			Percentage of anhydrous residue.		
	1	2	3	1	2	3
Suspended matter at 180° C	20	534				
Dissolved matter at 180° C	71	122	98			
Silica (SiO_2)	10	9.4	7.6	14.2	8.1	7.8
Iron (Fe)	.02	.10		.0	.1	
Calcium (Ca)	16	28	22	22.9	24.1	22.2
Magnesium (Mg)	3.0	6.0	4.6	4.3	5.2	4.7
Sodium and potassium (Na+K)	3.8	5.9	6.0	5.5	5.0	6.1
Carbonate radicle (CO_3)	.0	Tr.		42.9	43.6	46.2
Bicarbonate radicle (HCO_3)	60	103	91			
Sulphate radicle (SO_4)	7.0	16	11	10.2	13.9	10.8
Chloride radicle (Cl)	Tr.	.02	.4	.0	.0	.4

1. Average of first 4 analyses by Dole and Chambers.
2. Average of last 13 analyses by Dole and Chambers.
3. Analysis by George Steiger. Aluminum oxide (Al_2O_3), 1.8 parts per million or 1.8 per cent.

[1] Clarke, F. W., The data of geochemistry, 3d ed.; U. S. Geol. Survey Bull. 616, p. 86, 1916.

Digitized by Google

All three sets of figures are concordant, and they represent a calcium carbonate water low in mineral content. The river water below the mouth of Stewart River averages about 102 parts per million, or 0.85 pound per 1,000 gallons in its content of scale-forming material, excluding the suspended clay; the scale-forming material, including the clay, amounts to about 640 parts per million, or 5.3 pounds per 1,000 gallons. The chief result of the use of this water in boilers would be the deposition of soft sludge that could readily be blown out. It would be more economical to allow the mud to settle in tanks before introducing the water into boilers than to use the muddy water. The water would not cause foaming or corrosion under normal conditions.

DISCHARGE OF YUKON RIVER.

The total drainage basin of Yukon River covers 320,000 square miles according to Brooks,[1] who has also published estimates of the discharge, ranging from 96,000 to 436,000 second-feet, respectively, at low and high water stages. The mean discharge[2] of Yukon River at Eagle, Alaska, during the 3-year period 1911–1913 was 73,200 second-feet, and the drainage basin above that point covers 122,000 square miles. If the discharge at the mouth is proportionate to that at Eagle, the average discharge at the mouth is about 200,000 second-feet. If the average discharge is 200,000 second-feet, the average content of dissolved matter 122 parts per million, and the average content of suspended matter 500 parts per million the river carries annually into Bering Sea 98,000,000 tons of suspended matter and 24,000,000 tons of dissolved matter, equivalent to 1,600 millionths of an inch as suspended and 380 millionths of an inch as dissolved matter each year, or about 2 thousandths of an inch total. The average rate of denudation in the United States is equivalent to 490 millionths of an inch as dissolved matter and 890 millionths of an inch as suspended matter,[3] or about 1.4 thousandths of an inch total. It appears, therefore, that the removal of material in solution is progressing somewhat more slowly in Alaska than in the United States, because of less precipitation and less underground circulation of water. The estimate of removal as suspended matter is doubtless too high; the analyses on which the estimate is based were made on samples collected in summer, and it is understood that the stream, in its lower portion at least, carries very little suspended matter in winter.

[1] Brooks, A. H., The geography and geology of Alaska: U. S. Geol. Survey Prof. Paper 45, pp. 64–66, 1906.

[2] Porter, E. A., and Davenport, R. W., The discharge of Yukon River at Eagle, Alaska: U. S. Geol. Survey Water-Supply Paper 345, pp. 67–77, 1915.

[3] Dole, R. B., and Stabler, Herman, Denudation: U. S. Geol. Survey Water-Supply Paper 234, p. 84, 1909.

Digitized by Google

COMPARATIVE COMPOSITION OF WATERS OF GREAT NORTH AMERICAN RIVERS.

The composition of the water of Yukon River in comparison with that of other great rivers of North America is shown in the following table. It resembles that of Columbia and St. Lawrence rivers more closely than the others.

Chemical composition of waters of great North American rivers.

Constituents.	Parts per million.					
	1	2	3	4	5	6
Suspended matter	524	46	5,354	2,475	600	Tr.
Dissolved matter	122	93	707	791	166	134
Silica (SiO_2)	9.4	14	.....	29	11	6.6
Iron (Fe)	.10	.05	.....	[a] 3.6	[b] .13	.05
Calcium (Ca)	28	16	92	104	32	31
Magnesium (Mg)	6.0	4.0	23	23	8.4	7.2
Sodium and potassium (Na+K)	5.9	8.2	113	119	13	6.3
Carbonate radicle (CO_3)	Tr.	.0	2.0	.0	.0	2.9
Bicarbonate radicle (HCO_3)	103	68	233	178	111	116
Sulphate radicle (SO_4)	16	12	184	228	24	12
Chloride radicle (Cl)	.02	2.6	127	164	9.7	7.7
Nitrate radicle (NO_3)	.....	.5	.7	.....	2.5	.3

Constituents.	Percentage of anhydrous residue.					
	1	2	3[c]	4	5	6
Silica (SiO_2)	14.2	15.2	.....	3.8	7.1	5.0
Iron (Fe)	.0	[d] .1	.....	[a] .5	[d] .1	[d] .1
Calcium (Ca)	22.9	17.5	18	13.7	20.6	23.6
Magnesium (Mg)	4.3	4.4	3.3	3.0	5.4	5.5
Sodium and potassium (Na+K)	5.5	9.0	16	15.7	8.4	4.8
Carbonate radicle (CO_3)	42.9	37.2	16.6	11.6	34.7	45.7
Bicarbonate radicle (HCO_3)	.....	.....	.....	.....	.....	.....
Sulphate radicle (SO_4)	10.2	13.1	26	30.1	15.4	9.2
Chloride radicle (Cl)	.0	2.9	18	21.6	6.2	5.9
Nitrate radicle (NO_3)	.....	.6	.1	.....	1.6	.2

[a] $Fe_2O_3+Al_2O_3$.
[b] Also Al = 0.4 part or 0.2 per cent.
[c] Percentage of dissolved matter.
[d] Fe_2O_3.

1. Average of last 13 analyses of Yukon River by Dole and Chambers, July and August, 1915.
2. Average of 66 analyses of 10-day composite samples from Columbia River at Cascade Locks, Oreg., March, 1910, to August, 1912, by Walton Van Winkle, U. S. Geological Survey.
3. Average of 12 analyses of monthly composite samples from Colorado River at Yuma, Ariz., in 1905, by H. W. Heileman.
4. Average of 37 analyses of 10-day composite samples of Rio Grande at Laredo, Tex., August, 1905, to August, 1906, by H. W. Heileman.
5. Average of 52 analyses of weekly samples from Mississippi River at New Orleans, La., April, 1905, to May, 1906, by J. L. Porter, New Orleans, La.
6. Average of 11 analyses of monthly samples from St. Lawrence River at Ogdensburg, N. Y., September, 1906, to August, 1907, by R. B. Dole and M. G. Roberts.

YUKON-TANANA REGION.

Analyses of 11 samples of water from Tanana River, creeks in the vicinity of Fairbanks, and other streams in the Yukon-Tanana region are given in the following table:

Digitized by Google

Analyses of waters from streams in the Yukon-Tanana region.

[Parts per million; S. C. Dinsmore, analyst.]

Constituents.	1	2	3	4	5	6	7	8	9	10	11
Silica (SiO_2)	11	28	11	21	11	10	8.0	5.0	12	17	12
Iron (Fe)	Tr.	Tr.	.08	Tr.	.5	Tr.	.05	Tr.	.0	.0	.02
Calcium (Ca)	31	32	30	19	19	17	6.5	12	13	12	19
Magnesium (Mg)	4.9	4.9	5.1	3.8	6.2	4.8	5.4	3.0	5.0	8.0	8.0
Sodium and potassium (Na+K) [a]	4.0	6.2	7.7	5.1	2.3	5.2	7.3	5.0	12	4.0	.5
Carbonate radicle (CO_3)	.0	.0	.0	.0	.0	.0	.0	.0	.0	.0	.0
Bicarbonate radicle (HCO_3)	107	109	106	80	76	76	29	49	88	44	85
Sulphate radicle (SO_4)	13	17	21	4.9	10	5.7	2.8	5.3	.0	31	.0
Chloride radicle (Cl)	3.0	4.0	1.6	1.5	2.0	2.5	1.0	1.0	4.0	2.0	8.0
Nitrate radicle (NO_3)	.8	1.0	.2	1.0	3.0	2.0	Tr.	1.5	.6	.5	.5
Total dissolved solids at 180° C	123	147	130	101	105	107	82	59	140	93	141
Probable scale-forming ingredients [a]	110	130	100	85	75	70	35	45	60	70	80

[a] Calculated.

1. Tanana River 15 miles below Chena. River at medium stage. Collected by G. A. Waring, July 21, 1915.
2. Tanana River 5 miles below entrance of Kantishna River. River at medium stage. Collected by G. A. Waring, July 20, 1915.
3. Tanana River 5 miles above its mouth. River at medium stage. Collected by G. A. Waring, July 19, 1915.
4. Baker Creek 30 yards above mouth of Eureka Creek. Collected by G. A. Waring, Aug. 7, 1915.
5. Chatanika River one-half mile above its junction with Tolovana River. Collected by G. A. Waring, Aug. 3, 1915.
6. Tolovana River 2 miles above its junction with Tanana River. Collected by G. A. Waring, Aug. 4, 1915.
7. North Fork of Chena River above mouth of Monument Creek. Collected by R. F. Chamberlin August, 1915.
8. Illinois Creek one-quarter mile above its junction with Yukon River. Collected by G. A. Waring, Aug. 17, 1915.
9. A small tributary of Esther Creek from the south, opposite the mouth of Eva Creek, about 7 miles west of Fairbanks. Collected by H. M. Eakin, Aug. 10, 1914.
10. Ready Bullion Creek near mouth; a tributary of Esther Creek about 8 miles west of Fairbanks. Collected by H. M. Eakin, Aug. 10, 1914.
11. St. Patricks Creek at Esther Siding, about 5 miles west of Fairbanks. Collected by H. M. Eakin, Aug. 10, 1914.

Digitized by Google

Tanana River drains a large area south of Yukon River in central Alaska. (See Pl. I, in pocket.) The water of this stream is low in mineral content and calcium carbonate in type. It contains almost no iron and little sulphate or chloride. It would form a small amount of soft scale in boilers but would not foam or cause corrosion. The water is moderately hard, but is far softer than many widely used city supplies. The waters of Baker Creek, Chatanika River, and Tolovana River are similar to one another in concentration and composition and are like the water of Tanana River except that they are lower in mineral content. The waters from the North Fork of Chena River and from Illinois Creek are particularly low in mineral content and typify drainage from silicate rocks.

Esther Creek enters Cripple Creek, and that stream in turn enters Chena Slough, which is a tributary of Tanana River, one of the chief branches of Yukon River in central Alaska. These three waters are low in mineral content and are good for boiler use, though that represented by analysis No. 10 is somewhat less desirable than the others because of its relatively high content of sulphate, which would render the scale much harder.

SEWARD PENINSULA.

Analyses by S. C. Dinsmore of 6 samples of surface water from Seward Peninsula (Pl. I, in pocket) are given in the following table:

Mineral analyses of waters from Seward Peninsula, Alaska.

[Parts per million; S. C. Dinsmore, analyst.]

Constituents.	1	2	3	4	5	6
Silica (SiO_2)	5.0	22	17	8.0	25	5.0
Iron (Fe)	.02	.02	.02	.01	.03	Tr.
Calcium (Ca)	9.0	40	48	41	46	27
Magnesium (Mg)	3.0	6.0	5.0	3.0	9.0	6.7
Sodium and potassium (Na+K)[a]	1.0	1.0	16	6.5	1.0	Tr.
Carbonate radicle (CO_3)	.0	.0	.0	.0	.0	.0
Bicarbonate radicle (HCO_3)	19	114	178	136	178	76
Sulphate radicle (SO_4)	9.0	.0	.0	5.0	.0	4.9
Chloride radicle (Cl)	8.0	13	21	6.0	6.0	17
Nitrate radicle (NO_3)	1.0	18	.0	4.5	.0	Tr.
Total solids at 180° C.	50	164	224	138	178	98

[a] Calculated.

1. Sutter Creek near mouth, York region, July 16, 1914.
2. Dry Creek, 2 miles above mouth, near Nome, July 20, 1914. A mining plant was in operation 2 miles above the sampling point.
3. Typical water from a pool on the tundra near the mouth of Dry Creek, July 20, 1914.
4. "Moonlight Springs," a surface-water lake, near Nome, July 20, 1914.
5. Large spring at foot of slope below Iron Mine on Sinuk River, September, 1914.
6. Kruzgamepa River opposite Kruzgamepa Hot Springs, low stage, Sept. 2, 1915.

The first five samples were collected by H. M. Eakin and the last one by G. A. Waring. All these waters, except the first and the last, are similar in composition and appreciably higher in mineral content than those from creeks near Fairbanks, and they show the essential characteristics of drainage from limestone. They are moderate in mineral content and calcium carbonate in type; they contain small

Digitized by Google

amounts of sulphate and chloride but almost no iron. In boilers they would deposit a moderate quantity of rather soft scale but would not foam or cause corrosion. Analyses 1 and 6 represent waters much lower in mineral content.

LOWE AND COPPER RIVERS.

Analyses of the water of Lowe and Copper rivers are given in the following table. Lowe River, a glacial stream flowing into Port Valdez (Pl. I, in pocket), drains a region essentially of hard, insoluble silicate rocks and its composition reflects that condition. The water of Copper River, flowing into the Pacific Ocean, was very muddy at the time of sampling, and is noticeably higher in several ingredients than that of Lowe River.

Mineral analyses of waters of Lowe and Copper rivers.

[Parts per million.]

Constituents.	1	2
Silica (SiO_2)	7.0	8.0
Iron (Fe)	.5	.30
Calcium (Ca)	11	32
Magnesium (Mg)	3.0	7.3
Sodium and potassium (Na+K)	[a] 11	11
Carbonate radicle (CO_3)	.0	.0
Bicarbonate radicle (HCO_3)	59	110
Sulphate radicle (SO_4)	9.8	18
Chloride radicle (Cl)	3.0	1.6
Nitrate radicle (NO_3)	2.0	.50
Suspended solids at 180° C		1,068
Dissolved solids at 180° C	87	146
Probable scale-forming constituents [a]	45	115

[a] Calculated.

1. Lowe River near Valdez. Collected Oct. 20, 1915, by B. L. Johnson; S. C. Dinsmore, analyst.
2. Copper River at Flag Point Bridge (mile 30) on Copper River & Northwestern Ry. Collected Sept. 24, 1915, by F. H. Moffit; Alfred A. Chambers, analyst.

STIKINE RIVER.

One analysis of the water of Stikine River, whose mouth is in southeastern Alaska, is given below. The sample was collected June 20, 1915, by G. A. Waring about 15 miles above Wrangell and was analyzed by S. C. Dinsmore. The river is said to be muddy always. The content of dissolved matter is very low, and the water represents in composition the drainage from rather insoluble silicate rocks.

Mineral analysis of water from Stikine River.

[Parts per million.]

Silica (SiO_2)	15	Bicarbonate radicle (HCO_3)	63
Iron (Fe)	.5	Sulphate radicle (SO_4)	15
Calcium (Ca)	21	Chloride radicle (Cl)	1.5
Magnesium (Mg)	3.6	Nitrate radicale (NO_3)[1]	Tr.
Sodium and potassium (Na+K)[1]	1.0	Dissolved solids at 180° C	81
Carbonate radicle (CO_3)	.0		

[1] Calculated.

Digitized by Google

Digitized by Google

INDEX.

A.

Page.

Agiapuk River, carbonated springs near ---- 88
Agriculture, Dept. of, analyses by--- 18
Akutan Island, hot spring on------ 44–45
hot spring on, analysis of------ 45
Alaska, map of, showing mineral springs and volcanoes.. 12
subdivisions of---------- 12–13
Alaska, northern, erosion in------- 8–9
ground frost in---------- 9
origin of---------- 10
ground-water of, circulation of.. 9
surface waters of, analyses of... 8
Alaska, southeastern, carbonated springs in-------- 13, 77–83
carbonated springs in, distribution of ---------- 77
hot springs in---------- 13, 19–42
distribution of---------- 19
map of, showing mineral springs---------- 18
hot springs of---------- 42–49
See also Alaska Peninsula; Aleutian Islands.
Alaska Peninsula, hot springs of.. 13, 42–47
Alatna River, warm springs on---- 69
Aleutian Islands, hot springs of.. 13, 42–44, 47–49
Algae, occurrence of---------- 16–17
Aluminum in solution, effect of---- 15
Analyses, forms of---------- 18
See also particular springs, etc.
Anvik, well water at, analysis of--- 97
Arctic Hot Springs, cause of------- 14
description of---------- 75–76
salt springs near---------- 98
Attu Island, warm springs on------ 49

B.

Bailey Bay Hot Springs, analysis of.. 25
description of---------- 20–23
map of---------- 21
Baker Hot Springs, analysis of------ 62
description of---------- 60–62
map of---------- 61
view of---------- 54
Baranof Hot Springs, analysis of--- 32
description of---------- 26–27
map of---------- 26
Baranof Island, hot springs on------ 26–27, 30–31
Baths, hot, effect of---------- 17
Becharof Lake, hot springs on------ 46
Bell Island Hot Springs, analysis of.. 25
description of---------- 19–20
view of---------- 20
Bering, carbonated springs near---- 86–88
carbonated springs near, analysis of---------- 87
Bering River, sulphur springs on--- 92
Big Windy Creek, hot springs on--- 53–54
Bogoslof Island, hot springs on---- 47
origin of---------- 47–49
Brooks, A. H., preface by---------- 7

C.

Calcium in solution, effect of------- 15, 18
Cameron, A. G., on Bogoslof Island.. 47, 49
Carbonated springs, description of... 77–89
Carbonated waters, effect of------- 16
Chambers, A. A. *See* Dole and Chambers.
Chapin, Theodore, mineral springs reported by---------- 81–82
Chapman, J. W., water samples collected by---------- 11
Chena Hot Springs, analysis of----- 62
description of---------- 55–57
map of---------- 56
view of---------- 54
Chena River, iron springs on------- 95
Chloride (saline) waters, effect of... 16
taste of---------- 18
See also Salt Springs.
Circle district, mineral springs of... 51–54
mineral springs of, map showing ---------- 50
sulphur springs in---------- 94–95
Circle Hot Springs, analysis of----- 62
description of---------- 51–53
map of---------- 51
view of---------- 28
Coal Creek (Circle district), sulphur springs on ---------- 94
Coal Creek (Yukon River), carbonated springs on---- 84–85
Collier, A. J., on Arctic Hot Springs.. 75–76
Copper River, water of, analysis of.. 109
Coyote Creek, carbonated springs near ---------- 88
Crenothrix, occurrence of---------- 17, 96

D.

Dall, W. H., on hot springs... 28, 44, 63–64
Dinsmore, S. C., analysis by------- 18

Digitized by Google

Page.

Dole, R. B., and Chambers, A. A., on Chemical character of some surface waters of Alaska 99–109

E.

Eagle, iron spring near 95
Eakin, H. M., acknowledgments to 8, 12, 99
springs reported by 45
Edgecumbe, Mount, sulphur springs near 91
Eldorado Creek, sulphur spring on .. 93

F.

Fairbanks district, mineral springs in 55–57
mineral springs of, map showing 55
Fish Bay, hot springs near 31–33
hot springs near, analysis of ... 32
map of 30
Flat Creek, hot springs near 54

G.

Giffen, C. E., mineral springs reported by 69, 70, 92
Glacier, warm springs near 63–64
Grewingk, C., on southwestern Alaska 42–44
Gut Bay, hot springs near 30–31

H.

Harrington, G. L., acknowledgments to 12
on carbonated springs 85
Hoonlah, hot spring near 41
Hoonlah Warm Springs, analysis of 40
description of 34–35
Horner Hot Springs, analysis of 74
description of 68–69
view of 74
Hosoanna Creek, carbonated spring on 85
Hot springs, cause of 7–8
descriptions of 19–77
distribution of 7–8, 19
early use of 7
Hot Springs district, mineral springs in 57–60
mineral springs in, map showing 58
Hutlinana Hot Spring, analysis of .. 62
description of 59–60

I.

Iditarod, hot springs near 71
Igloo Creek, carbonated springs near 88
Ignak River, sulphur springs near .. 95
Inmachuk River, warm springs near 76
warm springs near, view of 76
Innoko basin, hot springs in 70–71
Iron in solution, effect of 15
taste of 18
Iron springs, descriptions of 95–97
Itinerary 11–12

K.

Page.

Katmai Pass, hot springs near 74
Kokrines, iron seeps near 96
Krusgamepa Hot Springs, analysis of 74
description of 72–75, 96
iron deposits near 96
map of 73
view of 74
salt in 96
Kwiniuk River, hot springs near 77

L.

Leffingwell, E. de K., on mineral springs 96
Little Chena River, iron stains near 96
Little Meloxitna Hot Springs, description of 64–66
map of 65
Little Minook Creek, hot springs near 59
Lituya Bay, hot springs near 41
Lowe River, water of, analysis of ... 109

M.

Maddren, A. G., acknowledgments to 12
mineral springs reported by ... 71
Magnesium in solution, effect of 15, 18
Marshall, carbonated springs near .. 85–86
carbonated springs near, analysis of 87
Martin, G. C., acknowledgments to 12
on mineral springs 85, 92
Meloxitna Hot Springs, analysis of .. 74
description of 66–68
map of 67
view of 18
Merriam, C. H., in Bogoslof Island .. 47–49
Michigan Creek, iron springs on 95
Mineral waters, beneficial effects of 14–15
Moffit, T. H., acknowledgments to .. 12
on mineral springs reported by 93–94

N.

Nenana River, sulphur spring near 93–94
New Eddystone Rock, carbonated springs near 78
carbonated springs near, analysis of 87
view of 6
Nika Bay, hot spring near 41
North American rivers, composition of 106

P.

Parts per million, meaning of 16
Peril Strait, hot springs on, analysis of 40
hot springs on, description of .. 33–34
Petrof, Ivan, on hot springs 44
Platinum Creek, sulphur spring near 94

Digitized by Google

Page.

Port Heiden, hot springs near 46
Port Moller Hot Springs, description of 45–46
Potassium in solution, effect of 16
Prince of Wales Island, sulphur spring on 91

R.

Roy River, hot springs on 64
Reed River, warm spring near 70
Revillagigedo Island, carbonated springs on 78–79
carbonated springs on, analysis of 87
view of 76
sulphur springs on 89–91
analysis of 90
Rivers, North American, composition of 106
Russell, I. C., on volcanic belt in southwestern Alaska 42

S.

Saks Cove, hot springs near 23
Salt springs, description of 98
Selawik River, hot springs near 70
Seward Peninsula, carbonated springs of 14, 86–89
carbonated springs of, distribution of 86
hot springs of 14, 72–77
distribution of 72
iron springs in 96
map of, showing mineral springs 72
surface waters of, analyses of 108–109
Shakes Hot Springs, analysis of 25
description of 24
hot springs near 25
Silica in solution, amount of, in Alaska springs 18–19
effect of 15
Simpson, George, on Sitka Hot Springs 28
Sitka Hot Springs, analyses of 32
description of 28–30, 98
salt in 98
view of 28
Skilak Lake, sulphur springs near 93
Smith, P. S., acknowledgments to 12
Soda Bay, carbonated springs near 79–81
carbonated springs near, map of 80
view of 82
Sodium in solution, effect of 16
Springs, distribution of 12–14
distribution of, map showing 18
temperature of 17–18
depth of source indicated by 17–18
See also Hot springs; Carbonated springs; Sulphur springs; etc.

Page.

Spurr, J. E., on springs at Katmai Pass 47
Stikine River, hot springs on 25–26
water of, analysis of 109
Stoney, G. M., on spring near Reed River 70
Sulphate waters, effect of 16
taste of 18
Sulphide waters, effect of 16
Sulphur springs, descriptions of 89–95
distribution of 89
Sulphuraria, occurrence of 17
Sweepstake Creek, hot springs near 77

T.

Tanana, well water at 97
well water at, analysis of 97
Tanana River, iron springs on 95–96
Tanana River and tributaries, character of 108
waters of, analyses of 107
Tatalina River, iron seeps on 97
Temperature, estimation of depth of water source by 17–18
Tenakee Hot Springs, analysis of 40
description of 35–38
map of 36
view of 28
Tenakee Inlet, hot springs near, analysis of 40
hot springs near, description of 38–41
map of 39
Teller, carbonated springs near 88–89
iron seeps near 96
Tolovana River, hot springs near 57–58
Trocadero Bay, carbonated springs near 81
carbonated springs near, analysis of 87
map of 81
view of 82
Tuluksak River, hot springs near 72
Twelvemile Creek, hot spring on 41–42

U.

Unuk River, carbonated springs near 79
hot springs near 23

V.

Vank Island, hot springs on 25

W.

Waring, G. A., work of 11–12, 99
Waters, surface, general character of 99
Whitefish Lake, hot spring near 71
Woodchopper Creek, carbonated springs near 84
Wrangell region, minor hot springs of 25–26
Wright, F. E., springs reported by 25–26, 79

Digitized by Google

Y.

Page.
Yukon basin, carbonated springs of.. 84–86
carbonated springs of, distribution 84
character of..... 99–100
hot springs of..... 14, 50–72
distribution of..... 50
iron springs of..... 95–96
Yukon River, discharge of..... 105
water of, analyses of..... 100–104
chemical composition of.. 104–105
Yukon-Tanana region, surface waters of, analyses of..... 167

Z.

Zarembo Island, carbonated springs on..... 82–83
Zarembo Springs, analyses of..... 87
description of..... 82–83
view of..... 83

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

WATER-SUPPLY PAPER 419

MAY 4 1917

PROFILE SURVEYS IN 1915
IN
SKAGIT RIVER BASIN, WASHINGTON

PREPARED UNDER THE DIRECTION OF
W. H. HERRON
ACTING CHIEF GEOGRAPHER

Prepared in cooperation with
THE STATE OF WASHINGTON

WASHINGTON
GOVERNMENT PRINTING OFFICE
1916

Digitized by Google

Digitized by Google

DEPARTMENT OF THE INTERIOR
FRANKLIN K. LANE, Secretary

UNITED STATES GEOLOGICAL SURVEY
GEORGE OTIS SMITH, Director

Water-Supply Paper 419

PROFILE SURVEYS IN 1915

IN

SKAGIT RIVER BASIN, WASHINGTON

PREPARED UNDER THE DIRECTION OF
W. H. HERRON
ACTING CHIEF GEOGRAPHER

Prepared in cooperation with
THE STATE OF WASHINGTON

WASHINGTON
GOVERNMENT PRINTING OFFICE
1916

Digitized by Google

ADDITIONAL COPIES

OF THIS PUBLICATION MAY BE PROCURED FROM
THE SUPERINTENDENT OF DOCUMENTS
GOVERNMENT PRINTING OFFICE
WASHINGTON, D. C.
AT

15 CENTS PER COPY

Digitized by Google

CONTENTS.

	Page.
Introduction	5
General features of Skagit River basin	5
Gaging stations	7
Publications	8

ILLUSTRATIONS.

PLATES I–XII. Plan and profile of Skagit River and certain tributaries above Concrete, Wash. (Sheets A–L.)

Digitized by Google

Digitized by Google

PROFILE SURVEYS ALONG HENRYS FORK, IDAHO, AND LOGAN RIVER AND BLACKSMITH FORK, UTAH.

Prepared under the direction of W. H. HERRON, Acting Chief Geographer.

INTRODUCTION.

In order to determine the location of undeveloped water powers the United States Geological Survey has from time to time, alone and in cooperation with State organizations, made surveys and profiles of some of the rivers of the United States that are adapted to the development of power by low or medium heads of 20 to 100 feet.

The surveys are made by means of plane table and stadia. Elevations are based on heights derived from primary or precise levels of the United States Geological Survey. The maps are made in the field, and show not only the outlines of the river banks, the islands, the positions of rapids, falls, shoals, and existing dams, and the crossings of all ferries and roads, but the contours of banks to an elevation high enough to indicate the possibility of using the stream. The elevations of the various bench marks left are noted on the field sheets in their proper positions. The figures given with the gaging stations shown on the maps indicate the elevation of the zero of the gage.

HENRYS FORK, IDAHO.

GENERAL FEATURES OF SNAKE RIVER BASIN.

Snake River, the largest tributary of the Columbia, rises among the high peaks of the Rocky Mountains in Yellowstone National Park, western Wyoming, and eastern Idaho, heading in the divide from which streams flow northward and eastward into the Missouri, southward to the Colorado and the lakes of the Great Basin, and westward to the Columbia. From Shoshone, Lewis, and Hart lakes, in Yellowstone National Park, the South Fork of the river flows southward, broadening into Jackson Lake (4 miles wide and 18 miles long), and passing through Jackson Valley (8 miles wide and 40 miles long), beyond which, near the Idaho-Wyoming line, it enters a long canyon. In the southern part of Fremont County, Idaho, it receives Henrys Fork, below which it flows southward and westward across Idaho to a point near Homedale, near the Oregon-Idaho line, where it turns abruptly northward and forms for about 170 miles the boundary between Idaho and Oregon and for 30 miles more that between Idaho and Washington. It enters Washington at Lewiston,

Digitized by Google

flows northwest, west, and southwest, and joins the Columbia near Pasco.

Practically all the important tributaries of Snake River have their sources in the high mountains, which are heavily timbered. The most heavily timbered areas are at the head of the river, in the Yellowstone Park region, the upper areas of Teton, Fall, and Henrys Fork in eastern Idaho, and those of upper Boise and Payette rivers in central Idaho.

Precipitation in the Snake River basin ranges from 6 or 8 inches in the valley to 50 inches at the head of many of the tributaries. The precipitation in the higher altitudes is practically all in the form of snow, but the snowfall in the lower valleys, below American Falls, Idaho, is comparatively light. During the last few years there has been considerable rainfall, and dry farming has been practiced successfully in the valleys in the vicinity of Idaho Falls, Blackfoot, and St. Anthony, Idaho. The temperature in these valleys ranges from 100° in the summer to 35° below zero in the winter; in the Twin Falls and Boise valleys the temperature ranges from approximately 110° in the summer to zero in the winter.

The driest year recorded in the drainage basin was 1905; the wet years were 1896, 1899, 1904, 1907, and 1909.

Snake River basin has many feasible storage sites, but only a very few have been developed. About 400,000 acre-feet can be stored in Jackson Lake by a dam which has been constructed by the United States Reclamation Service. The largest site is at Swan Valley, on Snake River, and the water available for storage is approximately 4,000,000 acre-feet. Reservoir sites are found also on Henrys Fork, Fall, Teton, Boise, and Payette rivers. Many of these sites will no doubt be used at some future time by the United States Reclamation Service in connection with the Minidoka and Payette-Boise projects.

Irrigation has reached a high stage of development in the Snake River valley, yet approximately 6,000,000 acre-feet of water annually runs to waste. Eventually these flood waters will be stored and used to irrigate thousands of acres of arid land.

The streams afford enormous water powers, but only a few sites have been developed owing to the lack of market. Large power plants have been installed at Horseshoe Bend on the Payette, at the mouth of the canyon on the Boise, and on Snake River at American Falls, Shoshone Falls, Salmon Falls, and at the Minidoka dam. Many other smaller plants are also in use.

The upper drainage basin of the South Fork comprises the timbered mountainous country west and southwest of Yellowstone Lake. The east side of its valley is bounded by the Wind River Range, from the slopes of which it receives a large number of tributaries, and the west side by the high Teton Mountains. Most of the drainage from Teton Mountains flows westward through Teton River into Henrys Fork.

Digitized by Google

SURVEYS AND GAGING STATIONS.

The results of surveys along Henrys Fork in 1915 are presented in he plans and profiles which form Plates I–VIII.

The United States Geological Survey has maintained gaging stations on Henrys Fork at Warm River, Idaho (1910–1916), near Ora, daho (1902–1909), in canyon above mouth of Fall River, Idaho 1890–91), and near Rexburg, Idaho (1909–1916).

LOGAN RIVER BASIN.

GENERAL FEATURES.

Logan River rises on the west slope of the Bear River Range, flows outhwest and then northwest, and unites with the Bear near Benson, Utah. Its basin is rough and rugged, the elevations ranging from 4,500 to 9,000 feet above sea level and the river being confined largely to a steep, rough channel in a comparatively narrow canyon. Probably three-fourths of the precipitation in this basin is snow, the melting of which supplies the principal part of the spring and summer flow; the late summer and winter flow is derived chiefly from springs, which are well distributed over the basin. In its upper course the Logan receives many short, swift tributaries. Temple Fork and South Fork, which enter, respectively, 10 miles and 15 miles above Logan, are perennial streams that furnish one-third to one-fourth of the total flow. Blacksmith Fork comes in below Logan. The entire flow of this river, after being used to develop power at two electric plants near the mouth of the canyon, is diverted for irrigation. None of the run-off is stored at present.

The results of surveys along Logan River and Blacksmith Fork in 1914 are presented as Plates IX and X.

GAGING STATIONS.

The Geological Survey has maintained the following gaging stations on Logan River and Blacksmith Fork. The stations are arranged in downstream order, the position of tributaries being indicated by indention. A dash after the date indicates that station was being maintained June 30, 1916. A period after the date indicates discontinuance.

Logan River near Logan, Utah, 1896–1912.
Logan River above State dam, near Logan, Utah, 1913–
Logan River below State dam, near Logan, Utah, 1913–
  Utah Power & Light Co.'s tailrace near Logan, Utah, 1913.
  Logan, Hyde Park, and Smithfield canal near Logan, Utah, 1904; 1906–1907; 1909; 1912–
  Logan Northern canal near Logan, Utah, 1913–
  Blacksmith Fork above Utah Power & Light Co.'s dam near Hyrum, Utah, 1914–
  Blacksmith Fork at Utah Power & Light Co.'s plant near Hyrum, Utah, 1914–
  Blacksmith Fork below Utah Power & Light Co.'s plant near Hyrum, Utah, 1900–1902; 1904–1910; 1914–
    Blacksmith Fork power-plant race near Hyrum, Utah, 1904–1910; 1914–

Digitized by Google

PUBLICATIONS.

The following publications of the Geological Survey contain results of investigations of stream flow at the stations indicated in preceding lists:

Henrys Fork:
Annual Reports: Twelfth, Part II; Thirteenth, Part III.
Water-Supply Papers: 85, 100, 135, 178, 214, 252, 272, 292, 312, 332-B, 362-B.
Logan River basin:
Annual Reports: Eighteenth, Part IV; Nineteenth, Part IV; Twentieth, Part Twenty-second, Part IV.
Water-Supply Papers: 11, 16, 28, 38, 51, 66, 75, 85, 100, 133, 176, 212, 250, 270, 310, 330, 360.

Water-supply papers and other publications of the United Sta Geological Survey containing data in regard to the water resources the United States may be obtained or consulted as indicated belo

1. Copies may be obtained free of charge by applying to the Dir tor of the Geological Survey, Washington, D. C. The edition print for free distribution is, however, small and is soon exhausted.

2. Copies may be purchased at nominal cost from the Superi tendent of Documents, Government Printing Office, Washingto D. C., who will, on application, furnish lists giving prices.

3. Sets of the reports may be consulted in the libraries of the pri cipal cities in the United States.

4. Complete sets are available for consultation in the local offic of the water-resources branch of the Geological Survey, as follows:

Boston, Mass., Customhouse.
Albany, N. Y., Room 18, Federal Building.
Atlanta, Ga., Post Office Building.
Madison, Wis., care of Railroad Commission of Wisconsin.
St. Paul, Minn., Old Capitol Building.
Austin, Tex., Old Post Office Building.
Helena, Mont., Montana National Bank Building.
Denver, Colo., 403 New Post Office Building.
Phoenix, Ariz., 417 Fleming Building.
Salt Lake City, Utah, 421 Federal Building.
Boise, Idaho, 615 Idaho Building.
Tacoma, Wash., 406 Federal Building.
Portland, Oreg., 416 Couch Building.
San Francisco, Cal., 328 Customhouse.
Los Angeles, Cal., 619 Federal Building.
Honolulu, Hawaii, Kapiolani Building.

A list of the Geological Survey's publications may be obtained applying to the Director of the United States Geological Surv Washington, D. C.

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Digitized by Google

Stanford University Libraries
3 6105 007 638 864

FOR USE IN LIBRARY BUILDING ONLY
DO NOT REMOVE
766856
Digitized by Google


Digitized by Google

Stanford University Libraries
3 6105 007 638 864

FOR USE IN LIBRARY BUILDING ONLY
DO NOT REMOVE
766856

Digitized by Google

Digitized by Google